bvsl\ptreports\2001\aug\400base8-01graf.dwg



Air Photo Source: MAP, Inc. 3/19/99

N

0 Feet 400

Well Completed in Unit B
Well Completed in Deep Portion Unit A
Well Completed in Shallow Portion Unit A

Monitoring Well
Other Well
Pumping Test Well
Observation Well

Recovery Well
Replacement Wells
Source Area Characterization Well
Seasonal Pond

MAXIM 9732221

Chloroform Concentration vs Time
Bitterroot Valley Sanitary Landfill
Victor, Montana
FIGURE 7