

Facility Summary in BEAVERHEAD County in the City of DELL

Owner: Dell Center LLC			Address: Ellen Burdick, PO Box 240064, Dell MT 59724-0064		
Sys Fac ID 0101523	FITS SITE 32021	Location Name DELL CENTER LLC	Location Street Address 24 MAIN ST PO Box 240036	Location City DELL, MT 59724	Location Phone (406) 276-3332
Operating Permit Renewal Date: 07-Feb-2015			Last inspected on: 04-Nov-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / 04 Currently in Use	5045	10/6/2005 06 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
5 / 05 Currently in Use	5046	10/6/2005 06 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
6 / 06 Currently in Use	5047	10/6/2005 06 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
7 / 07 Currently in Use	5048	10/6/2005 06 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes

Owner: Canyon Ranch			Address: % Mike Barker, One Gorham Island, Westport CT 06880-3217		
Sys Fac ID 0109843	FITS SITE 32227	Location Name DELL AIRPORT CANYON RANCH	Location Street Address	Location City DELL, MT 59724	Location Phone (406) 276-3498
Operating Permit Renewal Date: 29-Apr-2010			Last inspected on: 13-Nov-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Temporarily Out of Use	516	6/13/1989 22 / No	Other 10,000	STI-P3 Double-Walled	No Piping None	Pressurized	A B C D E F ● H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in BEAVERHEAD County in the City of DILLON

Owner: The Mini Inc			Address: 410 N Montana St, Dillon MT 59725-3313		
Sys Fac ID 0101215	FITS SITE 32016	Location Name THE MINI INC	Location Street Address 410 N MONTANA ST	Location City DILLON, MT 59725	Location Phone (406) 683-6168
Operating Permit Renewal Date: 29-Apr-2013			Last inspected on: 09-Dec-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / 04 Currently In Use	3088	5/6/1998 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
5 / 05 Currently In Use	3089	5/6/1998 13 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
6 / 06 Currently In Use	3090	5/6/1998 13 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: Timothy Dietrich			Address: 636 S Atlantic St, Dillon MT 59725-2725		
Sys Fac ID 0105401	FITS SITE 32109	Location Name DIETRICH'S COLLEGE EXXON UST	Location Street Address 636 S ATLANTIC ST	Location City DILLON, MT 59725	Location Phone
Operating Permit Renewal Date: 01-Apr-2002			Last inspected on: 08-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 05 Temporarily Out of Use	3227	7/1/1994 17 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
2 / 04 Temporarily Out of Use	3226	7/1/1994 17 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: Beaverhead County Clerk			Address: 2 S Pacific St, Dillon MT 59725-4000		
Sys Fac ID 0105668	FITS SITE 32119	Location Name COUNTY COURTHOUSE	Location Street Address 2 S PACIFIC ST	Location City DILLON, MT 59725	Location Phone (406) 683-2642
Operating Permit Renewal Date: 06-Nov-2014			Last inspected on: 26-Sep-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
-----------------------------	---------------	----------------------	---------------------	--	-------------------------------------	-------------	--	------------------------------

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in BEAVERHEAD County in the City of DILLON

2 / 02 421 2/1/1993 Gasoline STI-P3 Galvanized Steel Safe Suction A B C D E F G H I J K L
 Currently in Use 19 / No 2,000 Double-Walled none B D E F G H I J K L Yes Yes Yes

Owner: Town Pump Inc Butte		Address: PO Box 6000, Butte MT 59702-6000	
Sys Fac ID 0108695	FITS SITE 32218	Location Name TOWN PUMP INC DILLON 1	Location Street Address 101 E HELENA ST
		Location City DILLON, MT 59725	Location Phone
Operating Permit Renewal Date: 14-Oct-2012		Last inspected on: 01-Oct-2009	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	4794	4/14/1961 51 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input checked="" type="checkbox"/> L	Yes Yes Yes
4 / 04 Currently in Use	4795	1/1/1986 26 / No	Gasoline 10,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input checked="" type="checkbox"/> L	Yes Yes Yes
5 / 05 Currently in Use	4796	1/1/1986 26 / No	Gasoline 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input checked="" type="checkbox"/> L	Yes Yes Yes

Owner: Major Brands Distributing Imports Inc		Address: PO Box 6000, Butte MT 59702-6000	
Sys Fac ID 0108696	FITS SITE 32219	Location Name TOWN PUMP INC DILLON 2	Location Street Address 635 N MONTANA ST
		Location City DILLON, MT 59725	Location Phone (406) 497-6700
Operating Permit Renewal Date: 14-Oct-2012		Last inspected on: 01-Oct-2009	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 10 Currently in Use	2375	9/10/1990 21 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input checked="" type="checkbox"/> L	Yes Yes Yes
2 / 11 Currently in Use	2376	9/10/1990 21 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input checked="" type="checkbox"/> L	Yes Yes Yes
4 / 07 Currently in Use	2372	9/10/1990 21 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input checked="" type="checkbox"/> L	Yes Yes Yes
5 / 08 Currently in Use	2373	9/10/1990 21 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input checked="" type="checkbox"/> L	Yes Yes Yes
6 / 09 Currently in Use	2374	9/10/1990 21 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input checked="" type="checkbox"/> L	Yes Yes Yes
7 / 13 Currently In Use	4541	5/1/1999 12 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input checked="" type="checkbox"/> L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in BEAVERHEAD County in the City of DILLON

8 / 14	4356	8/20/2001	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C ● E F ● H ● J K L B ● E F G H ● J K L	Yes	Yes	Yes
Currently In Use		10 / No	10,000	Double-Walled	None					
9 / 15	4357	8/20/2001	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C ● E F ● H ● J K L B ● E F G H ● J K L	Yes	Yes	Yes
Currently In Use		10 / No	5,000	Double-Walled	None					

Owner: Rocky Mountain Supply Inc			Address: Jason Rorabaugh Petroleum Mgr, 350 Jackrabbit Ln, Belgrade MT 59714-3035		
Sys Fac ID 0110034	FITS SITE 32230	Location Name ROCKY MOUNTAIN SUPPLY INC DILLON	Location Street Address 700 N MONTANA ST	Location City DILLON, MT 59725	Location Phone (406) 683-2308
Operating Permit Renewal Date: 19-Feb-2013			Last inspected on: 08-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	3900	1/12/1981 31 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	3901	1/12/1981 31 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
3 / 03 Currently in Use	3902	1/12/1981 31 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
4 / 04 Currently in Use	3903	1/12/1981 31 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
5 / 05 Currently in Use	3904	1/12/1981 31 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
9 / 09 Currently In Use	3905	12/1/1998 13 / No	Gasoline 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	A B C ● E F G H I J K L ● D E F G H I ● K L	Yes Yes Yes
10 / 10 Currently In Use	3906	12/1/1998 13 / No	Gasoline 4,100	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	A B C ● E F G H I J K L B D E F G H I J ● L	Yes Yes Yes
11 / 11 Currently In Use	3907	12/1/1998 13 / No	Gasoline 7,900	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	A B C ● E F G H I J K L B D E F G H I J ● L	Yes Yes Yes

Owner: Anthony D Walker			Address: 4055 Rebich Ln, Dillon MT 59725-9535		
Sys Fac ID 0113101	FITS SITE 32260	Location Name BIG SKY TRAVEL PLAZA	Location Street Address 4055 REBICH LN	Location City DILLON, MT 59725	Location Phone (406) 683-2666
Operating Permit Renewal Date: 22-Nov-2012			Last inspected on: 03-Nov-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
-----------------------------	---------------	----------------------	---------------------	--	-------------------------------------	-------------	--	------------------------------

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in BEAVERHEAD County in the City of DILLON

1 / 01	4634	7/1/1993	Gasoline	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	18 / No	8,000	None	Double-Walled		B ● E F ● H I J K L				
2 / 02	4635	7/1/1993	Gasoline	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	18 / No	8,000	None	Double-Walled		B ● E F ● H I J K L				
3 / 03	4636	7/1/1993	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	18 / No	8,000	None	None		● ● E F G H I J K L				
4 / 04	4637	7/1/1993	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	18 / No	8,000	None	None		● ● E F G H I J K L				
5 / 05	4638	7/1/1993	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	18 / No	8,000	None	None		● ● E F G H I J K L				

Owner: Beaverhead County Clerk		Address: 2 S Pacific St, Dillon MT 59725-4000			
Sys Fac ID 5613894	FITS SITE 45113	Location Name DILLON AIRPORT	Location Street Address 2400 AIRPORT RD	Location City DILLON, MT 59725	Location Phone (406) 683-5242
Operating Permit Renewal Date: 04-Mar-2015		Last inspected on: 26-Sep-2011			

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01	3995	4/1/1982	Other	Asphalt Coated or Bare Steel	Bare Steel	Pressurized	A B C ● E F G H I J K L	Yes
Currently In Use	30 / No	12,000	Impressed Current		None		● ● E F G H I J K L	
2 / 02	3996	4/1/1982	Other	Cathodically Protected Steel	Bare Steel	Pressurized	A B C ● E F G H I J K L	Yes
Currently In Use	30 / No	12,000	Lined Interior/Impressed Curre		None		● ● E F G H I J K L	

Owner: Safeway Stores Inc		Address: 1121 124th Ave NE, Bellevue WA 98005-2101			
Sys Fac ID 5613989	FITS SITE 45195	Location Name SAFEWAY 1581 DILLON	Location Street Address 570 N MONTANA ST	Location City DILLON, MT 59725	Location Phone
Operating Permit Renewal Date: 05-Nov-2013		Last inspected on: 04-May-2010			

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01	4222	10/9/2000	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F ● H I J K L	Yes
Currently In Use	11 / No	20,000	Double-Walled		Double-Walled		B ● E F ● H I J K L	
2 / 02	4223	10/1/2000	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F ● H I J K L	Yes
Currently In Use	11 / No	10,000	Double-Walled		Double-Walled		B ● E F ● H I J K L	
3 / 03	4224	10/1/2000	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F ● H I J K L	Yes
Currently In Use	11 / No	10,000	Double-Walled		Double-Walled		B ● E F ● H I J K L	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in BEAVERHEAD County in the City of DILLON

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in BEAVERHEAD County in the City of LIMA

Owner: Kevin Stosich			Address: T & R Enterprises Inc, PO Box 206, Lima MT 59739-0206		
Sys Fac ID 0100671	FITS SITE 32008	Location Name RALPHS EXXON	Location Street Address 114 South Harrison	Location City LIMA, MT 59739	Location Phone (406) 276-3431
Operating Permit Renewal Date: 21-Sep-2013			Last inspected on: 09-Aug-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
7 / 07 Currently In Use	2078	9/1/1998 13 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L													Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
8 / 08 Currently In Use	2079	9/1/1998 13 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L													Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					

Owner: School Dist 12 Lima			Address: PO Box 186, Lima MT 59739-0186		
Sys Fac ID 0107158	FITS SITE 32210	Location Name LIMA SCHOOL DIST 12 INC	Location Street Address 1 N HARRISON ST	Location City LIMA, MT 59739	Location Phone (406) 276-3571
Operating Permit Renewal Date: 17-Jan-2015			Last inspected on: 18-Aug-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / 03 Currently in Use	1535	6/1/1992 19 / No	Diesel 10,000	STI-P3 Double-Walled	Fiberglass Reinforced Plas Double-Walled	U.S. Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L													Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in BEAVERHEAD County in the City of WISDOM

Owner: Edward Stede		Address: PO Box 175, Wisdom MT 59761-0175			
Sys Fac ID 0102173	FITS SITE 32035	Location Name BIG HOLE PETROLEUM INC	Location Street Address 318 MT HIGHWAY 43 PO BOX 175	Location City WISDOM, MT 59761	Location Phone (406) 689-3225
Operating Permit Renewal Date: 30-Jul-2014			Last inspected on: 14-Jun-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	3323	3/10/1985 27 / No	Gasoline 2,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Galvanized Steel None	U.S. Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●												Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
●																																
2 / 02 Currently in Use	3324	3/10/1985 27 / No	Gasoline 1,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Galvanized Steel None	U.S. Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●												Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
●																																

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in BEAVERHEAD County in the City of WISE RIVER

Owner: Dawna Wilkinson		Address: PO Box 159, Wise River MT 59762	
Sys Fac ID 0102080	FITS SITE 32032	Location Name WISE RIVER STORE	Location Street Address MT HIGHWAY 43
		Location City WISE RIVER, MT 59762	Location Phone (406) 832-3271
Operating Permit Renewal Date: 13-Oct-2013		Last inspected on: 09-Aug-2010	

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	Installed Spill/Over/CPMe
3 / 03	1224	6/1/1998	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Safe Suction	A B C D E F G H I J K L	A B C D E F G H I J K L	Yes Yes Yes
Currently In Use		13 / No	2,000	None	None		B D E F G H I ● K L		

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed