

Facility Summary in DAWSON County in the City of BLOOMFIELD

Owner: Farmers Union Oil Co Bloomfield		Address: PO Box 15, Bloomfield MT 59315-0015	
Sys Fac ID 1104222	FITS SITE 34293	Location Name FARMERS UNION OIL CO BLOOMFIELD	Location Street Address ROAD 254
		Location City BLOOMFIELD, MT 59315	Location Phone (406) 583-7539
Operating Permit Renewal Date: 16-Jun-2015		Last inspected on: 08-Mar-2012	

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / 03 Currently in Use	950	11/28/1988 23 / No	Gasoline 4,000	STI-P3 None	Bare Steel none	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr> <td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td><td></td> </tr> </table>	A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L		Yes Yes Yes
A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DAWSON County in the City of GLENDIVE

Owner: Gregory Cross			Address: Cross Petroleum Service Inc, PO Box 1078, Billings MT 59103-1078		
Sys Fac ID 1100033	FITS SITE 34229	Location Name EAST END CONOCO GLENDIVE	Location Street Address INTERSTATE 94 & MERRILL AVE	Location City GLENDIVE, MT 59330	Location Phone (406) 365-8325
Operating Permit Renewal Date: 14-Mar-2015			Last inspected on: 04-Jan-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / 04 Currently in Use	773	1/17/1989 23 / No	Gasoline 4,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
5 / 05 Currently in Use	774	1/17/1989 23 / No	Gasoline 4,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
6 / 06 Currently in Use	775	1/17/1989 23 / No	Gasoline 4,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Owner: Dawson County			Address: Attn: Airport Manager, 207 W Bell St, Glendive MT 59330-1616		
Sys Fac ID 1102455	FITS SITE 34262	Location Name GLENDIVE AIRPORT LARGE HANGER	Location Street Address 402 DRY CREEK RD	Location City GLENDIVE, MT 59330	Location Phone (406) 687-3372
Operating Permit Renewal Date: 29-Sep-2012			Last inspected on: 18-Apr-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / 04 Currently in Use	824	11/21/1994 17 / No	Aviation Gas 8,000	STI-P3 None	Other Secondary Containment C	Pressurized	A B C D E F G H I J K L ● ● E F G ● H I J K L	Yes Yes No
5 / S5 Currently in Use	825	1/1/1974 38 / Yes	Jet Fuel 200	Unknown None	Bare Steel none	Pressurized	A B C D E F G H I J ● L ● ● E F G H I J K L	Yes Yes Yes

Owner: Berg Tire			Address: 2111 W Towne St, Glendive MT 59330-3214		
Sys Fac ID 1103214	FITS SITE 34275	Location Name BERGS TIRE INC	Location Street Address 2111 W TOWNE ST	Location City GLENDIVE, MT 59330	Location Phone (406) 377-5286
Operating Permit Renewal Date: 20-Jul-2013			Last inspected on: 26-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
-----------------------------	---------------	----------------------	---------------------	------------------------------------------------	-------------------------------------	-------------	----------------------------------------------------	------------------------------

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DAWSON County in the City of GLENDIVE

1 / 09	601	3/26/1987	Gasoline	STI-P3	Bare Steel	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Currently in Use		25 / No	6,000	Impressed Current	None	● E F G H I J K L		
2 / 08	600	3/26/1987	Diesel	STI-P3	Bare Steel	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Currently in Use		25 / No	6,000	Impressed Current	None	● E F G H I J K L		
3 / 07	599	3/26/1987	Gasoline	STI-P3	Galvanized Steel	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Currently in Use		25 / No	12,000	Impressed Current	None	● E F G H I J K L		
5 / 06	598	3/26/1987	Diesel	STI-P3	Galvanized Steel	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Currently in Use		25 / No	12,000	Impressed Current	None	● E F G H I J K L		

Owner: T & E Whistle Stop Inc		Address: PO Box 1313, Glendive MT 59330-1313	
Sys Fac ID 1104213	FITS SITE 34292	Location Name T & E WHISTLE STOP INC	Location Street Address 1320 N MERRILL AVE
		Location City GLENDIVE, MT 59330	Location Phone (406) 365-2177
Operating Permit Renewal Date: 09-Jun-2013		Last inspected on: 08-Dec-2009	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01	4308	5/6/1984	Diesel	Asphalt Coated or Bare Steel	Galvanized Steel	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use		27 / No	10,000	Impressed Current	None	B ● E F G H I J K L		
2 / 02	4309	5/6/1984	Gasoline	Asphalt Coated or Bare Steel	Galvanized Steel	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use		27 / No	10,000	Impressed Current	None	B ● E F G H I J K L		
3 / 03	4310	5/6/1984	Gasoline	Asphalt Coated or Bare Steel	Galvanized Steel	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use		27 / No	10,000	Impressed Current	None	B ● E F G H I J K L		

Owner: Mini Mart Inc Pueblo		Address: 442 Keeler Pkwy, Pueblo CO 81001-4813	
Sys Fac ID 1105093	FITS SITE 34301	Location Name MINI MART 710 1105093	Location Street Address 322 E BARRY ST
		Location City GLENDIVE, MT 59330	Location Phone (406) 365-6111
Operating Permit Renewal Date: 15-Jan-2014		Last inspected on: 27-Jul-2010	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / 04	1636	9/1/1996	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use		15 / No	10,000	None	Double-Walled	B D E F ● H I J K L		
5 / 05	1637	9/1/1996	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use		15 / No	10,000	None	Double-Walled	B D E F ● H I J K L		
6 / 06	1638	9/1/1996	Gasohol/Eth	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use		15 / No	10,000	None	Double-Walled	B D E F ● H I J K L		

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DAWSON County in the City of GLENDIVE

Owner: Trail Star LLC		Address: DBA Trail Star Car and Truck Stop, PO Box 557, Glendive MT 59330-0557			
Sys Fac ID 1105754	FITS SITE 34306	Location Name TRAIL STAR CAR AND TRUCK STOP	Location Street Address EXIT 213 MT HIGHWAY 16	Location City GLENDIVE, MT 59330	Location Phone (406) 365-0557
Operating Permit Renewal Date: 29-Sep-2012		Last inspected on: 20-Aug-2009			

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
5 / 05 Currently In Use	4274	11/30/1998 13 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
6 / 06 Currently In Use	4275	11/30/1998 13 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
7 / 07 Currently In Use	4276	11/30/1998 13 / No	Diesel 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
8 / 08 Currently In Use	4277	11/30/1998 13 / No	Diesel 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
9 / 09 Currently In Use	4278	11/30/1998 13 / No	Diesel 15,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: Qwest Corporation dba CenturyLink		Address: 250 East 200 South #1601, Salt Lake City UT 84111			
Sys Fac ID 1106870	FITS SITE 34328	Location Name QWEST GLENDIVE CENTRAL OFFICE	Location Street Address 119 W VALENTINE ST	Location City GLENDIVE, MT 59330	Location Phone (801) 237-3006
Operating Permit Renewal Date: 10-Mar-2015		Last inspected on: 07-Dec-2011			

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	1726	4/1/1993 19 / No	Diesel 553	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	U.S. Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DAWSON County in the City of GLENDIVE

Owner: Joys Glendive Service Inc			Address: 74 Highway 16, Glendive MT 59330-3609		
Sys Fac ID 1107770	FITS SITE 34345	Location Name JOYS GLENDIVE SERVICE INC	Location Street Address 74 HIGHWAY 16	Location City GLENDIVE, MT 59330	Location Phone (406) 377-1821
Operating Permit Renewal Date: 18-Jun-2013			Last inspected on: 06-Apr-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
6 / 06 Currently In Use	1511	5/28/1998 13 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B ● E F ● H I J K L	Yes Yes Yes
7 / 07 Currently In Use	1512	5/28/1998 13 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B ● E F ● H I J K L	Yes Yes Yes
8 / 08 Currently In Use	1513	5/28/1998 13 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
9 / 09 Currently In Use	1514	5/28/1998 13 / No	Diesel 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F ● H I J K L	Yes Yes Yes

Owner: Rocky Mountain Oil Co Inc			Address: PO Box 1224, Minneapolis MN 55440-1224		
Sys Fac ID 1108061	FITS SITE 34349	Location Name HOLIDAY STATIONSTORE 271	Location Street Address 701 N MERRILL AVE	Location City GLENDIVE, MT 59330	Location Phone (406) 365-2221
Operating Permit Renewal Date: 12-Jul-2013			Last inspected on: 04-Feb-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 02 Currently in Use	3002	10/1/1979 32 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H I J K L ● ● E F ● H I J K L	Yes Yes Yes
2 / 03 Currently in Use	3003	10/1/1979 32 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H I J K L ● ● E F ● H I J K L	Yes Yes Yes
3 / 04 Currently in Use	3004	10/1/1979 32 / No	Diesel 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H I J K L ● ● E F ● H I J K L	Yes Yes Yes
4 / 01 Currently in Use	3001	10/1/1979 32 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H I J K L ● ● E F ● H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DAWSON County in the City of GLENDIVE

Owner: Cross Petroleum Services Glendive			Address: PO Box 1388, Glendive MT 59330-1388		
Sys Fac ID 1108908	FITS SITE 34367	Location Name West Park Cenex	Location Street Address 2200 W TOWNE ST	Location City GLENDIVE, MT 59330	Location Phone (406) 365-6282
Operating Permit Renewal Date: 09-Oct-2012			Last inspected on: 01-Apr-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / S4 Currently in Use	553	9/1/1999 12 / Yes	Gasoline 12,000	Unknown None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
5 / S5 Currently in Use	554	9/1/1999 12 / Yes	Gasoline 12,000	Unknown None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
6 / S6 Currently in Use	555	9/1/1999 12 / Yes	Diesel 10,000	Unknown None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes

Owner: Cross Petroleum Services Glendive			Address: PO Box 1388, Glendive MT 59330-1388		
Sys Fac ID 1108909	FITS SITE 34368	Location Name WESTGATE CENEX	Location Street Address 56 Highway 16	Location City GLENDIVE, MT 59330	Location Phone (406) 365-8325
Operating Permit Renewal Date: 31-Oct-2012			Last inspected on: 31-Aug-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently In Use	556	5/22/1961 50 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L ● ● E F ● H I J K L	Yes Yes Yes
2 / 02 Currently In Use	557	5/22/1961 50 / No	Diesel 8,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L ● ● E F ● H I J K L	Yes Yes Yes
5 / 05 Currently In Use	558	2/7/1992 20 / No	Gasoline 10,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L ● ● E F ● H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DAWSON County in the City of GLENDIVE

Owner: Montana Dakota Utilities Co			Address: 400 N 4th St, Bismarck ND 58501-4022		
Sys Fac ID 1109400	FITS SITE 34372	Location Name GLENDIVE COMBUSTION TURBINE	Location Street Address 366 FAS 355	Location City GLENDIVE, MT 59330	Location Phone (406) 365-2551
Operating Permit Renewal Date: 17-Nov-2012			Last inspected on: 13-Nov-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / S2 Currently in Use	1692	7/1/1987 24 / Yes	Diesel 75,000	Cathodically Protected Steel None	Bare Steel Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						

Owner: Michael J Perrodin			Address: Burlington Northern Railroad, 235 Main St, Havre MT 59501-3523		
Sys Fac ID 1109528	FITS SITE 34374	Location Name BN GLENDIVE FUELING FACILITY	Location Street Address 310 N Merrill Ave	Location City Glendive, MT 59330	Location Phone (406) 265-0483
Operating Permit Renewal Date: 03-Mar-2015			Last inspected on: 03-Nov-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
4 / SKC1 Currently in Use	505	9/1/1991 20 / Yes	Diesel 680,000	Epoxy Coated Steel None	Bare Steel Double-Walled	Gravity Feed	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes No
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
12 / 03 Currently in Use	504	12/28/1989 22 / No	Mixture 16,000	STI-P3 Double-Walled	Fiberglass Reinforced Plas Double-Walled	Gravity Feed	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						

Owner: Glendive Medical Center			Address: 202 Prospect Dr, Glendive MT 59330-1999		
Sys Fac ID 1109735	FITS SITE 34377	Location Name GLENDIVE MEDICAL CENTER	Location Street Address 202 PROSPECT DR	Location City GLENDIVE, MT 59330	Location Phone (406) 345-3306
Operating Permit Renewal Date: 19-Dec-2014			Last inspected on: 19-Oct-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 03 Currently in Use	1223	11/16/1995 16 / No	Diesel 4,010	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DAWSON County in the City of RICHEY

Owner: Cenex Harvest States Saint Paul			Address: Kum and Go Stores, PO Box 64089, Saint Paul MN 55164-0089		
Sys Fac ID 1105898	FITS SITE 34307	Location Name FARMERS ELEVATOR CO RICHEY	Location Street Address 111 RAILROAD AVE	Location City RICHEY, MT 59259	Location Phone (406) 773-5638
Operating Permit Renewal Date: 02-Feb-2013			Last inspected on: 06-Aug-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection		Installed Spill/Over/CPMe
							Piping Release Detection		
5 / 05 Currently In Use	4314	7/11/2001 10 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F ● H I J K L B D E F G H I ● K L	Yes Yes Yes	
6 / 06 Currently In Use	4315	7/11/2001 10 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F ● H I J K L B D E F G H I ● K L	Yes Yes Yes	
7 / 07 Currently In Use	4316	7/11/2001 10 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F ● H I J K L B D E F G H I ● K L	Yes Yes Yes	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed