

Facility Summary in DEER LODGE County in the City of ANACONDA

Owner: Sutey Oil Co Inc			Address: 2000 Holmes Ave, Butte MT 59701-3553		
Sys Fac ID 1207938	FITS SITE 34473	Location Name THRIFTWAY SUPER STOP 3	Location Street Address 1420 E PARK AVE	Location City ANACONDA, MT 59711	Location Phone
Operating Permit Renewal Date: 25-Sep-2014			Last inspected on: 01-Jun-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 08 Currently in Use	2050	9/1/1990 21 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
2 / 07 Currently in Use	2049	9/1/1990 21 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
4 / 06 Currently in Use	2048	9/1/1990 21 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
9 / 10 Currently in Use	2052	9/1/1990 21 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
10 / 09 Currently in Use	2051	9/1/1990 21 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Owner: Town Pump of Anaconda Inc			Address: PO Box 6000, Butte MT 59702-6000		
Sys Fac ID 1208668	FITS SITE 34478	Location Name TOWN PUMP INC ANACONDA 2	Location Street Address 819 W PARK AVE	Location City ANACONDA, MT 59711	Location Phone (406) 563-6707
Operating Permit Renewal Date: 14-Oct-2012			Last inspected on: 07-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 06 Currently in Use	2410	4/1/1991 21 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H ● ● K L B ● E F G H ● ● K L	Yes Yes Yes
2 / 05 Currently in Use	2409	4/1/1991 21 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H ● ● K L B ● E F G H ● ● K L	Yes Yes Yes
5 / 03 Currently in Use	2407	4/1/1991 21 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H ● ● K L B ● E F G H ● ● K L	Yes Yes Yes
6 / 04 Currently in Use	2408	4/1/1991 21 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H ● ● K L B ● E F G H ● ● K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DEER LODGE County in the City of ANACONDA

Owner: Town Pump Inc			Address: PO Box 6000, Butte MT 59702-2534		
Sys Fac ID 1209326	FITS SITE 34480	Location Name TOWN PUMP INC ANACONDA 1	Location Street Address 6940 MT Hwy 1 Suite A	Location City ANACONDA, MT 59711	Location Phone (406) 497-6700
Operating Permit Renewal Date: 02-Mar-2013			Last inspected on: 07-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection		Installed Spill/Over/CPMe
							Piping Release Detection		
1 / 08 Currently in Use	2414	11/1/1994 17 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H ● J K L B ● E F ● H ● J K L	Yes Yes Yes	
2 / 07 Currently in Use	2413	12/1/1994 17 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H ● J K L B ● E F ● H ● J K L	Yes Yes Yes	
3 / 06 Currently in Use	2412	5/1/1991 20 / No	Gasoline 12,000	Epoxy Coated Steel Impressed Current	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H ● J K L B ● E F ● H ● J K L	Yes Yes Yes	
4 / 05 Currently in Use	2411	5/1/1991 20 / No	Diesel 12,000	Epoxy Coated Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H ● J K L B ● E F ● H ● J K L	Yes Yes Yes	
9 / 09 Currently In Use	4574	7/1/2001 10 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C ● E F ● H ● J K L B ● E F ● H ● J K L	Yes Yes Yes	
10 / 10 Currently In Use	4575	7/1/2001 10 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C ● E F ● H ● J K L B ● E F ● H ● J K L	Yes Yes Yes	

Owner: ARCO Environmental Remediation LLC			Address: attn Trey Harbert, 317 Anaconda Rd, Butte MT 59701-8805		
Sys Fac ID 1210912	FITS SITE 34488	Location Name ATLANTIC RICHFIELD COMPANY	Location Street Address 105 N Silver St	Location City ANACONDA, MT 59711	Location Phone (406) 563-3433
Operating Permit Renewal Date: 18-Sep-2007			Last inspected on: 06-May-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection		Installed Spill/Over/CPMe
							Piping Release Detection		
1 / S1 Temporarily Out of Use	1836	4/16/1985 27 / Yes	Waste Oil 12,800	Unknown None	Bare Steel PVC	Pressurized	A B C D E F G H I J ● K L B D E F G H I ● K L	Yes Yes No	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DEER LODGE County in the City of ANACONDA

Owner: Fairmont RV Park & Campground LLC			Address: 1700 Fairmont Rd, Anaconda MT 59711-9419		
Sys Fac ID 5613976	FITS SITE 45183	Location Name FAIRMONT RV PARK AND CAMPGROUND LLC	Location Street Address 1700 FAIRMONT RD	Location City ANACONDA, MT 59711	Location Phone (406) 797-3505
Operating Permit Renewal Date: 01-Nov-2013			Last inspected on: 18-Sep-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
2 / 02 Currently In Use	4187	4/1/2000 12 / No	Gasoline 3,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		D	E	F	G	H	I	J	K	L	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
	B		D	E	F	G	H	I	J	K	L																					
3 / 03 Currently In Use	4188	4/1/2000 12 / No	Diesel 3,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		D	E	F	G	H	I	J	K	L	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
	B		D	E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in DEER LODGE County in the City of WARM SPRINGS

Owner: Montana Dept of Corrections			Address: Mike Ferriter, PO Box 201301, Helena MT 59620-1301		
Sys Fac ID 1207585	FITS SITE 34471	Location Name XANTHOPOULOS BLDG	Location Street Address 2 C ST	Location City WARM SPRINGS, MT 59756	Location Phone (406) 693-7110
Operating Permit Renewal Date: 26-Nov-2014			Last inspected on: 23-Sep-2011		

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
4 / 04 Currently in Use	829	1/1/1987 25 / No	Diesel 2,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<table border="1" style="font-size: small; text-align: center;"> <tr> <td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="2">B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td> </tr> </table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed