

Facility Summary in GRANITE County in the City of DRUMMOND

Owner: Cenex Harvest States Missoula			Address: DBA Mountain West Co Op, 4570 N Reserve St, Missoula MT 59808-1411		
Sys Fac ID 5613926	FITS SITE 45141	Location Name MOUNTAIN WEST CO OP DRUMMOND	Location Street Address 229 FRONTAGE ROAD E	Location City DRUMMOND, MT 59832	Location Phone
Operating Permit Renewal Date: 26-Mar-2015			Last inspected on: 06-Dec-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe
							Piping Release Detection	
1 / 01 Currently in Use	2846	8/25/1995 16 / No	Gasoline 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plas none	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	2847	8/1/1995 16 / No	Diesel 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plas none	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
3 / S3 Currently in Use	2848	8/1/1995 16 / Yes	Gasoline 14,000	Other None	Fiberglass Reinforced Plas none	Pressurized	A B C D E F G H I J ● L ● ● E F G H I J K L	Yes Yes Yes
4 / S4 Currently in Use	2849	8/1/1995 16 / Yes	Diesel 12,000	Other None	Fiberglass Reinforced Plas none	Pressurized	A B C D E F G H I J ● L ● ● E F G H I J K L	Yes Yes Yes
5 / S5 Currently in Use	2850	8/1/1995 16 / Yes	Diesel 14,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas none	Pressurized	A B C D E F G H I J ● L ● ● E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in GRANITE County in the City of PHILIPSBURG

Owner: Hi Noon Petroleum Missoula			Address: PO Box 7578, Missoula MT 59807-7578		
Sys Fac ID 2005771	FITS SITE 36665	Location Name SUNSHINE STATION 417	Location Street Address 3830 MT HIGHWAY 1	Location City PHILIPSBURG, MT 59858	Location Phone (406) 859-3450
Operating Permit Renewal Date: 11-Feb-2015			Last inspected on: 16-Nov-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	1313	4/27/1983 28 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
2 / 02 Currently in Use	4516	4/27/1983 28 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
3 / 03 Currently In Use	4517	9/20/1999 12 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes

Owner: William Antonioli			Address: PO Box 486, Philipsburg MT 59858-0486		
Sys Fac ID 5613983	FITS SITE 45190	Location Name PINTLER PETROLEUM INC	Location Street Address 906 W BROADWAY RD	Location City PHILIPSBURG, MT 59858	Location Phone (406) 859-3164
Operating Permit Renewal Date: 07-Oct-2014			Last inspected on: 01-Jun-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / S1 Currently In Use	4215	9/1/2000 11 / Yes	Gasoline 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J ● L B D E F ● H I J K L	Yes Yes Yes
2 / S2 Currently In Use	4216	9/1/2000 11 / Yes	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J ● L B D E F ● H I J K L	Yes Yes Yes
3 / S3 Currently In Use	4217	9/1/2000 11 / Yes	Gasoline 20,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J ● L B D E F ● H I J K L	Yes Yes Yes
4 / S4 Currently In Use	4218	9/1/2000 11 / Yes	Diesel 24,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J ● L B D E F ● H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed