

Facility Summary in HILL County in the City of GILDFORD

| | | | | | |
|---|---------------------------|---|---|--|---|
| Owner: Farmers Union Oil Co Kremlin | | | Address: PO Box 110, Kremlin MT 59532-0110 | | |
| Sys Fac ID 2105421 | FITS SITE 36830 | Location Name FARMERS UNION OIL CO GILDFORD | Location Street Address 5TH ST | Location City GILDFORD, MT 59525 | Location Phone (406) 376-3248 |
| Operating Permit Renewal Date: 11-Oct-2013 | | | Last inspected on: 11-Oct-2010 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Installed Spill/Over/CPMe |
|------------------------------|---------------|----------------------|---------------------|--|-------------------------------------|-------------|--|------------------------------|
| | | | | | | | Piping Release Detection | |
| 12 / S12 Currently In Use | 979 | 7/1/1999 12 / Yes | Gasoline 15,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |
| 13 / S13 Currently In Use | 980 | 7/1/1999 12 / Yes | Gasoline 15,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |
| 14 / S14 Currently In Use | 981 | 7/1/1999 12 / Yes | Diesel 15,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |
| 15 / S15 Currently In Use | 982 | 7/1/1999 12 / Yes | Diesel 15,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in HILL County in the City of HAVRE

| | | | | | |
|---|---------------------------|--|---|---|---|
| Owner: Ellis Enterprises Inc | | | Address: 1230 11th St, Havre MT 59501-4657 | | |
| Sys Fac ID 2100088 | FITS SITE 36713 | Location Name SHORT STOP HAVRE | Location Street Address 1639 5TH AVE | Location City HAVRE, MT 59501 | Location Phone (406) 265-6454 |
| Operating Permit Renewal Date: 31-Dec-2010 | | | Last inspected on: 20-Dec-2010 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|----------------------------------|---------------|-----------------------|---------------------|--|-------------------------------------|-------------|--|------------------------------|
| 1 / 01 Temporarily Out of Use | 3862 | 12/31/1971 40 / No | Gasoline 10,000 | Cathodically Protected Steel Lined Interior/Impressed Curre | Galvanized Steel None | Pressurized | A ● C ● D ● E ● F ● G ● H ● I ● J ● K ● L ● ● E ● F ● G ● H ● I ● J ● K ● L | Yes Yes Yes |
| 2 / 02 Temporarily Out of Use | 3863 | 12/31/1971 40 / No | Gasoline 10,000 | Cathodically Protected Steel Lined Interior/Impressed Curre | Galvanized Steel None | Pressurized | A ● C ● D ● E ● F ● G ● H ● I ● J ● K ● L ● ● E ● F ● G ● H ● I ● J ● K ● L | Yes Yes Yes |

| | | | | | |
|---|---------------------------|-------------------------------------|--|---|---|
| Owner: CHS Inc | | | Address: 16124 E Marietta Lane, Spokane Valley WA 99216 | | |
| Sys Fac ID 2100089 | FITS SITE 36714 | Location Name ZIP TRIP 48 | Location Street Address 911 11TH ST W | Location City HAVRE, MT 59501 | Location Phone (509) 535-7701 |
| Operating Permit Renewal Date: 27-Jun-2012 | | | Last inspected on: 08-Feb-2011 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|----------------------|---------------------|--|-------------------------------------|-------------|--|------------------------------|
| 3 / 03 Currently in Use | 5341 | 10/1/2011 00 / No | Gasoline 15,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C ● E F ● H I J K L B D E F ● H I J K L | Yes Yes Yes |
| 4 / 04 Currently in Use | 5342 | 10/1/2011 00 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C ● E F ● H I J K L B D E F ● H I J K L | Yes Yes Yes |
| 5 / 05 Currently in Use | 5343 | 10/1/2011 00 / No | Diesel 6,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C ● E F ● H I J K L B D E F ● H I J K L | Yes Yes Yes |

| | | | | | |
|---|---------------------------|-------------------------------------|--|---|---|
| Owner: CHS Inc | | | Address: 16124 E Marietta Lane, Spokane Valley WA 99216 | | |
| Sys Fac ID 2100103 | FITS SITE 36715 | Location Name ZIP TRIP 49 | Location Street Address 1004 1ST ST | Location City HAVRE, MT 59501 | Location Phone (406) 265-9812 |
| Operating Permit Renewal Date: 23-May-2014 | | | Last inspected on: 08-Feb-2011 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|----------------------|---------------------|--|-------------------------------------|-------------|--|------------------------------|
|-----------------------------|---------------|----------------------|---------------------|--|-------------------------------------|-------------|--|------------------------------|

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in HILL County in the City of HAVRE

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|------------------|------|-----------|----------|------------------------------|----------------------------|-------------|--|---|---|---|---|---|---|---|---|---|---|---|---|---|--|--|--|---|---|---|---|---|---|---|---|-----|-----|-----|
| 1 / 01 | 3729 | 2/18/1972 | Gasoline | Asphalt Coated or Bare Steel | Fiberglass Reinforced Plas | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td></td><td></td><td></td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | ● | | | | ● | ● | ● | ● | ● | ● | ● | ● | Yes | Yes | Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |
| ● | | | | ● | ● | ● | ● | ● | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 40 / No | 10,000 | Impressed Current | None | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 2 / 02 | 3730 | 2/18/1972 | Diesel | Asphalt Coated or Bare Steel | Fiberglass Reinforced Plas | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td></td><td></td><td></td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | ● | | | | ● | ● | ● | ● | ● | ● | ● | ● | Yes | Yes | Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |
| ● | | | | ● | ● | ● | ● | ● | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 40 / No | 10,000 | Impressed Current | None | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 3 / 03 | 3731 | 2/18/1972 | Gasoline | Asphalt Coated or Bare Steel | Fiberglass Reinforced Plas | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td></td><td></td><td></td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | ● | | | | ● | ● | ● | ● | ● | ● | ● | ● | Yes | Yes | Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |
| ● | | | | ● | ● | ● | ● | ● | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 40 / No | 10,000 | Impressed Current | None | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

| | | | | | | | |
|---|---------------------------|---|---|---|---|--|--|
| Owner: Stromberg Enterprises Inc | | | | Address: PO Box 608, Havre MT 59501-0608 | | | |
| Sys Fac ID 2102166 | FITS SITE 36754 | Location Name STROMBERGS SINCLAIR | Location Street Address 1200 1ST ST | Location City HAVRE, MT 59501 | Location Phone (406) 265-3441 | | |
| Operating Permit Renewal Date: 13-Dec-2013 | | | | Last inspected on: 07-Sep-2010 | | | |

| TankID/Alt TankID | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-------------------|------------|-------------------|------------------|---|----------------------------------|-------------|---|---------------------------|---|---|---|---|---|---|---|---|---|---|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|-------------|
| 8 / 08 | 3965 | 3/1/1999 | Gasoline | Fiberglass Reinforced Plastic | Flexible Plastic | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 13 / No | 12,000 | None | Double-Walled | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 9 / 09 | 3966 | 3/1/1999 | Gasoline | Fiberglass Reinforced Plastic | Flexible Plastic | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 13 / No | 8,000 | None | Double-Walled | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10 / 10 | 3967 | 3/1/1999 | Diesel | Fiberglass Reinforced Plastic | Flexible Plastic | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 13 / No | 4,000 | None | Double-Walled | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

| | | | | | | | |
|---|---------------------------|---|--|--|---|--|--|
| Owner: EZZIES WHOLESALE INC | | | | Address: PO Box 1770, Malta MT 59538-1770 | | | |
| Sys Fac ID 2107467 | FITS SITE 36884 | Location Name EZZIES GENEX CARDTROL | Location Street Address 5 1ST ST | Location City HAVRE, MT 59501 | Location Phone (406) 265-7636 | | |
| Operating Permit Renewal Date: 07-Jan-2015 | | | | Last inspected on: 08-Sep-2011 | | | |

| TankID/Alt TankID | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-------------------|------------|-------------------|------------------|---|----------------------------------|-------------|---|---------------------------|---|---|---|---|---|---|---|---|---|---|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|-------------|
| 8 / 08 | 538 | 6/1/1997 | Diesel | Fiberglass Reinforced Plastic | Flexible Plastic | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 14 / No | 4,000 | None | Double-Walled | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 9 / 09 | 539 | 6/1/1997 | Diesel | Fiberglass Reinforced Plastic | Flexible Plastic | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 14 / No | 4,000 | None | Double-Walled | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10 / 10 | 540 | 6/1/1997 | Gasoline | Fiberglass Reinforced Plastic | Flexible Plastic | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 14 / No | 4,000 | None | Double-Walled | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 11 / 11 | 541 | 6/28/1997 | Diesel | Fiberglass Reinforced Plastic | Flexible Plastic | Pressurized | <table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 14 / No | 6,000 | None | Double-Walled | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in HILL County in the City of HAVRE

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|------------------|-----|-------------------------------------|-------------------------------------|-------------------------------|------------------|-------------|--|---|---|---|-------------------------------------|---|---|---|---|---|---|---|---|---|--|-------------------------------------|--|---|--|---|--|---|--|---|--|---|---|---|-----|-----|-----|
| 12 / 12 | 542 | 6/28/1997 | Gasoline | Fiberglass Reinforced Plastic | Flexible Plastic | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes | Yes | Yes |
| A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 14 / No | 6,000 | None | Double-Walled | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 13 / 13 | 543 | 6/1/1997 | Diesel | Fiberglass Reinforced Plastic | Flexible Plastic | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes | Yes | Yes |
| A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |
| Currently in Use | | 14 / No | 8,000 | None | Double-Walled | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

| | | | | | |
|---|---------------------------|--|--|---|---|
| Owner: Rocky Mountain Oil Co Inc | | | Address: PO Box 1224, Minneapolis MN 55440-1224 | | |
| Sys Fac ID 2108068 | FITS SITE 36895 | Location Name HOLIDAY STATIONSTORE 272 | Location Street Address 200 1ST ST W | Location City HAVRE, MT 59501 | Location Phone (406) 265-8421 |
| Operating Permit Renewal Date: 04-Dec-2014 | | | Last inspected on: 06-Sep-2011 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------------------------|---------------|-------------------------------------|-------------------------------------|--|-------------------------------------|-------------|--|------------------------------|---|---|-------------------------------------|---|---|---|---|---|---|---|---|---|--|-------------------------------------|--|---|--|---|--|---|--|---|--|---|---|---|-------------|
| 1 / 01 Currently in Use | 3013 | 10/1/1985 26 / No | Gasoline 12,000 | STI-P3 Impressed Current | Bare Steel None | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes Yes Yes |
| A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 2 / 02 Currently in Use | 3014 | 10/1/1985 26 / No | Gasoline 12,000 | STI-P3 Impressed Current | Bare Steel None | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes Yes Yes |
| A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 3 / 03 Currently in Use | 3015 | 10/1/1985 26 / No | Gasoline 10,000 | STI-P3 Impressed Current | Bare Steel None | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes Yes Yes |
| A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 4 / 04 Currently in Use | 3016 | 10/1/1985 26 / No | Diesel 10,000 | STI-P3 Impressed Current | Bare Steel None | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes Yes Yes |
| A | B | C | <input checked="" type="checkbox"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | |

| | | | | | |
|---|---------------------------|---|--|---|---|
| Owner: Town Pump of Havre Inc | | | Address: PO Box 6000, Butte MT 59702-6000 | | |
| Sys Fac ID 2108705 | FITS SITE 36904 | Location Name TOWN PUMP INC HAVRE | Location Street Address 136 1ST ST W | Location City HAVRE, MT 59501 | Location Phone (406) 265-9577 |
| Operating Permit Renewal Date: 01-Apr-2013 | | | Last inspected on: 11-Dec-2009 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------------------------|---------------|-------------------------------------|---------------------|--|-------------------------------------|-------------|--|-------------------------------------|-------------------------------------|---|---|---|---|---|---|-------------------------------------|-------------------------------------|---|---|---|--|-------------------------------------|--|---|--|---|--|---|--|---|--|---|---|---|-------------|
| 3 / 03 Currently in Use | 2472 | 11/15/1989 22 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | D | E | F | G | H | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes Yes Yes |
| A | B | C | D | E | F | G | H | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | K | L | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 4 / 04 Currently in Use | 2473 | 11/15/1989 22 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | D | E | F | G | H | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes Yes Yes |
| A | B | C | D | E | F | G | H | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | K | L | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 5 / 05 Currently in Use | 2474 | 11/15/1989 22 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | D | E | F | G | H | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes Yes Yes |
| A | B | C | D | E | F | G | H | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | K | L | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 6 / 06 Currently in Use | 2475 | 11/15/1989 22 / No | Diesel 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Pressurized | <table border="1" style="font-size: 8px; border-collapse: collapse;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td colspan="2"><input checked="" type="checkbox"/></td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2">H</td><td colspan="2">I</td><td>J</td><td>K</td><td>L</td></tr> </table> | A | B | C | D | E | F | G | H | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | K | L | B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | Yes Yes Yes |
| A | B | C | D | E | F | G | H | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | K | L | | | | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="checkbox"/> | | E | | F | | H | | I | | J | K | L | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in HILL County in the City of HAVRE

| | | | | | |
|---|---------------------------|---------------------------------------|--|---|---|
| Owner: BNSF Railway Havre | | | Address: 235 Main St, Havre MT 59501-3523 | | |
| Sys Fac ID 2109548 | FITS SITE 36971 | Location Name BN HAVRE WWTP | Location Street Address 235 MAIN ST | Location City HAVRE, MT 59501 | Location Phone (406) 265-0483 |
| Operating Permit Renewal Date: 26-Aug-2014 | | | Last inspected on: 30-Jun-2011 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|------------------------------|---------------|-----------------------|---------------------|--|-------------------------------------|-------------|---|------------------------------|
| 6 / 22 Currently in Use | 506 | 6/21/1993 18 / No | Waste Oil 20,000 | Cathodically Protected Steel Double-Walled | No Piping None | Not Listed | A B C <input checked="" type="checkbox"/> E F <input checked="" type="checkbox"/> H I J K L B <input type="checkbox"/> D E F G H I J K L | Yes Yes Yes |
| 17 / S23 Currently In Use | 4877 | 1/22/2004 08 / Yes | Diesel 640,000 | Concrete None | Galvanized Steel none | Pressurized | A B C D E F G H I J <input checked="" type="checkbox"/> L B <input type="checkbox"/> D E F G H I J K <input checked="" type="checkbox"/> | Yes Yes Yes |
| 18 / S24 Currently In Use | 4878 | 1/22/2004 08 / Yes | Diesel 640,000 | Concrete None | Galvanized Steel none | Pressurized | A B C D E F G H I J <input checked="" type="checkbox"/> L B <input type="checkbox"/> D E F G H I J K <input checked="" type="checkbox"/> | Yes Yes Yes |

| | | | | | |
|---|---------------------------|--|--|---|-----------------------|
| Owner: EZZIES WHOLESALE INC | | | Address: PO Box 1770, Malta MT 59538-1770 | | |
| Sys Fac ID 2112751 | FITS SITE 37005 | Location Name EZZIES WHOLESALE HAVRE | Location Street Address 726 1ST ST W | Location City HAVRE, MT 59501 | Location Phone |
| Operating Permit Renewal Date: 09-Jul-2013 | | | Last inspected on: 10-Mar-2010 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|----------------------|---------------------|--|-------------------------------------|-------------|--|------------------------------|
| 1 / 06 Currently in Use | 883 | 7/1/1992 19 / No | Diesel 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Pressurized | A B C D E F G H I J K L B <input checked="" type="checkbox"/> E F G H I J K L | Yes Yes Yes |
| 2 / 07 Currently in Use | 884 | 7/1/1992 19 / No | Diesel 12,000 | Cathodically Protected Steel None | Fiberglass Reinforced Plas None | Pressurized | A B C D E F G H I J K L B <input checked="" type="checkbox"/> E F G H I J K L | Yes Yes Yes |
| 3 / 05 Currently in Use | 882 | 7/1/1992 19 / No | Gasoline 12,000 | Cathodically Protected Steel None | Fiberglass Reinforced Plas None | Pressurized | A B C D E F G H I J K L B <input checked="" type="checkbox"/> E F G H I J K L | Yes Yes Yes |
| 4 / 08 Currently in Use | 885 | 7/1/1992 19 / No | Diesel 12,000 | Cathodically Protected Steel None | Fiberglass Reinforced Plas None | Pressurized | A B C D E F G H I J K L B <input checked="" type="checkbox"/> E F G H I J K L | Yes Yes Yes |
| 5 / 01 Currently in Use | 878 | 7/1/1992 19 / No | Solvents 4,000 | Cathodically Protected Steel None | Fiberglass Reinforced Plas None | Pressurized | A B C D E F G H I J K L B <input checked="" type="checkbox"/> E F G H I J K L | Yes Yes Yes |
| 6 / 02 Currently in Use | 879 | 7/1/1992 19 / No | Gasoline 12,000 | Cathodically Protected Steel None | Fiberglass Reinforced Plas None | Pressurized | A B C D E F G H I J K L B <input checked="" type="checkbox"/> E F G H I J K L | Yes Yes Yes |
| 7 / 03 Currently in Use | 880 | 7/1/1992 19 / No | Diesel 12,000 | Cathodically Protected Steel None | Fiberglass Reinforced Plas None | Pressurized | A B C D E F G H I J K L B <input checked="" type="checkbox"/> E F G H I J K L | Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in HILL County in the City of HAVRE

8 / 04 881 7/1/1992 Gasoline Cathodically Protected Steel Fiberglass Reinforced Plas Pressurized
 Currently in Use 19 / No 12,000 None None

A B C D E F G H I J K L
B E F G H I J K L Yes Yes Yes

| | | | |
|---|---------------------------|--|---|
| Owner: William Dritshulas | | Address: PO Box 1430, Havre MT 59501-1430 | |
| Sys Fac ID 2112763 | FITS SITE 37006 | Location Name EMPORIUM FOOD & FUEL | Location Street Address 1415 1ST ST |
| | | Location City HAVRE, MT 59501 | Location Phone (406) 265-8861 |
| Operating Permit Renewal Date: 30-Jun-2013 | | Last inspected on: 10-Mar-2010 | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|----------------------|---------------------|--|-------------------------------------|-------------|--|------------------------------|
| 1 / 01 Currently in Use | 2971 | 8/1/1992 19 / No | Diesel 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Pressurized | <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L | Yes Yes Yes |
| 2 / 02 Currently in Use | 2972 | 8/1/1992 19 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Pressurized | <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L | Yes Yes Yes |
| 3 / 03 Currently in Use | 2973 | 8/1/1992 19 / No | Gasoline 6,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Pressurized | <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L | Yes Yes Yes |
| 4 / 04 Currently in Use | 2974 | 8/1/1992 19 / No | Gasoline 6,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Pressurized | <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L | Yes Yes Yes |

| | | | |
|---|---------------------------|--|---|
| Owner: Hill County Commissioners | | Address: 315 4th St, Havre MT 59501-3923 | |
| Sys Fac ID 5613886 | FITS SITE 45106 | Location Name HILL COUNTY JUSTICE CENTER | Location Street Address 1450 2ND ST W |
| | | Location City HAVRE, MT 59501 | Location Phone |
| Operating Permit Renewal Date: 30-Apr-2013 | | Last inspected on: 10-Nov-2009 | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|-----------------------|---------------------|--|---------------------------------------|-------------|--|------------------------------|
| 1 / S1 Currently In Use | 1377 | 7/20/1998 13 / Yes | Diesel 2,000 | Concrete None | Bare Steel Secondary Containment C | Pressurized | <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input checked="" type="checkbox"/> K <input type="checkbox"/> L | Yes Yes No |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in HILL County in the City of HINGHAM

| | | | | | |
|---|---------------------------|--|--|---|---|
| Owner: Hingham Motors | | | Address: PO Box 226, Hingham MT 59528-0228 | | |
| Sys Fac ID 2100783 | FITS SITE 36730 | Location Name HINGHAM MOTORS | Location Street Address CENTRAL AVE & 1ST ST N | Location City HINGHAM, MT 59528 | Location Phone (406) 397-3215 |
| Operating Permit Renewal Date: 14-May-2014 | | | Last inspected on: 10-Feb-2011 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|-----------------------|---------------------|--|-------------------------------------|-------------|--|------------------------------|
| | | | | | | | Piping Release Detection | |
| 4 / S06 Currently in Use | 1383 | 7/25/1995 16 / Yes | Diesel 12,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |
| 7 / S07 Currently In Use | 1384 | 10/1/1998 13 / Yes | Gasoline 12,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |
| 8 / S08 Currently In Use | 1385 | 10/1/1998 13 / Yes | Gasoline 12,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |
| 9 / S09 Currently In Use | 1386 | 10/1/1998 13 / Yes | Diesel 12,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in HILL County in the City of INVERNESS

| | | | | | |
|---|---------------------------|---|--|---|---|
| Owner: Fraser Oil Inc | | Address: PO Box 770, Inverness MT 59530-0770 | | | |
| Sys Fac ID 2107327 | FITS SITE 36882 | Location Name FRASER OIL INC INVERNESS | Location Street Address US HIGHWAY 2 | Location City INVERNESS, MT 59530 | Location Phone (406) 292-3833 |
| Operating Permit Renewal Date: 27-Mar-2015 | | | Last inspected on: 20-Oct-2011 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | | Installed Spill/Over/CPMe |
|-----------------------------|---------------|-----------------------|---------------------|--|-------------------------------------|--------------|--|-------------|------------------------------|
| | | | | | | | Piping Release Detection | | |
| 4 / 04 Currently in Use | 1120 | 10/15/1992 19 / No | Gasoline 1,000 | STI-P3 None | Fiberglass Reinforced Plas None | Safe Suction | A B C ● E F G H I J K L B D E F G H I J ● L | Yes Yes Yes | |
| 5 / 05 Currently in Use | 1121 | 10/15/1992 19 / No | Diesel 1,000 | STI-P3 None | Fiberglass Reinforced Plas None | Safe Suction | A B C ● E F G H I J K L B D E F G H I J ● L | Yes Yes Yes | |
| 6 / 06 Currently in Use | 1122 | 10/15/1992 19 / No | Gasoline 1,000 | STI-P3 None | Fiberglass Reinforced Plas None | Safe Suction | A B C ● E F G H I J K L B D E F G H I J ● L | Yes Yes Yes | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in HILL County in the City of KREMLIN

| | | | |
|---|---------------------------|--|---|
| Owner: Farmers Union Oil Co Kremlin | | Address: PO Box 110, Kremlin MT 59532-0110 | |
| Sys Fac ID 2110030 | FITS SITE 36985 | Location Name FARMERS UNION OIL CO KREMLIN | Location Street Address 110 MAIN ST |
| | | Location City KREMLIN, MT 59532 | Location Phone (406) 372-3248 |
| Operating Permit Renewal Date: 11-Oct-2013 | | Last inspected on: 11-Oct-2010 | |

| TankID/Alt TankID | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|------------|-----------------------|--------------------|---|-------------------------------------|-------------|--|---------------------------|---|-------------------------------------|---|---|---|---|---|---|---|-------------------------------------|---|---|--|---|---|---|-------------------------------------|---|---|---|---|---|--|-------------|
| 1 / S1 Currently in Use | 983 | 1/16/1972 40 / Yes | Gasoline 10,000 | Asphalt Coated or Bare Steel None | Flexible Plastic Double-Walled | Pressurized | <table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | <input checked="" type="checkbox"/> | L | B | | D | E | F | <input checked="" type="checkbox"/> | H | I | J | K | L | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | <input checked="" type="checkbox"/> | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | E | F | <input checked="" type="checkbox"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | |
| 2 / S2 Currently in Use | 984 | 1/16/1972 40 / Yes | Gasoline 15,000 | Asphalt Coated or Bare Steel None | Flexible Plastic Double-Walled | Pressurized | <table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | <input checked="" type="checkbox"/> | L | B | | D | E | F | <input checked="" type="checkbox"/> | H | I | J | K | L | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | <input checked="" type="checkbox"/> | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | E | F | <input checked="" type="checkbox"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in HILL County in the City of RUDYARD

| | | | | | |
|---|---------------------------|--|---|---|---|
| Owner: Toners Tire Rama | | | Address: PO Box 266, Rudyard MT 59540-0266 | | |
| Sys Fac ID 2102475 | FITS SITE 36757 | Location Name TONERS TIRE RAMA | Location Street Address 103 MAIN ST | Location City RUDYARD, MT 59540 | Location Phone (406) 355-4131 |
| Operating Permit Renewal Date: 24-Sep-2013 | | | Last inspected on: 14-Jun-2010 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|----------------------|---------------------|--|-------------------------------------|--------------|--|------------------------------|
| 5 / 05 Currently In Use | 2108 | 11/1/1997 14 / No | Diesel 2,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Safe Suction | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 6 / 06 Currently In Use | 2109 | 11/1/1997 14 / No | Gasoline 2,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas None | Safe Suction | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |

| | | | | | |
|---|---------------------------|--|--|---|---|
| Owner: Farmers Union Oil Co Rudyard | | | Address: PO Box 290, Rudyard MT 59540-0290 | | |
| Sys Fac ID 2103509 | FITS SITE 36784 | Location Name FARMERS UNION OIL CO RUDYARD | Location Street Address 1 MAIN ST PO BOX C | Location City RUDYARD, MT 59540 | Location Phone (406) 355-4543 |
| Operating Permit Renewal Date: 28-Sep-2013 | | | Last inspected on: 23-Jul-2010 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|-----------------------|---------------------|--|---|-------------|--|------------------------------|
| 4 / S4 Currently in Use | 947 | 4/23/1966 46 / Yes | Diesel 2,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 5 / S5 Currently in Use | 948 | 4/23/1966 46 / Yes | Gasoline 10,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 6 / S6 Currently in Use | 949 | 4/23/1966 46 / Yes | Gasoline 5,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |