

Facility Summary in LAKE County in the City of ARLEE

Owner: Wilson Foods Inc			Address: 92345 US Highway 93, Arlee MT 59821-9433		
Sys Fac ID 2406788	FITS SITE 37551	Location Name WILSON FOODS	Location Street Address US HIGHWAY 93 N	Location City ARLEE, MT 59821	Location Phone (406) 726-7777
Operating Permit Renewal Date: 21-Mar-2015			Last inspected on: 17-Jan-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
10 / 10 Currently In Use	3320	11/1/1998 13 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
11 / 11 Currently In Use	3321	11/1/1998 13 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
12 / 12 Currently In Use	3322	11/1/1998 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
13 / S13 Currently In Use	4599	11/1/2001 10 / Yes	Diesel 4,000	Concrete Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C ● E F ● H I J ● L ● D E F ● H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of BIG ARM

Owner: Juanita M Daly		Address: PO Box 159, Big Arm MT 59910-0159			
Sys Fac ID 2412285	FITS SITE 37795	Location Name BIG ARM GENERAL STORE	Location Street Address 314 5TH ST	Location City BIG ARM, MT 59910	Location Phone (406) 849-5355
Operating Permit Renewal Date: 28-May-2008			Last inspected on: 02-Sep-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / 03 Temporarily Out of Use	3566	4/30/1998 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L		Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L																						
4 / 04 Temporarily Out of Use	3567	4/30/1998 13 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L		Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of Bigfork

Owner: Montana Ranch at Bigfork LLC			Address: 301 Echo Lake Rd, Bigfork MT 59911		
Sys Fac ID 6015198	FITS SITE 45486	Location Name Montana Ranch LLC	Location Street Address 1463 HWY 83	Location City Bigfork, MT 59911	Location Phone (406) 837-5109
Operating Permit Renewal Date: 23-Mar-2015			Last inspected on: 19-Mar-2012		

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	5327	8/29/2011 00 / No	Gasoline 2,500	Fiberglass Reinforced Plastic Double-Walled	Bare Steel Double-Walled	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	B	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
B	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	K	L																						
2 / 02 Currently in Use	5328	8/29/2011 00 / No	Diesel 2,500	Fiberglass Reinforced Plastic Double-Walled	Bare Steel Double-Walled	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	B	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
B	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of CHARLO

Owner: School Dist 7 J Charlo			Address: PO Box 10, Charlo MT 59824-0010		
Sys Fac ID 2402789	FITS SITE 37452	Location Name CHARLO SCHOOL DIST 7 J	Location Street Address 405 2ND AVE E	Location City CHARLO, MT 59824	Location Phone (406) 644-2207
Operating Permit Renewal Date: 27-Mar-2015			Last inspected on: 31-Jan-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
5 / S5 Currently In Use	611	7/1/1998 13 / Yes	Heating Oil 10,000	Unknown None	Flexible Plastic Double-Walled	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L		B		D	E	F	<input checked="" type="checkbox"/>	H	I	<input checked="" type="checkbox"/>	K	L	Yes Yes No
A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L																					
	B		D	E	F	<input checked="" type="checkbox"/>	H	I	<input checked="" type="checkbox"/>	K	L																					

Owner: Coulter Automotive Inc			Address: PO Box 97, Charlo MT 59824-0097		
Sys Fac ID 2404615	FITS SITE 37492	Location Name COULTER AUTOMOTIVE INC	Location Street Address S MAIN PO BOX 97	Location City CHARLO, MT 59824	Location Phone
Operating Permit Renewal Date: 05-Oct-2013			Last inspected on: 27-Jul-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																																				
3 / 03 Currently in Use	2281	7/1/1995 16 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td><input checked="" type="checkbox"/></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	<input checked="" type="checkbox"/>																								Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	
<input checked="" type="checkbox"/>																																												
4 / 04 Currently in Use	2282	7/1/1995 16 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td><input checked="" type="checkbox"/></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	<input checked="" type="checkbox"/>																								Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	
<input checked="" type="checkbox"/>																																												

Owner: Moiese Mercantile			Address: PO Box 501, Charlo MT 59824-0501		
Sys Fac ID 2406382	FITS SITE 37540	Location Name MOIESE MERCANTILE	Location Street Address 64620 MT HIGHWAY 212	Location City CHARLO, MT 59824	Location Phone (406) 644-2385
Operating Permit Renewal Date: 17-Dec-2013			Last inspected on: 27-Jul-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																																				
3 / 03 Currently In Use	3968	3/1/1999 13 / No	Gasoline 1,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L																									Yes Yes Yes
A	B	C	D	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L																																	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of ELMO

Owner: Standing Arrow Trading Post Inc			Address: 77070 US HIGHWAY 93, Elmo MT 59915-9722		
Sys Fac ID 2403906	FITS SITE 37473	Location Name STANDING ARROW TRADING POST INC	Location Street Address 77070 US HIGHWAY 93	Location City ELMO, MT 59915	Location Phone (406) 849-6100
Operating Permit Renewal Date: 01-Apr-2002			Last inspected on: 26-May-2006		

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / 03	3999	5/1/1995	Gasoline	STI-P3	Fiberglass Reinforced Plas	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>●</td><td>●</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td></tr> </table>	A	●	●	D	E	F	G	H	I	J	K	L	B			D	E	F	G	H	I	●	K	L	Yes Yes Yes
A	●	●	D	E	F	G	H	I	J	K	L																					
B			D	E	F	G	H	I	●	K	L																					
Temporarily Out of Use		16 / No	4,000	None	None																											
4 / 04	4000	5/1/1995	Gasoline	STI-P3	Fiberglass Reinforced Plas	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>●</td><td>●</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td></tr> </table>	A	●	●	D	E	F	G	H	I	J	K	L	B			D	E	F	G	H	I	●	K	L	Yes Yes Yes
A	●	●	D	E	F	G	H	I	J	K	L																					
B			D	E	F	G	H	I	●	K	L																					
Temporarily Out of Use		16 / No	8,000	None	None																											

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of PABLO

Owner: School Dist 30 Ronan			Address: PO Box R, Ronan MT 59864-0799		
Sys Fac ID 2404823	FITS SITE 37497	Location Name PABLO ELEMENTARY SCHOOL	Location Street Address 608 4TH AVE	Location City PABLO, MT 59855	Location Phone (406) 676-3390
Operating Permit Renewal Date: 25-Sep-2014			Last inspected on: 08-Apr-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / S1 Currently in Use	1903	4/28/1966 45 / No	Heating Oil 8,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes

Owner: Margaret M Bowman			Address: PO Box 277, Pablo MT 59855		
Sys Fac ID 2407562	FITS SITE 37583	Location Name JOES JIFFY STOP	Location Street Address 51356 US HIGHWAY 93	Location City Pablo, MT 59855	Location Phone (406) 676-3570
Operating Permit Renewal Date: 01-Oct-2012			Last inspected on: 11-Aug-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / 03 Currently in Use	1269	10/4/1990 21 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● E F G H I J K L	Yes Yes Yes
4 / 04 Currently in Use	1270	10/4/1990 21 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● E F G H I J K L	Yes Yes Yes
5 / 05 Currently in Use	1271	10/4/1990 21 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● E F G H I J K L	Yes Yes Yes

Owner: Quick Silver Express			Address: PO Box 278, Pablo MT 59855		
Sys Fac ID 2411124	FITS SITE 37724	Location Name QUICKSILVER EXPRESS	Location Street Address 52001 US HIGHWAY 93	Location City PABLO, MT 59855	Location Phone (406) 675-5000
Operating Permit Renewal Date: 25-Oct-2014			Last inspected on: 11-Oct-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	3296	1/1/1987 25 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of PABLO

2 / 02	3297	1/1/1987	Gasoline	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use		25 / No	8,000	None	None	● E F G H I J K L				
3 / 03	3298	1/1/1987	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use		25 / No	8,000	None	None	● E F G H I J K L				
4 / 04	5344	5/1/2011	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes	Yes	Yes
Currently in Use		00 / No	12,000	None	Double-Walled	● D E F ● H I J K L				

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of POLSON

Owner: University of Montana Flathead Lake Biological Station			Address: 32125 Bio Station Lane, Polson MT 59860		
Sys Fac ID 2400507	FITS SITE 37398	Location Name U OF M FLATHEAD LAKE BIOLOGICAL STATION	Location Street Address 32125 Bio Station Ln	Location City POLSON, MT 59860	Location Phone (406) 982-3301
Operating Permit Renewal Date: 14-Jan-2015			Last inspected on: 07-Sep-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / 05 Currently in Use	2185	3/15/1991 21 / No	Gasoline 1,000	STI-P3 Double-Walled	Fiberglass Reinforced Plas Double-Walled	U.S. Suction	A B C D E F <input checked="" type="radio"/> H I J K L <input checked="" type="radio"/> D E F G H I J K L	Yes Yes Yes
5 / S6 Currently in Use	2186	3/15/1991 21 / No	Heating Oil 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F <input checked="" type="radio"/> H I J K L <input type="radio"/> B D E F <input checked="" type="radio"/> H I J K L	Yes Yes Yes

Owner: School Dist 23 Polson			Address: 111 4th Ave E, Polson MT 59860-2132		
Sys Fac ID 2402867	FITS SITE 37454	Location Name CHERRY VALLEY SCHOOL	Location Street Address 107 8TH AVE W	Location City POLSON, MT 59860	Location Phone (406) 883-6329
Operating Permit Renewal Date: 19-Feb-2015			Last inspected on: 13-Oct-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
2 / S2 Currently in Use	1805	8/1/1990 21 / No	Heating Oil 4,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F <input checked="" type="radio"/> H I J K L <input checked="" type="radio"/> D E F G H I J K L	Yes Yes Yes

Owner: Cenex Harvest States Missoula			Address: DBA Mountain West Co Op, 4570 N Reserve St, Missoula MT 59808-1411		
Sys Fac ID 2404560	FITS SITE 37491	Location Name MOUNTAIN WEST CO OP POLSON	Location Street Address 808 MAIN ST	Location City POLSON, MT 59860	Location Phone (406) 883-5600
Operating Permit Renewal Date: 02-Dec-2014			Last inspected on: 02-Aug-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
5 / 05 Currently In Use	4155	1/1/2000 12 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C <input checked="" type="radio"/> E F G H I J K L <input type="radio"/> B D E F <input checked="" type="radio"/> H I J K L	Yes Yes Yes
6 / 06 Currently In Use	4156	1/1/2000 12 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C <input checked="" type="radio"/> E F G H I J K L <input type="radio"/> B D E F <input checked="" type="radio"/> H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of POLSON

7 / 07	4741	1/1/2000	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L			
Currently In Use		12 / No	10,000	None	Double-Walled		<input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes
8 / 08	4648	1/1/2000	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L			
Currently In Use		12 / No	5,000	None	Double-Walled		<input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes

Owner: George & Ramona Mahoney			Address: PO Box 1127, Polson MT 59860-1127		
Sys Fac ID 2405770	FITS SITE 37528	Location Name POLSON BAY GROCERY 425	Location Street Address 50451 US Highway 93	Location City POLSON, MT 59860	Location Phone (406) 883-6851
Operating Permit Renewal Date: 09-Aug-2014			Last inspected on: 10-Mar-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / 04 Currently In Use	4664	5/23/2002 09 / No	Gasoline 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
5 / 05 Currently In Use	4665	5/23/2002 09 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
6 / 06 Currently In Use	4666	5/23/2002 09 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
7 / 07 Currently In Use	4667	5/23/2002 09 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes

Owner: Pier 93			Address: 49433 US Highway 93, Polson MT 59860-2162		
Sys Fac ID 2405957	FITS SITE 37533	Location Name PIER 93	Location Street Address 9 2ND AVE W	Location City POLSON, MT 59860	Location Phone (406) 883-4531
Operating Permit Renewal Date: 30-Jun-2013			Last inspected on: 14-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / 01 Currently in Use	1802	4/23/1986 26 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
4 / 02 Currently in Use	1803	4/23/1986 26 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
6 / 06 Currently in Use	1804	11/1/1990 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of POLSON

Owner: Grits Inc			Address: 44613 US Highway 93, Polson MT 59860-7585		
Sys Fac ID 2407247	FITS SITE 37571	Location Name JETTE STORE	Location Street Address 44613 US Highway 93	Location City POLSON, MT 59860	Location Phone (406) 883-3861
Operating Permit Renewal Date: 02-Dec-2014			Last inspected on: 02-Aug-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / 04 Currently in Use	1215	4/1/1996 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B ● D E F ● H I J K L	Yes Yes Yes
5 / 05 Currently in Use	1216	4/1/1996 16 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B ● D E F ● H I J K L	Yes Yes Yes
6 / 06 Currently in Use	1217	4/1/1996 16 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B ● D E F ● H I J K L	Yes Yes Yes

Owner: Town Pump Inc Butte			Address: PO Box 6000, Butte MT 59702-6000		
Sys Fac ID 2408717	FITS SITE 37611	Location Name TOWN PUMP INC POLSON	Location Street Address 50667 US Highway 93	Location City POLSON, MT 59860	Location Phone (406) 883-9445
Operating Permit Renewal Date: 14-May-2013			Last inspected on: 29-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	2490	9/1/1982 29 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H ● J K L B ● E F ● H ● J ● L	Yes Yes Yes
2 / 02 Currently in Use	2491	9/1/1982 29 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H ● J K L B ● E F ● H ● J ● L	Yes Yes Yes
3 / 03 Currently in Use	2492	9/1/1982 29 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H ● J K L B ● E F ● H ● J ● L	Yes Yes Yes
4 / 04 Currently in Use	2493	9/1/1982 29 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H ● J K L B ● E F ● H ● J ● L	Yes Yes Yes
5 / 05 Currently in Use	2494	9/1/1982 29 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H ● J K L B ● E F ● H ● J ● L	Yes Yes Yes
11 / 11 Currently In Use	4819	10/24/2002 09 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F ● H ● J K L B ● E F ● H ● J K L	Yes Yes Yes
12 / 12 Currently In Use	4820	10/24/2002 09 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F ● H ● J K L B ● E F ● H ● J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of POLSON

Owner: City of Polson			Address: 106 1st St E, Polson MT 59860-2137		
Sys Fac ID 2411824	FITS SITE 37772	Location Name POLSON COUNTRY CLUB	Location Street Address 111 BAYVIEW DR	Location City POLSON, MT 59860	Location Phone
Operating Permit Renewal Date: 08-Nov-2013			Last inspected on: 01-Sep-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																										
1 / 01 Currently in Use	647	8/14/1990 21 / No	Gasoline 500	Cathodically Protected Steel None	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small;"> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> </table>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Yes Yes Yes
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						

Owner: Confederated Salish & Kootenai Tribe			Address: PO Box 278, Pablo MT 59855-0278		
Sys Fac ID 5613869	FITS SITE 45093	Location Name KWATAQNUK RESORT	Location Street Address 49708 US Highway 93	Location City POLSON, MT 59860	Location Phone (406) 883-3636
Operating Permit Renewal Date: 01-Apr-2002			Last inspected on: 09-May-1997		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																										
1 / 01 Currently In Use		5/1/1991 20 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> </table>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Yes Yes Yes
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						

Owner: Safeway Stores Inc			Address: 1121 124th Ave NE, Bellevue WA 98005-2101		
Sys Fac ID 6015097	FITS SITE 45413	Location Name SAFEWAY FUEL STATION 1646	Location Street Address 40772 MT Highway 35	Location City Polson, MT 59860	Location Phone (425) 201-6301
Operating Permit Renewal Date: 28-Mar-2015			Last inspected on: 01-Dec-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																										
1 / 01 Currently in Use	5164	5/22/2008 03 / No	Gasoline 20,000	Composite (Steel w/ FRP) Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> </table>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Yes Yes Yes
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						
2 / 02 Currently in Use	5165	5/22/2008 03 / No	Gasoline 10,000	Composite (Steel w/ FRP) Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> </table>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Yes Yes Yes
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						
3 / 03 Currently in Use	5166	5/22/2008 03 / No	Diesel 10,000	Composite (Steel w/ FRP) Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> <tr><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td><td><input type="radio"/></td></tr> </table>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Yes Yes Yes
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of RAVALLI

Owner: Marcia Harris			Address: PO Box 630223, Ravalli MT 59863-0223		
Sys Fac ID 2409997	FITS SITE 37644	Location Name RAVALLI STORE	Location Street Address 205 BUFFALO ST	Location City RAVALLI, MT 59863	Location Phone (406) 745-3866
Operating Permit Renewal Date: 19-Oct-2007			Last inspected on: 02-Sep-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection		Installed Spill/Over/CPMe
							Piping Release Detection		
1 / 01 Temporarily Out of Use	3464	9/1/1989 22 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C ● E F G H I J K L B D E F ● H I ● K L	Yes Yes Yes	
2 / 02 Temporarily Out of Use	3465	9/1/1989 22 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C ● E F G H I J K L B D E F ● H I ● K L	Yes Yes Yes	
3 / 03 Temporarily Out of Use	3466	9/1/1989 22 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C ● E F G H I J K L B D E F ● H I ● K L	Yes Yes Yes	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of RONAN

Owner: Saint Luke Hospital			Address: 107 6th Ave SW, Ronan MT 59864-2634		
Sys Fac ID 2403736	FITS SITE 37471	Location Name MISSION MOUNTAIN MEDICINE RONAN	Location Street Address 107 6TH AVE SW	Location City RONAN, MT 59864	Location Phone (406) 676-4441
Operating Permit Renewal Date: 16-Oct-2014			Last inspected on: 12-Aug-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / S3 Currently In Use	4369	11/1/1999 12 / Yes	Diesel 2,000	Unknown None	Copper Secondary Containment C	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes No

Owner: Cenex Harvest States Missoula			Address: DBA Mountain West Co Op, 4570 N Reserve St, Missoula MT 59808-1411		
Sys Fac ID 2404530	FITS SITE 37489	Location Name MOUNTAIN WEST CO OP RONAN	Location Street Address 63932 US Highway 93	Location City RONAN, MT 59864	Location Phone (406) 676-2201
Operating Permit Renewal Date: 01-Jul-2014			Last inspected on: 31-Mar-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
9 / 09 Currently In Use	2829	5/1/1997 14 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L D E F G H I J K L	Yes Yes Yes
10 / 10 Currently In Use	2830	5/1/1997 14 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L D E F G H I J K L	Yes Yes Yes
11 / 11 Currently In Use	2831	5/1/1997 14 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L D E F G H I J K L	Yes Yes Yes
12 / 12 Currently In Use	2832	5/1/1997 14 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L D E F G H I J K L	Yes Yes Yes
13 / 13 Currently In Use	2833	5/1/1997 14 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of RONAN

Owner: Lake County Joint Airport Board			Address: Lake County Courthouse, 106 4th Ave E, Polson MT 59860-2133		
Sys Fac ID 2404649	FITS SITE 37493	Location Name RONAN AIRPORT	Location Street Address 35564 Ronan Airport Rd	Location City RONAN, MT 59864	Location Phone (406) 676-3461
Operating Permit Renewal Date: 26-Apr-2013			Last inspected on: 20-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
2 / 02 Currently In Use	3984	4/1/1999 13 / No	Jet Fuel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
3 / 03 Currently In Use	3985	4/1/1999 13 / No	Aviation Gas 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B ● E F ● H I J K L	Yes Yes Yes

Owner: School Dist 30 Ronan			Address: PO Box R, Ronan MT 59864-0799		
Sys Fac ID 2404824	FITS SITE 37498	Location Name EAST OF RONAN MIDDLE SCHOOL	Location Street Address 200 ROUND BUTTE ROAD E	Location City RONAN, MT 59864	Location Phone (406) 676-3390
Operating Permit Renewal Date: 13-Sep-2014			Last inspected on: 08-Apr-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / S5 Currently In Use	1904	8/1/1996 15 / No	Heating Oil 10,000	Fiberglass Reinforced Plastic None	Copper Secondary Containment C	U.S. Suction	A B C D E F G H I J K L B D E F G H I J K ●	Yes Yes No

Owner: Arnies Gas and Tire Center Inc			Address: 63145 US Highway 93, Ronan MT 59864-2808		
Sys Fac ID 2405517	FITS SITE 37515	Location Name ARNIES GAS AND TIRE CENTER INC	Location Street Address 63145 US Highway 93	Location City RONAN, MT 59864	Location Phone (406) 676-0400
Operating Permit Renewal Date: 15-Aug-2014			Last inspected on: 16-Mar-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 04 Currently in Use	3888	5/7/1978 33 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
5 / 03 Currently in Use	3889	5/8/1971 40 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of RONAN

6 / 02	3890	5/8/1971	Gasoline	Cathodically Protected Steel	Fiberglass Reinforced Plas	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L			
Currently in Use		40 / No	6,000	Lined Interior/Impressed Curre	None		<input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes
7 / 01	3891	5/8/1971	Gasoline	Cathodically Protected Steel	Fiberglass Reinforced Plas	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L			
Currently in Use		40 / No	10,000	Lined Interior/Impressed Curre	None		<input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes

Owner: Joes Jiffy Stop Inc			Address: PO Box 277, Pablo MT 59855-0277		
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone
2405768	37526	DYNO MART	303 US HIGHWAY 93 N	RONAN, MT 59864	(406) 676-3570
Operating Permit Renewal Date: 09-Sep-2014			Last inspected on: 16-Mar-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 03 Currently In Use	1317	4/1/1992 20 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
2 / 01 Currently In Use	1315	11/13/1984 27 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
3 / 02 Currently In Use	1316	11/13/1984 27 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes

Owner: Johns Fuel Farm Inc			Address: 14 Cleveland St SE, Ronan MT 59864-3027		
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone
2407437	37577	JOHNS FUEL FARM INC	14 Cleveland St SE	RONAN, MT 59864	(406) 676-3461
Operating Permit Renewal Date: 26-Apr-2013			Last inspected on: 20-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	3394	4/23/1961 51 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Bare Steel Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes No
2 / 02 Currently in Use	3395	4/23/1961 51 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Bare Steel Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes No
3 / 04 Currently in Use	3397	4/24/1971 41 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
4 / 05 Currently in Use	3398	4/24/1971 41 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Bare Steel Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes No
5 / 06 Currently in Use	3399	4/23/1961 51 / No	Heating Oil 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Bare Steel Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of RONAN

11 / 03 3396 4/24/1971 Diesel Fiberglass Reinforced Plastic Bare Steel Pressurized A B C E F G H I J K L
 Currently in Use 41 / No 8,000 None Double-Walled D E F H I J K L Yes Yes No

Owner: Town Pump Inc Butte			Address: PO Box 6000, Butte MT 59702-6000		
Sys Fac ID 2408718	FITS SITE 37612	Location Name TOWN PUMP INC RONAN	Location Street Address 63459 US Highway 93	Location City RONAN, MT 59864	Location Phone (406) 676-5290
Operating Permit Renewal Date: 14-May-2013			Last inspected on: 29-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	4822	4/14/1972 40 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
2 / 02 Currently in Use	4823	4/14/1972 40 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
3 / 03 Currently in Use	4824	4/14/1972 40 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
4 / 04 Currently in Use	4825	4/14/1980 32 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
5 / 05 Currently in Use	5073	7/5/2007 04 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> D <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes

Owner: Confederated Salish & Kootenai Tribe			Address: PO Box 278, Pablo MT 59855-0278		
Sys Fac ID 2410386	FITS SITE 37675	Location Name KICKING HORSE JOB CORPS CENTER	Location Street Address 33091 Mollmann Pass Trl	Location City RONAN, MT 59864	Location Phone (406) 644-2217
Operating Permit Renewal Date: 01-Apr-2002			Last inspected on: 15-May-1998		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 14 Currently in Use		3/27/1995 17 / No	Diesel 1,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
2 / 15 Currently in Use		3/27/1995 17 / No	Gasoline 1,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
3 / 13 Currently in Use		3/27/1995 17 / No	Diesel 1,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of SAINT IGNATIUS

Owner: School Dist 28 Saint Ignatius			Address: PO Box 1540, Saint Ignatius MT 59865-1540		
Sys Fac ID 2403762	FITS SITE 37472	Location Name SAINT IGNATIUS SCHOOL	Location Street Address 4TH & BLAINE ST	Location City SAINT IGNATIUS, MT 59865	Location Phone (406) 745-3811
Operating Permit Renewal Date: 26-Feb-2015			Last inspected on: 13-Oct-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																												
3 / 03 Currently In Use	4563	6/1/1997 14 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	U.S. Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="3"></td><td>B</td><td colspan="3"></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L				B				D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																									
			B				D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					

Owner: Hi Noon Petroleum Missoula			Address: PO Box 7578, Missoula MT 59807-7578		
Sys Fac ID 2405769	FITS SITE 37527	Location Name ALLARDS GENERAL STORE 447	Location Street Address US HIGHWAY 93 N PO BOX 460	Location City SAINT IGNATIUS, MT 59865	Location Phone (406) 745-9192
Operating Permit Renewal Date: 13-Mar-2015			Last inspected on: 11-Oct-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																													
4 / 04 Currently in Use	5042	12/1/2005 06 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="3"></td><td>B</td><td colspan="3"></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L				B				D	E	F	G	H	I	J	K	<input checked="" type="checkbox"/>	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																										
			B				D	E	F	G	H	I	J	K	<input checked="" type="checkbox"/>	L																					
5 / 05 Currently in Use	5043	12/1/2005 06 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="3"></td><td>B</td><td colspan="3"></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L				B				D	E	F	G	H	I	J	K	<input checked="" type="checkbox"/>	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																										
			B				D	E	F	G	H	I	J	K	<input checked="" type="checkbox"/>	L																					

Owner: Morton & Coffman LLC			Address: PO Box 507, Saint Ignatius MT 59865-0507		
Sys Fac ID 2410647	FITS SITE 37698	Location Name STUARTS SERVICE CENTER INC	Location Street Address 240 MOUNTAIN VIEW DR	Location City SAINT IGNATIUS, MT 59865	Location Phone (406) 745-3696
Operating Permit Renewal Date: 22-Jan-2015			Last inspected on: 13-Oct-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																											
1 / 06 Currently in Use	4595	5/1/1995 16 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="3"></td><td><input checked="" type="checkbox"/></td><td colspan="3"></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L				<input checked="" type="checkbox"/>				E	F	G	H	I	J	K	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																								
			<input checked="" type="checkbox"/>				E	F	G	H	I	J	K	L																					
2 / 07 Currently in Use	4596	5/1/1995 16 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plas None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="3"></td><td><input checked="" type="checkbox"/></td><td colspan="3"></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L				<input checked="" type="checkbox"/>				E	F	G	H	I	J	K	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																								
			<input checked="" type="checkbox"/>				E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in LAKE County in the City of SAINT IGNATIUS

3 / 08
Currently in Use

4597

5/1/1995
16 / No

Diesel
6,000

Cathodically Protected Steel
None

Fiberglass Reinforced Plas
None

Pressurized

A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L

Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed