

Facility Summary in MINERAL County in the City of ALBERTON

Owner: Cenex Harvest States Missoula			Address: DBA Mountain West Co Op, 4570 N Reserve St, Missoula MT 59808-1411		
Sys Fac ID 5613785	FITS SITE 45018	Location Name MOUNTAIN WEST CO OP ALBERTON	Location Street Address 415 RAILROAD AVE	Location City ALBERTON, MT 59820	Location Phone (406) 543-8383
Operating Permit Renewal Date: 30-Apr-2013			Last inspected on: 22-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe
							Piping Release Detection	
1 / S1 Currently In Use	3858	8/1/1997 14 / Yes	Gasoline 12,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes
2 / S2 Currently In Use	3859	8/1/1997 14 / Yes	Diesel 12,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes
3 / S3 Currently In Use	3860	8/1/1997 14 / Yes	Diesel 10,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes
4 / S4 Currently In Use	3861	8/1/1997 14 / Yes	Gasoline 4,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MINERAL County in the City of HAUGAN

Owner: Silver Dollar Ventures Inc			Address: I-90 & Exit 16, PO Box 420038, Haugan MT 59842-0038		
Sys Fac ID 3113289	FITS SITE 39686	Location Name SILVER EXPRESS EXXON	Location Street Address EXIT 16 & INTERSTATE 90	Location City HAUGAN, MT 59842	Location Phone (406) 678-4242
Operating Permit Renewal Date: 28-Aug-2013			Last inspected on: 09-Apr-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe																								
							Piping Release Detection																									
1 / 01 Currently in Use	3161	4/1/1994 18 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					
2 / 02 Currently in Use	3162	4/1/1994 18 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					
3 / 03 Currently in Use	3163	4/1/1994 18 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					
4 / 04 Currently in Use	3164	4/1/1994 18 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MINERAL County in the City of SAINT REGIS

Owner: Lindevco Inc		Address: PO Box 190, Saint Regis MT 59866-0190			
Sys Fac ID 3107690	FITS SITE 39630	Location Name SAINT REGIS TRAVEL CENTER	Location Street Address 100 MULLAN ROAD W	Location City SAINT REGIS, MT 59866	Location Phone (406) 649-2407
Operating Permit Renewal Date: 17-Oct-2014			Last inspected on: 31-May-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe																								
							Piping Release Detection																									
2 / 02 Currently in Use	3813	4/22/1985 27 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Galvanized Steel None	Pressurized	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					
3 / 03 Currently in Use	3814	4/22/1985 27 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Galvanized Steel None	Pressurized	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					
4 / 04 Currently in Use	3815	4/22/1985 27 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Galvanized Steel None	Pressurized	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MINERAL County in the City of SALTESE

Owner: Bonneville Power Administration Kalispell		Address: 2520 US Highway 2 E, Kalispell MT 59901-2312	
Sys Fac ID 3107747	FITS SITE 39631	Location Name TAFT SUBSTATION	Location Street Address RANDOLPH CREEK RD
		Location City SALTESE, MT 59867	Location Phone (406) 257-4385
Operating Permit Renewal Date: 18-Aug-2013		Last inspected on: 16-Aug-2010	

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / 03 Currently in Use	478	10/1/1990 21 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Secondary Containment C	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr> <td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td><td></td> </tr> </table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>		Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MINERAL County in the City of SUPERIOR

Owner: Mineral County Health Dept			Address: PO Box 396, Superior MT 59872-0396		
Sys Fac ID 3102302	FITS SITE 39578	Location Name MINERAL COUNTY COURTHOUSE UST	Location Street Address 300 RIVER ST	Location City SUPERIOR, MT 59872	Location Phone (406) 822-3525
Operating Permit Renewal Date: 25-Jul-2015			Last inspected on: 16-Apr-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
2 / S2 Currently in Use	4450	5/1/1994 17 / No	Heating Oil 5,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	B		D	E	F	<input checked="" type="checkbox"/>	H	I	<input checked="" type="checkbox"/>	K	L		Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					
B		D	E	F	<input checked="" type="checkbox"/>	H	I	<input checked="" type="checkbox"/>	K	L																						

Owner: Jo-Joe Investments			Address: PO Box 413, Saint Regis MT 59866-0413		
Sys Fac ID 3107433	FITS SITE 39626	Location Name DURANGOS INC	Location Street Address 204 4TH AVE E	Location City SUPERIOR, MT 59872	Location Phone (406) 822-4967
Operating Permit Renewal Date: 26-Apr-2015			Last inspected on: 17-Feb-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	3816	4/23/1984 28 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Galvanized Steel None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td><input checked="" type="checkbox"/></td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	<input checked="" type="checkbox"/>	C	D	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L	B		<input checked="" type="checkbox"/>	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L		Yes Yes Yes
A	<input checked="" type="checkbox"/>	C	D	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L																					
B		<input checked="" type="checkbox"/>	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L																						
2 / 02 Currently in Use	3817	4/23/1984 28 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Galvanized Steel None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td><input checked="" type="checkbox"/></td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	<input checked="" type="checkbox"/>	C	D	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L	B		<input checked="" type="checkbox"/>	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L		Yes Yes Yes
A	<input checked="" type="checkbox"/>	C	D	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L																					
B		<input checked="" type="checkbox"/>	E	F	G	H	<input checked="" type="checkbox"/>	J	K	L																						

Owner: Town Pump of Superior Inc			Address: PO Box 6000, Butte MT 59702-6000		
Sys Fac ID 3108719	FITS SITE 39638	Location Name TOWN PUMP INC SUPERIOR	Location Street Address 3961 Diamond Match Rd	Location City SUPERIOR, MT 59872	Location Phone (406) 822-4451
Operating Permit Renewal Date: 14-May-2013			Last inspected on: 25-Feb-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	2538	1/22/1970 42 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	K	L	B		<input checked="" type="checkbox"/>	E	F	G	H	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	K	L	Yes Yes Yes
A	B	C	D	E	F	G	H	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	K	L																					
B		<input checked="" type="checkbox"/>	E	F	G	H	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	K	L																					
2 / 02 Currently in Use	2539	1/22/1970 42 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	K	L	B		<input checked="" type="checkbox"/>	E	F	G	H	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	K	L	Yes Yes Yes
A	B	C	D	E	F	G	H	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	K	L																					
B		<input checked="" type="checkbox"/>	E	F	G	H	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MINERAL County in the City of SUPERIOR

3 / 03	2540	1/1/1986	Diesel	STI-P3	Flexible Plastic	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		D	E	F	G	H	I	J	K	L	Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
	B		D	E	F	G	H	I	J	K	L																							
Currently in Use		26 / No	12,000	Lined Interior/Impressed Curre	Double-Walled																													
4 / 04	2541	1/1/1972	Gasoline	Cathodically Protected Steel	Fiberglass Reinforced Plas	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		E	F	G	H	I	J	K	L		Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
	B		E	F	G	H	I	J	K	L																								
Currently in Use		40 / No	12,000	Lined Interior/Impressed Curre	None																													
5 / 05	4840	1/1/1981	Diesel	STI-P3	Flexible Plastic	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		D	E	F	G	H	I	J	K	L	Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
	B		D	E	F	G	H	I	J	K	L																							
Currently in Use		31 / No	12,000	Lined Interior/Impressed Curre	Double-Walled																													
6 / 06	2543	1/1/1989	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		E	F	G	H	I	J	K	L		Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
	B		E	F	G	H	I	J	K	L																								
Currently in Use		23 / No	12,000	None	Double-Walled																													
7 / 07	4841	1/1/1989	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		E	F	G	H	I	J	K	L		Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
	B		E	F	G	H	I	J	K	L																								
Currently in Use		23 / No	10,000	None	Double-Walled																													
8 / 08	4842	6/9/2003	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		D	E	F	G	H	I	J	K	L	Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
	B		D	E	F	G	H	I	J	K	L																							
Currently In Use		08 / No	8,000	Double-Walled	Double-Walled																													
9 / 09	4843	6/9/2003	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		D	E	F	G	H	I	J	K	L	Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
	B		D	E	F	G	H	I	J	K	L																							
Currently In Use		08 / No	3,000	Double-Walled	Double-Walled																													

Owner: Cenex Harvest States Missoula				Address: DBA Mountain West Co Op, 4570 N Reserve St, Missoula MT 59808-1411			
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone		
3108916	39639	MOUNTAIN WEST CO OP SUPERIOR	211 RIVER ST	SUPERIOR, MT 59872	(406) 543-8383		
Operating Permit Renewal Date: 30-Apr-2013				Last inspected on: 22-Oct-2009			

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / 01	1063	5/1/1986	Diesel	STI-P3	Flexible Plastic	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		E	F	G	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
	B		E	F	G	H	I	J	K	L																						
Currently in Use		25 / No	2,000	None	Double-Walled																											
4 / 02	1064	5/1/1986	Gasoline	STI-P3	Flexible Plastic	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		E	F	G	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
	B		E	F	G	H	I	J	K	L																						
Currently in Use		25 / No	2,000	None	Double-Walled																											
5 / 03	1065	5/1/1986	Diesel	STI-P3	Flexible Plastic	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L		B		E	F	G	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
	B		E	F	G	H	I	J	K	L																						
Currently in Use		25 / No	2,000	None	Double-Walled																											

Owner: Cstore Inc				Address: PO Box 190, Saint Regis MT 59866-0190			
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone		
3112870	39683	S & S FOODS INC 3112870	205 4TH AVE E	SUPERIOR, MT 59872	(406) 822-4837		
Operating Permit Renewal Date: 25-Sep-2013				Last inspected on: 27-Jul-2010			

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
-----------------------------	---------------	----------------------	---------------------	--	-------------------------------------	-------------	--	------------------------------

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MINERAL County in the City of SUPERIOR

1 / 04	1971	10/1/1992	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C D E F G H I J K L			
Currently in Use		19 / No	3,000	None	None		● D E F G H I J K L	Yes	Yes	Yes
2 / 03	1970	10/1/1992	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C D E F G H I J K L			
Currently in Use		19 / No	6,000	None	None		● D E F G H I J K L	Yes	Yes	Yes
3 / 01	1968	10/1/1992	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C D E F G H I J K L			
Currently in Use		19 / No	8,000	None	None		● D E F G H I J K L	Yes	Yes	Yes
4 / 02	1969	10/1/1992	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C D E F G H I J K L			
Currently in Use		19 / No	4,000	None	None		● D E F G H I J K L	Yes	Yes	Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed