

Facility Summary in MUSSELSHELL County in the City of MELSTONE

Owner: Jakes Garage Inc			Address: 221 US Highway 12, Melstone MT 59054		
Sys Fac ID 3301481	FITS SITE 40339	Location Name JAKES GARAGE	Location Street Address 221 US HIGHWAY 12	Location City MELSTONE, MT 59054	Location Phone (406) 358-2389
Operating Permit Renewal Date: 30-Mar-2013			Last inspected on: 06-Oct-2009		

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
8 / 08 Currently In Use	3770	12/1/1998 13 / No	Gasoline 3,750	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	B	D	E	F	G	H	I	J	K	L			Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
B	D	E	F	G	H	I	J	K	L																							
9 / 09 Currently In Use	3771	12/1/1998 13 / No	Gasoline 2,250	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	B	D	E	F	G	H	I	J	K	L			Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
B	D	E	F	G	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MUSSELSHELL County in the City of ROUNDUP

Owner: Wells Fargo Bank Roundup			Address: 12 Main St, Roundup MT 59072-2828		
Sys Fac ID 3302079	FITS SITE 40351	Location Name WELLS FARGO BANK ROUNDUP	Location Street Address 12 MAIN ST	Location City ROUNDUP, MT 59072	Location Phone (406) 323-2000
Operating Permit Renewal Date: 28-Dec-2013			Last inspected on: 01-Nov-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / S2 Currently in Use	3495	10/6/1993 18 / No	Heating Oil 2,000	STI-P3 Double-Walled	Copper Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: McCleary Distributing Inc			Address: PO Box 406, Roundup MT 59072-0406		
Sys Fac ID 3305030	FITS SITE 40390	Location Name CONOCO CONVENIENCE CENTER	Location Street Address 806 MAIN ST	Location City ROUNDUP, MT 59072	Location Phone (406) 323-1108
Operating Permit Renewal Date: 14-Dec-2013			Last inspected on: 08-Sep-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 09 Currently in Use	1594	10/1/1996 15 / No	Diesel 4,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
2 / 07 Currently in Use	1592	8/30/1989 22 / No	Gasoline 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L G H I J K L	Yes Yes Yes
3 / 08 Currently in Use	1593	9/1/1992 19 / No	Gasoline 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L G H I J K L	Yes Yes Yes
4 / 06 Currently in Use	1591	8/30/1989 22 / No	Gasoline 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
10 / 10 Currently in Use	1595	10/1/1996 15 / No	Diesel 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
11 / 11 Currently in Use	1596	10/1/1996 15 / No	Diesel 4,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
12 / 12 Currently in Use	1597	10/1/1996 15 / No	Diesel 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MUSSELSHELL County in the City of ROUNDUP

Owner: Stockton Oil Company		Address: PO Box 1756, Billings MT 59103-1756	
Sys Fac ID 3306612	FITS SITE 40407	Location Name EXPRESS CENTER CONVENIENCE STORE	Location Street Address 701 1ST AVE W
		Location City ROUNDUP, MT 59072	Location Phone (406) 323-3443
Operating Permit Renewal Date: 07-Feb-2015		Last inspected on: 12-Dec-2011	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe
							Piping Release Detection	
1 / 01 Currently in Use	3757	3/26/1985 27 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H ● J K L ● ● E F G H ● J K L	Yes Yes Yes
2 / 02 Currently in Use	3758	3/26/1985 27 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H ● J K L ● ● E F G H ● J K L	Yes Yes Yes
3 / 03 Currently in Use	3759	3/26/1985 27 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H ● J K L ● ● E F G H ● J K L	Yes Yes Yes
4 / 04 Currently In Use	1985	10/1/1998 13 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F ● H ● J K L B D E F ● H ● J K L	Yes Yes Yes
5 / 05 Currently In Use	1986	10/1/1998 13 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F ● H ● J K L B D E F ● H ● J K L	Yes Yes Yes
6 / 06 Currently In Use	1987	10/1/1998 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F ● H ● J K L B D E F ● H ● J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed