

Facility Summary in PARK County in the City of CLYDE PARK

Owner: Dale Jones			Address: PO Box 90, Clyde Park MT 59018-0090		
Sys Fac ID 3407600	FITS SITE 40604	Location Name DALES CONOCO	Location Street Address 301 1ST AVE	Location City CLYDE PARK, MT 59018	Location Phone (406) 686-4681
Operating Permit Renewal Date: 15-Jun-2013			Last inspected on: 12-Apr-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
5 / 05 Currently In Use	3991	4/1/1999 13 / No	Gasoline 6,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
6 / 06 Currently In Use	3992	4/1/1999 13 / No	Gasoline 2,500	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
7 / 07 Currently In Use	3993	4/1/1999 13 / No	Diesel 1,900	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
8 / 08 Currently In Use	3994	4/1/1999 13 / No	Diesel 1,900	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: School Dist Shields Valley			Address: PO Box 131, Wilsall MT 59086-0131		
Sys Fac ID 3412515	FITS SITE 40692	Location Name SHIELDS VALLEY HIGH SCHOOL	Location Street Address 401 1ST ST E	Location City CLYDE PARK, MT 59018	Location Phone (406) 686-4621
Operating Permit Renewal Date: 24-Sep-2013			Last inspected on: 12-Apr-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	2725	7/1/1965 46 / No	Diesel 8,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Flexible Plastic Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of COOKE CITY

Owner: Rick D Sommers			Address: PO Box 1128, Cooke City MT 59020-1128		
Sys Fac ID 3401584	FITS SITE 40470	Location Name COOKE CITY EXXON	Location Street Address US HIGHWAY 212	Location City COOKE CITY, MT 59020	Location Phone (406) 838-2244
Operating Permit Renewal Date: 17-Sep-2013			Last inspected on: 06-Sep-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
7 / 07 Currently in Use	757	10/1/1991 20 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
8 / 08 Currently in Use	758	10/1/1991 20 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
9 / 09 Currently In Use	759	10/1/1997 14 / No	Diesel 5,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
10 / 10 Currently In Use	760	10/1/1997 14 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes

Owner: National Park Service			Address: Attn Plumbing Shop, PO Box 168, Yellowstone National Park WY 82190-0168		
Sys Fac ID 3408869	FITS SITE 40627	Location Name NORTHEAST ENTRANCE GAS PUMPS	Location Street Address	Location City COOKE CITY, MT 59020	Location Phone
Operating Permit Renewal Date: 26-Sep-2013			Last inspected on: 01-Jul-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 04 Currently in Use	1741	8/1/1992 19 / No	Gasoline 2,000	Cathodically Protected Steel Double-Walled	Galvanized Steel Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
2 / 05 Currently in Use	1742	8/1/1992 19 / No	Diesel 2,000	Cathodically Protected Steel Double-Walled	Galvanized Steel Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of COOKE CITY

Owner: Rick D Sommers		Address: PO Box 1128, Cooke City MT 59020-1128			
Sys Fac ID 3410046	FITS SITE 40648	Location Name COOKE CITY SINCLAIR AND CABINS	Location Street Address 115 MAIN ST	Location City COOKE CITY, MT 59020	Location Phone (406) 838-2000
Operating Permit Renewal Date: 17-Sep-2013			Last inspected on: 06-Sep-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
6 / 06 Currently In Use	3670	10/1/1998 13 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	B		<input checked="" type="checkbox"/>	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					
B		<input checked="" type="checkbox"/>	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																						
7 / 07 Currently In Use	3671	10/1/1998 13 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	B		<input checked="" type="checkbox"/>	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					
B		<input checked="" type="checkbox"/>	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of EMIGRANT

Owner: Bert Otis			Address: Emigrant General Store, PO Box 60, Emigrant MT 59027-0060		
Sys Fac ID 3406713	FITS SITE 40580	Location Name EMIGRANT GENERAL STORE	Location Street Address 3 MURPHY LN	Location City EMIGRANT, MT 59027	Location Phone (406) 333-4434
Operating Permit Renewal Date: 08-Jul-2013			Last inspected on: 05-May-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 02 Currently in Use	4351	9/1/1989 22 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B ● E F ● H I J K L	Yes Yes Yes
5 / 06 Currently in Use	4352	1/1/1997 15 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B ● E F ● H I J K L	Yes Yes Yes
6 / 01 Currently in Use	4353	9/1/1989 22 / No	Diesel 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B ● E F ● H I J K L	Yes Yes Yes

Owner: Community Continuity Inc			Address: PO Box 135, Emigrant MT 59027-0135		
Sys Fac ID 3410930	FITS SITE 40658	Location Name COMMUNITY CONTINUITY INC	Location Street Address 18 POLARIS WAY PARCEL 70 S GLASTONBURY	Location City EMIGRANT, MT 59027	Location Phone (406) 333-4727
Operating Permit Renewal Date: 31-Mar-2015			Last inspected on: 24-Jan-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	4821	2/1/1990 22 / No	Diesel 20,000	STI-P3 None	Flexible Plastic Double-Walled	Gravity Feed	A B C D ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes

Owner: Community Restoration Inc			Address: PO Box 414, Emigrant MT 59027-0414		
Sys Fac ID 3410931	FITS SITE 40659	Location Name COMMUNITY RESTORATION INC	Location Street Address HERCULES ROAD & POLARIS WAY	Location City EMIGRANT, MT 59027	Location Phone (800) 631-8885
Operating Permit Renewal Date: 31-Mar-2015			Last inspected on: 24-Jan-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	701	2/20/1990 22 / No	Diesel 20,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	A B C D ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of EMIGRANT

Owner: Shelter Invincible Inc		Address: PO Box 111, Emigrant MT 59027-0039			
Sys Fac ID 3410933	FITS SITE 40660	Location Name SHELTER INVINCIBLE INC	Location Street Address 25 GEMINI RD	Location City EMIGRANT, MT 59027	Location Phone (406) 333-4485
Operating Permit Renewal Date: 24-Aug-2014			Last inspected on: 17-Aug-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	1882	4/17/1990 22 / No	Diesel 2,000	STI-P3 None	Copper Secondary Containment C	Safe Suction	<table border="1" style="font-size: small;"> <tr> <td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="12" style="text-align: center;">(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)</td> </tr> </table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)												Yes Yes No
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)																																

Owner: Community Conservation Association		Address: 500 Concord Dr, Bozeman MT 59715-7120			
Sys Fac ID 3410934	FITS SITE 40661	Location Name COMMUNITY CONSERVATION ASSOCIATION	Location Street Address	Location City EMIGRANT, MT 59027	Location Phone (406) 587-5667
Operating Permit Renewal Date: 11-Dec-2013			Last inspected on: 26-Oct-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	4684	4/18/1990 22 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	<table border="1" style="font-size: small;"> <tr> <td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="12" style="text-align: center;">(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)</td> </tr> </table>	A	B	C	D	<input checked="" type="radio"/>	F	G	H	I	J	K	L	(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)												Yes Yes Yes
A	B	C	D	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)																																

Owner: B Bunk Inc		Address: 3333 Regent Park Walk, Virginia Beach VA 23452-6257			
Sys Fac ID 3410959	FITS SITE 40663	Location Name B BUNK INC	Location Street Address PO Box 519	Location City EMIGRANT, MT 59027	Location Phone
Operating Permit Renewal Date: 26-Mar-2015			Last inspected on: 06-Jan-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	415	4/18/1990 22 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	<table border="1" style="font-size: small;"> <tr> <td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="12" style="text-align: center;">(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)</td> </tr> </table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)												Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)																																

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of EMIGRANT

Owner: Marks Ark Inc			Address: PO Box 11, Emigrant MT 59027-1626		
Sys Fac ID 3410960	FITS SITE 40664	Location Name MARKS ARK INC	Location Street Address PO Box 11	Location City EMIGRANT, MT 59027	Location Phone (406) 333-4707
Operating Permit Renewal Date: 06-Jan-2015			Last inspected on: 29-Dec-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	1579	4/11/1990 22 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	<table border="1" style="font-size: small;"> <tr> <td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td><td></td> </tr> </table>	A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L	B		D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L		Yes Yes Yes
A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L																						

Owner: Lifesavers Inc			Address: PO Box 211, Emigrant MT 59027-0211		
Sys Fac ID 3410965	FITS SITE 40665	Location Name LIFESAVERS INC	Location Street Address PO Box 56	Location City EMIGRANT, MT 59027	Location Phone
Operating Permit Renewal Date: 06-Jan-2015			Last inspected on: 15-Sep-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	4499	4/1/1990 22 / No	Diesel 12,000	STI-P3 None	Galvanized Steel Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr> <td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="2">B</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td> </tr> </table>	A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L	B		D	<input checked="" type="checkbox"/>	F	<input checked="" type="checkbox"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L																					
B		D	<input checked="" type="checkbox"/>	F	<input checked="" type="checkbox"/>	H	I	J	K	L																						

Owner: Craig Newhouse			Address: Earth Home Properties LLC, 5 Middlesex Ave Unit 20A, Wilmington MA 01887-2745		
Sys Fac ID 3410978	FITS SITE 40668	Location Name TRACT S7 E1	Location Street Address EVENING STAR DR	Location City EMIGRANT, MT 59027	Location Phone (978) 658-7675
Operating Permit Renewal Date: 08-Sep-2013			Last inspected on: 03-Sep-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 02 Currently in Use	4754	4/23/1990 22 / No	Diesel 10,000	STI-P3 None	No Piping None	Safe Suction	<table border="1" style="font-size: small;"> <tr> <td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td> </tr> </table>	A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L	B		D	E	F	G	H	I	J	K	L		Yes Yes Yes
A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	J	K	L																						
2 / 01 Temporarily Out of Use	4753	4/23/1990 22 / No	Diesel 12,000	STI-P3 None	Flexible Plastic None	Safe Suction	<table border="1" style="font-size: small;"> <tr> <td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td><td></td> </tr> </table>	A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L	B		D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L		Yes Yes Yes
A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of EMIGRANT

Owner: Capstone Project		Address: 14449 N 99th St, Scottsdale AZ 85260-3835			
Sys Fac ID 3410989	FITS SITE 40670	Location Name CAPSTONE SHELTER	Location Street Address Lot 105 S Glistenbury	Location City EMIGRANT, MT 59027	Location Phone
Operating Permit Renewal Date: 17-Jul-2006			Last inspected on: 25-Oct-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Temporarily Out of Use	4827	4/13/1990 22 / No	Diesel 12,000	STI-P3 Double-Walled	Bare Steel Double-Walled	Pressurized	<table border="0" style="font-size: small;"> <tr> <td><input type="radio"/>A</td><td><input type="radio"/>B</td><td><input type="radio"/>C</td><td><input type="radio"/>D</td><td><input checked="" type="radio"/>E</td><td><input type="radio"/>F</td><td><input type="radio"/>G</td><td><input type="radio"/>H</td><td><input type="radio"/>I</td><td><input type="radio"/>J</td><td><input type="radio"/>K</td><td><input type="radio"/>L</td> </tr> <tr> <td><input type="radio"/>B</td><td><input type="radio"/>D</td><td><input checked="" type="radio"/>E</td><td><input type="radio"/>F</td><td><input type="radio"/>G</td><td><input type="radio"/>H</td><td><input type="radio"/>I</td><td><input checked="" type="radio"/>J</td><td><input type="radio"/>K</td><td><input type="radio"/>L</td><td colspan="2"></td> </tr> </table>	<input type="radio"/> A	<input type="radio"/> B	<input type="radio"/> C	<input type="radio"/> D	<input checked="" type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L	<input type="radio"/> B	<input type="radio"/> D	<input checked="" type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input checked="" type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L			Yes Yes Yes
<input type="radio"/> A	<input type="radio"/> B	<input type="radio"/> C	<input type="radio"/> D	<input checked="" type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L																					
<input type="radio"/> B	<input type="radio"/> D	<input checked="" type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input checked="" type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L																							

Owner: Helmet of Salvation Shelter Assoc		Address: PO Box 419, Emigrant MT 59027-0419			
Sys Fac ID 3413180	FITS SITE 40701	Location Name HELMET OF SALVATION SHELTER UST	Location Street Address 65 ARCTURUS DR	Location City EMIGRANT, MT 59027	Location Phone (406) 333-4669
Operating Permit Renewal Date: 30-Jun-2014			Last inspected on: 01-May-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
2 / 02 Currently in Use	3123	12/1/1995 16 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	<table border="0" style="font-size: small;"> <tr> <td><input type="radio"/>A</td><td><input type="radio"/>B</td><td><input type="radio"/>C</td><td><input type="radio"/>D</td><td><input type="radio"/>E</td><td><input type="radio"/>F</td><td><input type="radio"/>G</td><td><input type="radio"/>H</td><td><input checked="" type="radio"/>I</td><td><input type="radio"/>J</td><td><input type="radio"/>K</td><td><input type="radio"/>L</td> </tr> <tr> <td><input type="radio"/>B</td><td><input type="radio"/>D</td><td><input type="radio"/>E</td><td><input type="radio"/>F</td><td><input type="radio"/>G</td><td><input type="radio"/>H</td><td><input type="radio"/>I</td><td><input checked="" type="radio"/>J</td><td><input type="radio"/>K</td><td><input type="radio"/>L</td><td colspan="2"></td> </tr> </table>	<input type="radio"/> A	<input type="radio"/> B	<input type="radio"/> C	<input type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input checked="" type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L	<input type="radio"/> B	<input type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input checked="" type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L			Yes Yes Yes
<input type="radio"/> A	<input type="radio"/> B	<input type="radio"/> C	<input type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input checked="" type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L																					
<input type="radio"/> B	<input type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input checked="" type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of GARDINER

Owner: Gardiner Town Club Inc			Address: PO Box 990, Gardiner MT 59030-0990		
Sys Fac ID 3402285	FITS SITE 40489	Location Name TOWN STATION	Location Street Address 220 PARK ST	Location City GARDINER, MT 59030	Location Phone (406) 848-7501
Operating Permit Renewal Date: 21-Dec-2013			Last inspected on: 26-Oct-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently In Use	3910	4/29/1976 35 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
2 / 02 Currently In Use	3911	4/29/1976 35 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
3 / 03 Currently In Use	3912	4/29/1976 35 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
7 / 07 Currently In Use	4247	1/1/2001 11 / No	Diesel 10,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Owner: Church Universal & Triumphant Inc			Address: 63 Summit Way, Gardiner MT 59030-9314		
Sys Fac ID 3403402	FITS SITE 40522	Location Name RANCH OFFICE	Location Street Address 558 OLD YELLOWSTONE TRAIL SOUTH	Location City GARDINER, MT 59030	Location Phone (406) 848-9043
Operating Permit Renewal Date: 03-Sep-2014			Last inspected on: 13-Jun-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
7 / 07 Currently in Use	1861	10/21/1988 23 / No	Gasoline 20,000	STI-P3 Excavation Liner	Bare Steel none	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
8 / 08 Currently in Use	1862	10/21/1988 23 / No	Diesel 20,000	STI-P3 Double-Walled	Bare Steel none	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of GARDINER

Owner: Kremer Brothers Inc			Address: DBA Kremers Cenex, PO Box 507, Gardiner MT 59030-0507		
Sys Fac ID 3406531	FITS SITE 40575	Location Name KREMERS CENEX	Location Street Address 401 SCOTT ST W PO Box 507	Location City GARDINER, MT 59030	Location Phone (406) 848-7742
Operating Permit Renewal Date: 03-Mar-2015			Last inspected on: 25-Oct-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	3189	4/16/1984 28 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	3190	4/16/1984 28 / No	Gasoline 4,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
3 / 03 Currently in Use	3191	4/16/1984 28 / No	Diesel 4,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
4 / 04 Currently in Use	3192	4/16/1984 28 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Owner: Xanterra Parks & Resorts Inc			Address: ATTN Beth Pratt, PO Box 753, Yellowstone National Park WY 82190-0753		
Sys Fac ID 3408868	FITS SITE 40626	Location Name GARDINER SERVICE CENTER	Location Street Address US HIGHWAY 89 S	Location City GARDINER, MT 59030	Location Phone (307) 344-5331
Operating Permit Renewal Date: 28-Jul-2013			Last inspected on: 11-Mar-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
6 / 06 Currently in Use	3492	4/1/1996 16 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C D E F ● H I J K L B D E F ● H I J ● L	Yes Yes Yes
7 / 07 Currently in Use	3493	4/1/1996 16 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C ● E F ● H I J K L B D E F ● H I J ● L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of GARDINER

Owner: Xanterra Parks & Resorts Inc			Address: ATTN Beth Pratt, PO Box 753, Yellowstone National Park WY 82190-0753		
Sys Fac ID 3408873	FITS SITE 40628	Location Name GARDINER LAUNDRY	Location Street Address E PARK ST	Location City GARDINER, MT 59030	Location Phone (307) 344-5327
Operating Permit Renewal Date: 28-Jul-2013			Last inspected on: 11-Mar-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
2 / 02 Currently In Use	3494	11/1/1997 14 / No	Diesel 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table style="font-size: small; border: none;"> <tr> <td><input type="radio"/>A</td><td><input type="radio"/>B</td><td><input type="radio"/>C</td><td><input type="radio"/>D</td><td><input type="radio"/>E</td><td><input checked="" type="radio"/>F</td><td><input type="radio"/>G</td><td><input type="radio"/>H</td><td><input type="radio"/>I</td><td><input type="radio"/>J</td><td><input type="radio"/>K</td><td><input type="radio"/>L</td> </tr> <tr> <td><input type="radio"/>B</td><td><input checked="" type="radio"/></td><td><input type="radio"/>E</td><td><input type="radio"/>F</td><td><input checked="" type="radio"/>H</td><td><input type="radio"/>I</td><td><input type="radio"/>J</td><td><input type="radio"/>K</td><td><input type="radio"/>L</td><td colspan="3"></td> </tr> </table>	<input type="radio"/> A	<input type="radio"/> B	<input type="radio"/> C	<input type="radio"/> D	<input type="radio"/> E	<input checked="" type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L	<input type="radio"/> B	<input checked="" type="radio"/>	<input type="radio"/> E	<input type="radio"/> F	<input checked="" type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L				Yes Yes Yes
<input type="radio"/> A	<input type="radio"/> B	<input type="radio"/> C	<input type="radio"/> D	<input type="radio"/> E	<input checked="" type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L																					
<input type="radio"/> B	<input checked="" type="radio"/>	<input type="radio"/> E	<input type="radio"/> F	<input checked="" type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L																								

Owner: School Dist 7 & 4 Gardiner Public			Address: 510 Stone St, Gardiner MT 59030-9378		
Sys Fac ID 3409287	FITS SITE 40631	Location Name GARDINER SCHOOL DIST 4	Location Street Address 510 STONE ST	Location City GARDINER, MT 59030	Location Phone (406) 848-7563
Operating Permit Renewal Date: 02-Jan-2015			Last inspected on: 10-Nov-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
2 / S2 Currently in Use	4451	4/24/1987 25 / No	Heating Oil 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table style="font-size: small; border: none;"> <tr> <td><input type="radio"/>A</td><td><input type="radio"/>B</td><td><input type="radio"/>C</td><td><input checked="" type="radio"/>D</td><td><input type="radio"/>E</td><td><input type="radio"/>F</td><td><input type="radio"/>G</td><td><input type="radio"/>H</td><td><input type="radio"/>I</td><td><input type="radio"/>J</td><td><input type="radio"/>K</td><td><input type="radio"/>L</td> </tr> <tr> <td><input type="radio"/>B</td><td><input type="radio"/>D</td><td><input type="radio"/>E</td><td><input type="radio"/>F</td><td><input checked="" type="radio"/>H</td><td><input type="radio"/>I</td><td><input type="radio"/>J</td><td><input type="radio"/>K</td><td><input type="radio"/>L</td><td colspan="3"></td> </tr> </table>	<input type="radio"/> A	<input type="radio"/> B	<input type="radio"/> C	<input checked="" type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L	<input type="radio"/> B	<input type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input checked="" type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L				Yes Yes Yes
<input type="radio"/> A	<input type="radio"/> B	<input type="radio"/> C	<input checked="" type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L																					
<input type="radio"/> B	<input type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input checked="" type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L																								

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of LIVINGSTON

Owner: Gasparro Enterprises LLC			Address: PO Box 758, Pleasant Valley NY 12569-0758		
Sys Fac ID 3408071	FITS SITE 40615	Location Name Old Holiday Gas Station	Location Street Address 1019 W PARK ST	Location City LIVINGSTON, MT 59047	Location Phone
Operating Permit Renewal Date:			Last inspected on: 28-Aug-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Temporarily Out of Use	3031	10/1/1975 36 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A ● C D E F G H ● J K L ● ● E F G H ● J K L	Yes Yes Yes
2 / 02 Temporarily Out of Use	3032	10/1/1975 36 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A ● C D E F G H ● J K L ● ● E F G H ● J K L	Yes Yes Yes

Owner: Park Casino			Address: 600 S Main St, BUTTE MT 59701		
Sys Fac ID 3408713	FITS SITE 40623	Location Name TOWN PUMP INC LIVINGSTON 2	Location Street Address 29 N H ST	Location City LIVINGSTON, MT 59047	Location Phone
Operating Permit Renewal Date: 02-Apr-2013			Last inspected on: 29-Mar-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 05 Currently in Use	2577	9/1/1996 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F ● H ● ● K L B ● E F ● H ● ● K L	Yes Yes Yes
2 / 06 Currently in Use	2578	9/1/1996 15 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F ● H ● ● K L B ● E F ● H ● ● K L	Yes Yes Yes
5 / 03 Currently in Use	2575	9/1/1996 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F ● H ● ● K L B ● E F ● H ● ● K L	Yes Yes Yes
6 / 04 Currently in Use	2576	9/1/1996 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F ● H I ● K L B ● E F ● H ● ● K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of LIVINGSTON

Owner: Qwest Corporation dba CenturyLink			Address: 250 East 200 South #1601, Salt Lake City UT 84111		
Sys Fac ID 3408777	FITS SITE 40624	Location Name QWEST LIVINGSTON CENTRAL OFFICE	Location Street Address 302 W CALLENDER ST	Location City LIVINGSTON, MT 59047	Location Phone (801) 237-3006
Operating Permit Renewal Date: 20-Mar-2015			Last inspected on: 08-Dec-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / S1 Currently In Use	4811	4/15/1957 55 / Yes	Diesel 275	Concrete Double-Walled	Flexible Plastic None	U.S. Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td><input checked="" type="checkbox"/></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	<input checked="" type="checkbox"/>		D	E	F	G	H	I	J	K	L		Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					
<input checked="" type="checkbox"/>		D	E	F	G	H	I	J	K	L																						

Owner: Talgo LRC LLC			Address: Antonio Perez, PO Box 992, Livingston MT 59047-0992		
Sys Fac ID 3409286	FITS SITE 40630	Location Name FITNESS & RCENTER	Location Street Address 704 E GALLATIN ST PO BOX 992	Location City LIVINGSTON, MT 59047	Location Phone (406) 222-4200
Operating Permit Renewal Date:			Last inspected on: 28-Aug-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
2 / 02 Temporarily Out of Use	4169	2/1/2000 12 / No	Waste Oil 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="checkbox"/>	H	I	<input checked="" type="checkbox"/>	K	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="checkbox"/>	H	I	<input checked="" type="checkbox"/>	K	L																					

Owner: Dead Rock Investments LLC			Address: PO Box 1201, Bozeman MT 59771-1201		
Sys Fac ID 3409906	FITS SITE 40641	Location Name CASEYS CORNER #4	Location Street Address 5292 US HIGHWAY 89 S	Location City LIVINGSTON, MT 59047	Location Phone (406) 587-0702
Operating Permit Renewal Date: 22-Jul-2013			Last inspected on: 12-Jul-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
5 / 05 Currently In Use	2033	5/1/1998 13 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L		B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					
5 / 05 Currently In Use	2033	5/1/1998 13 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L		B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					
6 / 06 Currently In Use	2034	5/1/1998 13 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L		B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of LIVINGSTON

6 / 06	2034	5/1/1998	Gasoline	STI-P3	Flexible Plastic	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes
Currently In Use		13 / No	12,000	None	Double-Walled					
7 / 07	2035	5/1/1998	Diesel	STI-P3	Flexible Plastic	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes
Currently In Use		13 / No	8,000	None	Double-Walled					
7 / 07	2035	5/1/1998	Diesel	STI-P3	Flexible Plastic	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes
Currently In Use		13 / No	8,000	None	Double-Walled					

Owner: Livingston Health Care			Address: 504 S 13th St, Livingston MT 59047-3727		
Sys Fac ID 3409965	FITS SITE 40643	Location Name LIVINGSTON HEALTH CARE	Location Street Address 504 S 13TH ST	Location City LIVINGSTON, MT 59047	Location Phone (406) 823-6445
Operating Permit Renewal Date: 15-Nov-2013			Last inspected on: 01-Jul-2010		

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / S1	1550	1/4/1990	Heating Oil	STI-P3	Galvanized Steel	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input checked="" type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input checked="" type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
Currently in Use		22 / No	2,500	None	none			

Owner: Park County Shop			Address: ATTN Maint Supv Bruce, 414 E Callender St, Livingston MT 59047-2700		
Sys Fac ID 3410573	FITS SITE 40650	Location Name CITY COUNTY COMPLEX	Location Street Address 414 E CALLENDER ST	Location City LIVINGSTON, MT 59047	Location Phone (406) 222-4106
Operating Permit Renewal Date: 01-Oct-2013			Last inspected on: 16-Apr-2010		

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
2 / 02	1783	11/1/1995	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	U.S. Suction	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> B <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes Yes Yes
Currently in Use		16 / No	3,000	Double-Walled	Double-Walled			

Owner: Yellowstone Truck Stop Livingston			Address: 1226 US Highway 10 W, Livingston MT 59047-9004		
Sys Fac ID 3411200	FITS SITE 40682	Location Name YELLOWSTONE TRUCK STOP LIVINGSTON	Location Street Address 1226 US HIGHWAY 10 W	Location City LIVINGSTON, MT 59047	Location Phone (406) 222-6180
Operating Permit Renewal Date: 25-Mar-2014			Last inspected on: 18-Mar-2011		

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of LIVINGSTON

1 / 01	2313	1/1/1989	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
●	●	●	●	●	●	●	●	●	●	●	●																							
Currently in Use		23 / No	8,000	None	None																													
2 / 02	2314	1/1/1989	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
●	●	●	●	●	●	●	●	●	●	●	●																							
Currently in Use		23 / No	6,000	None	None																													
3 / 03	2315	1/1/1989	Gasoline	STI-P3	Fiberglass Reinforced Plas	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
●	●	●	●	●	●	●	●	●	●	●	●																							
Currently in Use		23 / No	6,000	None	None																													
4 / 04	2316	1/1/1989	Gasoline	STI-P3	Fiberglass Reinforced Plas	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes	Yes	Yes
A	B	C	D	E	F	G	H	I	J	K	L																							
●	●	●	●	●	●	●	●	●	●	●	●																							
Currently in Use		23 / No	6,000	None	None																													

Owner: CHS Inc		Address: 16124 E Marietta Lane, Spokane Valley WA 99216					
Sys Fac ID 3411741	FITS SITE 40690	Location Name ZIP TRIP 47	Location Street Address 101 CENTENNIAL DR	Location City LIVINGSTON, MT 59047	Location Phone (406) 222-7371		
Operating Permit Renewal Date: 09-Mar-2015			Last inspected on: 25-Oct-2011				

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	562	9/1/1990 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	●	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	●	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					
2 / 02 Currently in Use	563	9/1/1990 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	●	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	●	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					
3 / 03 Currently in Use	564	9/1/1990 21 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td><td>●</td></tr> </table>	A	B	C	●	E	F	G	H	I	J	K	L	●	●	●	●	●	●	●	●	●	●	●	●	Yes Yes Yes
A	B	C	●	E	F	G	H	I	J	K	L																					
●	●	●	●	●	●	●	●	●	●	●	●																					

Owner: Livingston Holdings LLC		Address: PO Box 6000, Butte MT 59702-6000					
Sys Fac ID 3413409	FITS SITE 40707	Location Name TOWN PUMP INC LIVINGSTON 3	Location Street Address 2200 PARK ST S	Location City LIVINGSTON, MT 59047	Location Phone (406) 222-5527		
Operating Permit Renewal Date: 02-Apr-2013			Last inspected on: 29-Mar-2010				

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	2579	5/20/1994 17 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>●</td><td>●</td><td>●</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>●</td><td>●</td><td>●</td><td>L</td></tr> </table>	A	B	C	D	E	F	●	H	●	●	●	L		B		D	E	F	●	H	●	●	●	L	Yes Yes Yes
A	B	C	D	E	F	●	H	●	●	●	L																					
	B		D	E	F	●	H	●	●	●	L																					
2 / 02 Currently in Use	2580	5/20/1994 17 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>●</td><td>●</td><td>●</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>●</td><td>●</td><td>●</td><td>L</td></tr> </table>	A	B	C	D	E	F	●	H	●	●	●	L		B		D	E	F	●	H	●	●	●	L	Yes Yes Yes
A	B	C	D	E	F	●	H	●	●	●	L																					
	B		D	E	F	●	H	●	●	●	L																					
3 / 03 Currently in Use	2581	5/1/1994 17 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	<table border="1" style="font-size: 8px;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>●</td><td>●</td><td>●</td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>●</td><td>●</td><td>●</td><td>L</td></tr> </table>	A	B	C	D	E	F	●	H	●	●	●	L		B		D	E	F	●	H	●	●	●	L	Yes Yes Yes
A	B	C	D	E	F	●	H	●	●	●	L																					
	B		D	E	F	●	H	●	●	●	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of LIVINGSTON

4 / 04	2582	5/1/1994	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C D E F G H I J K L	Yes	Yes	Yes
Currently in Use	17 / No	12,000	Double-Walled	Double-Walled		(B) D E F G H I J K L				
5 / 05	2583	5/1/1994	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C D E F G H I J K L	Yes	Yes	Yes
Currently in Use	17 / No	12,000	Double-Walled	Double-Walled		(B) D E F G H I J K L				
6 / 06	4377	10/1/2001	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes	Yes	Yes
Currently In Use	10 / No	10,000	Double-Walled	Double-Walled		(B) D E F G H I J K L				
7 / 07	4378	10/1/2001	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes	Yes	Yes
Currently In Use	10 / No	5,000	Double-Walled	Double-Walled		(B) D E F G H I J K L				
8 / 08	4379	10/1/2001	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes	Yes	Yes
Currently In Use	10 / No	12,000	Double-Walled	Double-Walled		(B) D E F G H I J K L				

Owner: TJs Gas N Convenience		Address: 204 E Park St, Livingston MT 59047-2713			
Sys Fac ID 3413736	FITS SITE 40712	Location Name TJS GAS N CONVENIENCE	Location Street Address 204 W PARK ST	Location City LIVINGSTON, MT 59047	Location Phone (406) 222-9720
Operating Permit Renewal Date: 03-Sep-2014		Last inspected on: 14-Jun-2011			

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01	3371	5/1/1996	Gasoline	STI-P3	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use	15 / No	10,000	None	None	Double-Walled		(B) D E F G H I J K L	
2 / 02	3372	5/1/1996	Gasoline	STI-P3	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use	15 / No	10,000	None	None	Double-Walled		(B) D E F G H I J K L	

Owner: D M Curtin Family Limited Partnership		Address: 2860 NE Kendallwood Pkwy, Kansas City MO 64119-2026			
Sys Fac ID 5614035	FITS SITE 45236	Location Name DENNIS CURTIN	Location Street Address 325 MAJESTIC MEADOWS	Location City LIVINGSTON, MT 59047	Location Phone (406) 333-4056
Operating Permit Renewal Date: 31-Dec-2013		Last inspected on: 29-Sep-2010			

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01	4435	10/15/2001	Diesel	Polyethylene Tank Jacket	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently In Use	10 / No	8,000	Double-Walled	Double-Walled	Double-Walled		(B) D E F G H I J K L	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PARK County in the City of WILLSALL

Owner: Park Farmers Coop			Address: PO Box 129, Willsall MT 59086-0129		
Sys Fac ID 3406686	FITS SITE 40579	Location Name PARK FARMERS COOP	Location Street Address US HIGHWAY 89 N	Location City WILLSALL, MT 59086	Location Phone (406) 578-2543
Operating Permit Renewal Date: 24-May-2013			Last inspected on: 26-Apr-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe																								
							Piping Release Detection																									
13 / 13 Currently in Use	1784	7/1/1993 18 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="12" style="text-align: center;">(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)</td></tr> </table>	A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L	(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)												Yes Yes Yes
A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L																					
(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)																																
14 / 14 Currently in Use	1785	7/1/1993 18 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="12" style="text-align: center;">(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)</td></tr> </table>	A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L	(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)												Yes Yes Yes
A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L																					
(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)																																
15 / 15 Currently in Use	1786	7/1/1993 18 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="12" style="text-align: center;">(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)</td></tr> </table>	A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L	(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)												Yes Yes Yes
A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L																					
(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)																																
16 / 16 Currently in Use	1787	7/1/1993 18 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="checkbox"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="12" style="text-align: center;">(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)</td></tr> </table>	A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L	(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)												Yes Yes Yes
A	B	C	D	<input checked="" type="checkbox"/>	F	G	H	I	J	K	L																					
(B) <input checked="" type="checkbox"/> (E) (F) (G) (H) (I) (J) (K) (L)																																

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed