

Facility Summary in PHILLIPS County in the City of DODSON

| | | | | | |
|---|---------------------------|---|--|--|---|
| Owner: E Bruce Kirkaldie | | Address: Lodgepole Store, General Delivery, Dodson MT 59524-9999 | | | |
| Sys Fac ID 0306293 | FITS SITE 32446 | Location Name LODGE POLE STORE UST | Location Street Address GENERAL DELIVERY | Location City DODSON, MT 59524 | Location Phone (406) 673-3255 |
| Operating Permit Renewal Date: 01-Apr-2002 | | | Last inspected on: 18-Aug-1994 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|----------------------------------|---------------|----------------------|---------------------|--|-------------------------------------|-------------|---|------------------------------|
| 1 / 01 Temporarily Out of Use | | 4/24/1986 26 / No | Gasoline 1,000 | Asphalt Coated or Bare Steel None | Galvanized Steel None | Not Listed | <input checked="" type="radio"/> A <input type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input checked="" type="radio"/> L <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input checked="" type="radio"/> L | No No No |
| 2 / 02 Temporarily Out of Use | | 4/25/1971 41 / No | Gasoline 2,000 | Asphalt Coated or Bare Steel None | Galvanized Steel None | Not Listed | <input checked="" type="radio"/> A <input type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input checked="" type="radio"/> L <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input checked="" type="radio"/> L | No No No |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in PHILLIPS County in the City of MALTA

| | | | | | |
|---|---------------------------|------------------------------------|--|---|---|
| Owner: Adams Convenience Store Inc | | | Address: DBA Packys, 902 S Central Ave, Malta MT 59538-9304 | | |
| Sys Fac ID 3602359 | FITS SITE 40757 | Location Name PACKYS INC | Location Street Address 902 S CENTRAL AVE PO BOX 490 | Location City MALTA, MT 59538 | Location Phone (406) 654-2268 |
| Operating Permit Renewal Date: 08-Jun-2013 | | | Last inspected on: 17-Mar-2010 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|----------------------|---------------------|--|-------------------------------------|-------------|---|------------------------------|
| 2 / S7 Currently in Use | 892 | 6/1/1994 17 / Yes | Gasoline 17,000 | Asphalt Coated or Bare Steel None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K <input checked="" type="radio"/> | Yes Yes Yes |
| 3 / S8 Currently in Use | 893 | 6/1/1994 17 / Yes | Gasoline 17,000 | Asphalt Coated or Bare Steel None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K <input checked="" type="radio"/> | Yes Yes Yes |

| | | | | | |
|---|---------------------------|---|--|---|---|
| Owner: Little Otts Inc | | | Address: PO Box 9, Malta MT 59538-0009 | | |
| Sys Fac ID 3602371 | FITS SITE 40758 | Location Name LITTLE OTTS INC | Location Street Address 3 N 1ST ST E | Location City MALTA, MT 59538 | Location Phone (406) 654-1199 |
| Operating Permit Renewal Date: 31-Oct-2013 | | | Last inspected on: 22-Sep-2010 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|-----------------------|---------------------|--|-------------------------------------|-------------|---|------------------------------|
| 2 / 02 Currently in Use | 3287 | 10/29/1986 25 / No | Diesel 6,000 | STI-P3 None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |
| 3 / 03 Currently in Use | 3288 | 10/29/1986 25 / No | Diesel 6,000 | STI-P3 None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |
| 4 / 04 Currently in Use | 3289 | 10/1/1998 13 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |
| 5 / 05 Currently in Use | 3290 | 10/1/1998 13 / No | Gasoline 5,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F <input checked="" type="radio"/> H I J K L | Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in PHILLIPS County in the City of MALTA

| | | | | | |
|---|---------------------------|---|---|---|---|
| Owner: Robert Ereaux | | | Address: PO Box 1359, Malta MT 59538-1359 | | |
| Sys Fac ID 3606668 | FITS SITE 40819 | Location Name WESTSIDE SELF SERVICE INC | Location Street Address US HIGHWAY 2 & US HIGHWAY 191 | Location City MALTA, MT 59538 | Location Phone (406) 654-7070 |
| Operating Permit Renewal Date: 09-Jul-2013 | | | Last inspected on: 07-May-2010 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|----------------------|---------------------|--|---|-------------|--|------------------------------|
| 6 / 06 Currently in Use | 5069 | 4/25/2006 06 / No | Gasoline 15,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J K L B ● E F G H I J K L | Yes Yes Yes |
| 7 / 07 Currently in Use | 5070 | 4/25/2006 06 / No | Diesel 15,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J K L B ● E F G H I J K L | Yes Yes Yes |
| 8 / 08 Currently in Use | 5071 | 4/25/2006 06 / No | Diesel 15,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J K L B ● E F G H I J K L | Yes Yes Yes |
| 9 / 09 Currently in Use | 5075 | 4/25/2006 06 / No | Diesel 5,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J K L B ● E F G H I J K L | Yes Yes Yes |
| 10 / 10 Currently in Use | 5076 | 4/25/2006 06 / No | Diesel 5,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J K L B ● E F G H I J K L | Yes Yes Yes |
| 11 / 11 Currently in Use | 5077 | 4/25/2006 06 / No | Gasoline 5,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J K L B ● E F G H I J K L | Yes Yes Yes |

| | | | | | |
|---|---------------------------|---|--|---|---|
| Owner: Equity Coop Association Malta | | | Address: PO Box 340, Malta MT 59538-0340 | | |
| Sys Fac ID 3610706 | FITS SITE 40850 | Location Name EQUITY COOP ASSOCIATION MALTA | Location Street Address 428 S 1ST ST E | Location City MALTA, MT 59538 | Location Phone (406) 654-2240 |
| Operating Permit Renewal Date: 30-Oct-2013 | | | Last inspected on: 21-Sep-2010 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|-----------------------|---------------------|--|---|-------------|--|------------------------------|
| 3 / S3 Currently in Use | 860 | 12/9/1994 17 / Yes | Gasoline 25,600 | Unknown None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J ● K L B D E F ● H I J K L | Yes Yes Yes |
| 4 / S4 Currently in Use | 861 | 12/9/1994 17 / Yes | Diesel 17,000 | Unknown None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J ● K L B D E F ● H I J K L | Yes Yes Yes |
| 5 / S5 Currently In Use | 862 | 12/9/1994 17 / Yes | Diesel 12,000 | Unknown None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J ● K L B D E F ● H I J K L | Yes Yes Yes |
| 6 / S6 Currently In Use | 863 | 12/9/1994 17 / Yes | Gasoline 9,900 | Unknown None | Fiberglass Reinforced Plas Double-Walled | Pressurized | A B C D E F G H I J ● K L B D E F ● H I J K L | Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in PHILLIPS County in the City of MALTA

| | | | | | |
|---|---------------------------|---|--|---|-----------------------|
| Owner: EZZIES WHOLESALE INC | | | Address: PO Box 1770, Malta MT 59538-1770 | | |
| Sys Fac ID 6015156 | FITS SITE 45456 | Location Name EZZIES BULK STORAGE | Location Street Address 47259 Us Hwy 2 | Location City Malta, MT 59538 | Location Phone |
| Operating Permit Renewal Date: 20-Apr-2014 | | | Last inspected on: 11-Jan-2011 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Installed Spill/Over/CPMe |
|-----------------------------|---------------|----------------------|---------------------|--|-------------------------------------|-------------|--|------------------------------|
| | | | | | | | Piping Release Detection | |
| 1 / 01 Currently in Use | 5246 | 9/27/2010 01 / No | Gasoline 30,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 2 / 02 Currently in Use | 5247 | 9/27/2010 01 / No | Diesel 10,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 3 / 03 Currently in Use | 5248 | 9/27/2010 01 / No | Diesel 10,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 4 / 04 Currently in Use | 5249 | 9/27/2010 01 / No | Diesel 10,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 5 / 05 Currently in Use | 5250 | 9/27/2010 01 / No | Diesel 10,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 6 / 06 Currently in Use | 5251 | 9/27/2010 01 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 8 / 08 Currently in Use | 5253 | 9/27/2010 01 / No | Diesel 20,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |
| 9 / 09 Currently in Use | 5254 | 9/27/2010 01 / No | Diesel 30,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | A B C D E F G H I J K L B D E F G H I J K L | Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in PHILLIPS County in the City of WHITEWATER

| | | | | | |
|---|---------------------------|---|--|--|---|
| Owner: Farmers Union Oil Co Whitewater | | | Address: Main St, PO Box 7, Whitewater MT 59544 | | |
| Sys Fac ID 3604082 | FITS SITE 40772 | Location Name FARMERS UNION OIL CO WHITEWATER | Location Street Address PO Box 7 | Location City WHITEWATER, MT 59544 | Location Phone (406) 674-5515 |
| Operating Permit Renewal Date: 11-Feb-2015 | | | Last inspected on: 05-Dec-2011 | | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Installed Spill/Over/CPMe | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------------------------|---------------|------------------------|---------------------|--|-------------------------------------|-------------|---|------------------------------|---|---|---|---|---|---|---|---|---|---|---|--|--|--|--|--|--|--|--|--|--|--|--|-------------|
| | | | | | | | Piping Release Detection | | | | | | | | | | | | | | | | | | | | | | | | | |
| 5 / S5 Currently in Use | 3599 | 10/13/1998 13 / Yes | Diesel 10,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 6 / S6 Currently in Use | 3600 | 10/13/1998 13 / Yes | Gasoline 15,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 7 / S7 Currently In Use | 3601 | 10/13/1998 13 / Yes | Diesel 9,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 8 / S8 Currently In Use | 3602 | 10/13/1998 13 / Yes | Diesel 9,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Facility Summary in PHILLIPS County in the City of ZORTMAN

| | | | |
|---|---------------------------|---|---|
| Owner: Zortman Garage & Motel | | Address: PO Box 302, Zortman MT 59546-0302 | |
| Sys Fac ID 3611549 | FITS SITE 40859 | Location Name ZORTMAN GARAGE & MOTEL | Location Street Address 302 MAIN ST |
| | | Location City ZORTMAN, MT 59546 | Location Phone (406) 673-3160 |
| Operating Permit Renewal Date: 27-Nov-2013 | | Last inspected on: 18-Aug-2010 | |

| TankID/Alt TankID Status | Tag Number | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | Installed Spill/Over/CPMe | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------------------------|---------------|----------------------|---------------------|--|-------------------------------------|--------------|---|------------------------------|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|--|--|-------------|
| 3 / 03 Currently In Use | 4020 | 6/17/1999 12 / No | Gasoline 1,000 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plas None | Safe Suction | <table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | B | D | E | F | G | H | I | J | K | L | | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |
| 4 / 04 Currently In Use | 4021 | 6/17/1999 12 / No | Diesel 1,000 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plas None | Safe Suction | <table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | B | D | E | F | G | H | I | J | K | L | | | Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |