

Facility Summary in PONDERA County in the City of BRADY

Owner: School Dist 28C Dutton Brady			Address: 101 2nd St NE, Dutton MT 59433-9670		
Sys Fac ID 3702704	FITS SITE 40904	Location Name BRADY CAMPUS DUTTON BRADY SCHOOLS	Location Street Address 309 2ND AVE NE	Location City BRADY, MT 59416	Location Phone (406) 476-3424
Operating Permit Renewal Date: 19-Jun-2011			Last inspected on: 26-Apr-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / S3 Temporarily Out of Use	487	7/1/1997 14 / No	Heating Oil 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																						

Owner: Mountain View Coop Black Eagle			Address: Attn Pat or Frank, 2200 Old Havre Hwy, Black Eagle MT 59414-1043		
Sys Fac ID 3704241	FITS SITE 40935	Location Name MOUNTAIN VIEW COOP BRADY	Location Street Address 102 RAILROAD ST N	Location City BRADY, MT 59416	Location Phone (406) 753-2258
Operating Permit Renewal Date: 04-Aug-2013			Last inspected on: 25-Mar-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
6 / S11 Currently In Use	2142	11/1/1997 14 / Yes	Gasoline 17,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L																					
B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																						
7 / S12 Currently In Use	2143	11/1/1997 14 / Yes	Gasoline 17,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L																					
B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																						
8 / S13 Currently In Use	2144	11/1/1997 14 / Yes	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L																					
B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																						
9 / S14 Currently In Use	2145	11/1/1997 14 / Yes	Diesel 5,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L		Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L																					
B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PONDERA County in the City of CONRAD

Owner: Mountain View Coop Black Eagle			Address: Attn Pat or Frank, 2200 Old Havre Hwy, Black Eagle MT 59414-1043		
Sys Fac ID 3701649	FITS SITE 40889	Location Name MOUNTAIN VIEW COOP CONRAD	Location Street Address 19 S MAIN ST	Location City CONRAD, MT 59425	Location Phone (406) 278-5524
Operating Permit Renewal Date: 04-Aug-2013			Last inspected on: 26-May-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 10 Currently in Use	920	1/8/1997 15 / No	Diesel 7,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
2 / 11 Currently in Use	921	1/8/1997 15 / No	Diesel 7,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
3 / 12 Currently in Use	922	1/8/1997 15 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
4 / 09 Currently in Use	919	1/8/1997 15 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
5 / 08 Currently in Use	918	1/8/1997 15 / No	Diesel 9,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
11 / 06 Currently in Use	916	1/8/1997 15 / No	Gasoline 9,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
12 / 07 Currently in Use	917	1/8/1997 15 / No	Gasoline 6,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: Ben Taylor Inc			Address: PO Box 810, Shelby MT 59474-0810		
Sys Fac ID 3706114	FITS SITE 40961	Location Name TOMS SUPER SERVICE	Location Street Address 301 S MAIN ST	Location City CONRAD, MT 59425	Location Phone (406) 278-5213
Operating Permit Renewal Date: 20-Jul-2013			Last inspected on: 18-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 05 Currently in Use	425	5/12/1993 18 / No	Gasoline 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L G E F G H I J K L	Yes Yes Yes
4 / 03 Currently in Use	423	5/12/1993 18 / No	Gasoline 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L G E F G H I J K L	Yes Yes Yes
5 / 04 Currently in Use	424	5/12/1993 18 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L G E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PONDERA County in the City of CONRAD

Owner: Dans Tire Service			Address: 601 S Main St, Conrad MT 59425-2530		
Sys Fac ID 3706903	FITS SITE 40974	Location Name DANS TIRE SERVICE	Location Street Address 601 S MAIN ST	Location City CONRAD, MT 59425	Location Phone (406) 278-5856
Operating Permit Renewal Date: 19-Feb-2015			Last inspected on: 09-Nov-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	1418	5/7/1986 25 / No	Gasoline 8,000	STI-P3 None	Flexible Plastic None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	1419	5/7/1986 25 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Owner: Town Pump O Mat of Conrad			Address: 600 S Main St, , Butte MT 59701-2534		
Sys Fac ID 3708692	FITS SITE 40998	Location Name TOWN PUMP INC CONRAD	Location Street Address 217 N MAIN ST	Location City CONRAD, MT 59425	Location Phone (406) 278-7971
Operating Permit Renewal Date: 01-Apr-2013			Last inspected on: 11-Dec-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	2584	8/30/1983 28 / No	Gasoline 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H ● ● K L B ● E F G H ● ● K L	Yes Yes Yes
2 / 02 Currently in Use	2585	8/30/1983 28 / No	Gasoline 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H ● ● K L B ● E F G H ● ● K L	Yes Yes Yes
3 / 03 Currently in Use	2586	8/30/1983 28 / No	Diesel 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H ● ● K L B ● E F ● H ● ● K L	Yes Yes Yes
4 / 04 Currently in Use	2587	8/30/1986 25 / No	Gasoline 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H ● ● K L B ● E F G H ● ● K L	Yes Yes Yes
5 / 05 Currently in Use	2588	7/1/1988 23 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H ● ● K L B ● E F ● H ● ● K L	Yes Yes Yes
8 / 08 Currently In Use	4151	9/1/1999 12 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F ● H ● ● K L B D E F ● H ● ● K L	Yes Yes Yes
9 / 09 Currently In Use	4152	9/1/1999 12 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F ● H ● ● K L B D E F ● H ● ● K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in PONDERA County in the City of HEART BUTTE

Owner: School Dist 1 Heart Butte		Address: PO Box 259, Heart Butte MT 59448-0259	
Sys Fac ID 3709353	FITS SITE 41037	Location Name HEART BUTTE SCHOOL DIST 1	Location Street Address SCHOOL BUS BARN RD
		Location City HEART BUTTE, MT 59448	Location Phone
Operating Permit Renewal Date: 28-Dec-2013		Last inspected on: 16-Nov-2010	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / 03 Currently in Use	1901	5/6/1986 25 / No	Gasoline 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	B	D	E	F	G	H	I	●	K	L			Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
B	D	E	F	G	H	I	●	K	L																							
4 / 04 Currently in Use	1902	5/6/1986 25 / No	Diesel 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	B	D	E	F	G	H	I	●	K	L			Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
B	D	E	F	G	H	I	●	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

