

Facility Summary in POWELL County in the City of DEER LODGE

Owner: Town Pump Inc Butte			Address: PO Box 6000, Butte MT 59702-6000		
Sys Fac ID 3908694	FITS SITE 41261	Location Name TOWN PUMP INC DEER LODGE	Location Street Address 203 N MAIN ST	Location City DEER LODGE, MT 59722	Location Phone
Operating Permit Renewal Date: 14-Oct-2012			Last inspected on: 07-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	2589	4/14/1977 35 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H ● J K L B ● E F G H ● J K L	Yes Yes Yes
2 / 02 Currently in Use	2590	4/14/1977 35 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H ● J K L B ● E F G H ● J K L	Yes Yes Yes
5 / 05 Currently in Use	2591	4/14/1977 35 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H ● J K L B ● E F ● H ● J K L	Yes Yes Yes
7 / 07 Currently In Use	2592	7/30/1998 13 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F ● H ● J K L B ● E F G H ● J K L	Yes Yes Yes
8 / 08 Currently In Use	4282	9/15/2000 11 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C ● E F ● H ● J K L B ● E F ● H ● J K L	Yes Yes Yes
9 / 09 Currently In Use	4283	9/15/2000 11 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C ● E F ● H ● J K L B ● E F ● H ● J K L	Yes Yes Yes

Owner: JD & JD LLC			Address: 200 Regal St, Billings MT 59101-3133		
Sys Fac ID 3910909	FITS SITE 41273	Location Name HAPPY ENDINGS 418	Location Street Address 141 N INTERCHANGE	Location City DEER LODGE, MT 59722	Location Phone (406) 560-6023
Operating Permit Renewal Date: 26-Jul-2014			Last inspected on: 01-Mar-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / 03 Currently in Use	767	4/13/1989 23 / No	Gasoline 4,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
4 / 04 Currently in Use	768	11/19/1998 13 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
5 / 05 Currently in Use	769	11/19/1998 13 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in POWELL County in the City of DEER LODGE

Owner: Broken Circle Ranch Co Inc		Address: 3987 Eastside Rd, Deer Lodge MT 59722-9520			
Sys Fac ID 3913744	FITS SITE 41298	Location Name BROKEN CIRCLE RANCH CO INC	Location Street Address 3850 Eastside Rd	Location City DEER LODGE, MT 59722	Location Phone (406) 846-9614
Operating Permit Renewal Date: 26-Mar-2015			Last inspected on: 01-Mar-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
1 / 01 Currently in Use	4624	6/1/1996 15 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	K	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	K	L																					
2 / 02 Currently in Use	4625	6/1/1996 15 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	K	L	Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in POWELL County in the City of GARRISON

Owner: Garrison Mercantile & Post Office Inc		Address: PO Box 636, Garrison MT 59731-0636	
Sys Fac ID 3903405	FITS SITE 41183	Location Name GARRISON MERCANTILE & POST OFFICE INC	Location Street Address INTERSTATE 90 & US HIGHWAY 12
		Location City GARRISON, MT 59731	Location Phone (406) 846-9961
Operating Permit Renewal Date: 01-Apr-2002		Last inspected on: 08-Oct-2009	

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01	3934	5/5/1981	Gasoline	Cathodically Protected Steel	Galvanized Steel	Safe Suction	A B ● ● E F G H I J K L B D E F G H I ● K L	Yes Yes Yes
Temporarily Out of Use		30 / No	5,000	Lined Interior/Impressed Curre	None			
2 / 02	3935	5/5/1981	Gasoline	Cathodically Protected Steel	Galvanized Steel	Safe Suction	A B ● ● E F G H I J K L B D E F G H I ● K L	Yes Yes Yes
Temporarily Out of Use		30 / No	5,000	Lined Interior/Impressed Curre	None			

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in POWELL County in the City of OVANDO

Owner: Blackfoot Commercial Co LLC			Address: PO Box 108, Ovando MT 59854		
Sys Fac ID 3902276	FITS SITE 41161	Location Name BLACKFOOT COMMERCIAL CO LLC	Location Street Address 722 PINE ST	Location City OVANDO, MT 59854	Location Phone
Operating Permit Renewal Date: 30-Nov-2013			Last inspected on: 11-Nov-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection		Installed Spill/Over/CPMe
							Piping Release Detection		
1 / S07 Currently in Use	3362	6/1/1996 15 / Yes	Diesel 1,000	Other None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L	<input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes
2 / S08 Currently in Use	3363	6/1/1996 15 / Yes	Gasoline 3,000	Other None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L	<input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes
3 / S09 Currently in Use	3364	6/1/1996 15 / Yes	Gasoline 1,000	Other None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L	<input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed