

Facility Summary in RAVALLI County in the City of CORVALLIS

Owner: The Merc Fresh Market Inc		Address: PO Box 1025, 1000 Main St, Corvallis MT 59828-9749			
Sys Fac ID 4102402	FITS SITE 41407	Location Name THE MERC FRESH MARKET INC	Location Street Address 1000 MAIN ST	Location City CORVALLIS, MT 59828	Location Phone (406) 961-4830
Operating Permit Renewal Date: 17-Feb-2013			Last inspected on: 02-Nov-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe
							Piping Release Detection	
4 / 04 Currently in Use	376	2/1/1994 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
5 / 05 Currently in Use	377	8/1/1996 15 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
6 / 06 Currently in Use	378	8/1/1996 15 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of DARBY

Owner: Floodtide Inc			Address: PO Box 508, Darby MT 59829-0508		
Sys Fac ID 4100028	FITS SITE 41374	Location Name MR TS FOOD AND FUEL	Location Street Address 101 S MAIN ST	Location City DARBY, MT 59829	Location Phone (406) 821-1940
Operating Permit Renewal Date: 16-May-2014			Last inspected on: 18-Jan-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
6 / 06 Currently in Use	3070	4/13/1995 17 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
7 / 07 Currently in Use	3071	4/13/1995 17 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner:			Address:		
Sys Fac ID 4100853	FITS SITE 41389	Location Name DARBY LUMBER	Location Street Address	Location City DARBY, MT 59829	Location Phone
Operating Permit Renewal Date: 01-Apr-2002			Last inspected on: 04-Feb-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
4 / 04 Temporarily Out of Use	803	4/1/1992 20 / No	Diesel 3,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L C D E F G H I J K L	Yes Yes Yes
5 / 05 Temporarily Out of Use	804	4/1/1992 20 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L C D E F G H I J K L	Yes Yes Yes

Owner: Tabish Brothers Distributors Inc			Address: GW Petroleum, PO Box 8448, Missoula MT 59807-8448		
Sys Fac ID 4110908	FITS SITE 41524	Location Name OLES COUNTRY STORE 6	Location Street Address US HIGHWAY 93 S	Location City DARBY, MT 59829	Location Phone (406) 543-7621
Operating Permit Renewal Date:			Last inspected on: 30-Jan-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 06 Temporarily Out of Use	1441	4/1/1995 17 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L C D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of DARBY

2 / 07	1442	4/1/1995	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A ● ● ● ● E F G H I J K L ● ● ● ● ● E F G H I J K L	Yes	Yes	Yes
Temporarily Out of Use		17 / No	8,000	None	None					
3 / 08	1443	4/1/1995	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A ● ● ● ● E F G H I J K L ● ● ● ● ● E F G H I J K L	Yes	Yes	Yes
Temporarily Out of Use		17 / No	5,000	None	None					

Owner: Peoples Market			Address: 801 N Main St, Darby MT 59829-9542		
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone
5614029	45233	PEOPLES MARKET	801 N MAIN ST	DARBY, MT 59829	(406) 821-3612
Operating Permit Renewal Date: 26-Dec-2013			Last inspected on: 23-Jun-2010		

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / S1	4338	8/20/2001	Gasoline	Unknown	Flexible Plastic	Pressurized	A B C D E F G H I J ● L ● ● ● ● ● E F ● H I J K L	Yes Yes Yes
Currently In Use		10 / Yes	8,000	None	Double-Walled			
2 / S2	4339	8/20/2001	Gasoline	Not Listed	Flexible Plastic	Pressurized	A B C D E F G H I J ● L ● ● ● ● ● E F ● H I J K L	Yes Yes Yes
Currently In Use		10 / Yes	4,000	None	Double-Walled			
3 / S3	4340	8/20/2001	Diesel	Not Listed	Flexible Plastic	Pressurized	A B C D E F G H I J ● L ● ● ● ● ● E F ● H I J K L	Yes Yes Yes
Currently In Use		10 / Yes	5,000	None	Double-Walled			
4 / S4	4341	8/20/2001	Diesel	Not Listed	Flexible Plastic	Pressurized	A B C D E F G H I J ● L ● ● ● ● ● E F ● H I J K L	Yes Yes Yes
Currently In Use		10 / Yes	5,000	None	Double-Walled			

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of FLORENCE

7 / 07	4194	5/1/2000	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes
Currently In Use		11 / No	5,000	Double-Walled	Double-Walled	<input type="checkbox"/> B <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L				
8 / 08	4195	5/1/2000	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes
Currently In Use		11 / No	10,000	Double-Walled	Double-Walled	<input type="checkbox"/> B <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L				
9 / 09	4196	5/1/2000	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes
Currently In Use		11 / No	5,000	Double-Walled	Double-Walled	<input type="checkbox"/> B <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L				
10 / 10	4197	5/1/2000	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L	Yes	Yes	Yes
Currently In Use		11 / No	12,000	Double-Walled	Double-Walled	<input type="checkbox"/> B <input checked="" type="checkbox"/> E <input type="checkbox"/> F <input checked="" type="checkbox"/> H <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L				

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of HAMILTON

Owner: Missoula Holdings LLC			Address: PO Box 6000, Butte MT 59702-6000		
Sys Fac ID 4100145	FITS SITE 41375	Location Name TOWN PUMP INC HAMILTON 2	Location Street Address 932 S 1ST ST	Location City HAMILTON, MT 59840	Location Phone
Operating Permit Renewal Date: 27-May-2013			Last inspected on: 29-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	2593	4/7/1986 26 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	2594	4/7/1984 28 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
3 / 03 Currently in Use	2595	4/7/1984 28 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
4 / 04 Currently in Use	2596	4/7/1984 28 / No	Diesel 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes

Owner: Davisons Exxon Service			Address: 410 S 1st St, Hamilton MT 59840-2809		
Sys Fac ID 4104846	FITS SITE 41436	Location Name DAVISON'S EXXON SERVICE	Location Street Address 410 S 1ST ST	Location City HAMILTON, MT 59840	Location Phone (406) 363-1933
Operating Permit Renewal Date: 06-Aug-2012			Last inspected on: 10-Apr-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
5 / S8 Currently in Use	823	3/3/1993 19 / Yes	Diesel 20,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
6 / S7 Currently in Use	822	3/3/1993 19 / Yes	Gasoline 5,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
8 / S5 Currently in Use	821	3/1/1993 19 / Yes	Gasoline 2,678	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of HAMILTON

Owner: Anglers Roost LLP			Address: 815 US Highway 93 S, Hamilton MT 59840-9746		
Sys Fac ID 4105798	FITS SITE 41449	Location Name ANGLERS ROOST LLP	Location Street Address 815 US HIGHWAY 93 S	Location City HAMILTON, MT 59840	Location Phone (406) 363-1268
Operating Permit Renewal Date: 14-Jan-2009			Last inspected on: 21-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Temporarily Out of Use	3470	4/25/1984 28 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C D E F G H I J K L B ● E F G H ● J K L	Yes Yes Yes
2 / 02 Temporarily Out of Use	3471	4/4/1985 27 / No	Diesel 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C D E F G H I J K L B ● E F G H ● J K L	Yes Yes Yes

Owner: Ravalli County Sanitarian			Address: 205 Bedford St, Hamilton MT 59840-2853		
Sys Fac ID 4106546	FITS SITE 41462	Location Name RAVALLI COUNTY ROAD DEPT HAMILTON	Location Street Address 244 FAIRGROUNDS RD	Location City HAMILTON, MT 59840	Location Phone (406) 363-2733
Operating Permit Renewal Date: 12-Jul-2010			Last inspected on: 07-Jul-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
5 / 05 Temporarily Out of Use	1831	11/1/1991 20 / No	Diesel 12,000	STI-P3 None	Bare Steel Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J ● L	Yes Yes Yes

Owner: Save O Mat Corporations			Address: PO box 6000, Butte MT 59702-6000		
Sys Fac ID 4109670	FITS SITE 41497	Location Name TOWN PUMP INC HAMILTON 1	Location Street Address 1115 N 1ST ST	Location City HAMILTON, MT 59840	Location Phone (406) 363-4643
Operating Permit Renewal Date: 27-May-2013			Last inspected on: 29-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	2597	2/23/1987 25 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H ● J K L	Yes Yes Yes
2 / 02 Currently in Use	2598	2/23/1987 25 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H ● J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of HAMILTON

3 / 03	2599	2/23/1987	Gasoline	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use		25 / No	12,000	None	None	B ● E F G H I J K L		
4 / 05	2600	2/23/1987	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently in Use		25 / No	10,000	None	None	● E F G H I J K L		
5 / 06	4490	6/1/2001	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently In Use		10 / No	10,000	Double-Walled	Double-Walled	B ● E F G H I J K L		
6 / 07	4491	6/1/2001	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C D E F G H I J K L	Yes Yes Yes
Currently In Use		10 / No	5,000	Double-Walled	Double-Walled	B ● E F G H I J K L		

Owner: West Fork Holdings LLC		Address: Lone Pine Conoco, 504 US Highway 93 S, Hamilton MT 59840-8967			
Sys Fac ID 4113588	FITS SITE 41601	Location Name RIVERSIDE CONOCO	Location Street Address 1987 N 1ST ST	Location City HAMILTON, MT 59840	Location Phone (406) 363-3703
Operating Permit Renewal Date: 25-Mar-2015		Last inspected on: 25-Oct-2011			

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
2 / 02	3262	6/1/1998	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Currently In Use		13 / No	12,000	None	Double-Walled	B D E F ● H I J K L		
3 / 03	3263	6/1/1998	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Currently In Use		13 / No	8,000	None	Double-Walled	B D E F ● H I J K L		
4 / 04	3264	6/1/1998	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Currently In Use		13 / No	4,000	None	Double-Walled	B D E F ● H I J K L		
5 / 05	5061	12/7/2005	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Currently in Use		06 / No	8,000	None	Double-Walled	B D E F ● H I J K L		

Owner: Quality Investments		Address: PO BOX Q, , Salmon ID 83467			
Sys Fac ID 4113769	FITS SITE 41606	Location Name Quality Used Cars	Location Street Address 400 N 1ST ST	Location City HAMILTON, MT 59840	Location Phone (406) 363-0188
Operating Permit Renewal Date: 01-Apr-2002		Last inspected on: 16-Apr-2009			

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01	3436	3/5/1997	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Temporarily Out of Use		15 / No	12,000	None	Double-Walled	B ● E F ● H I J K L		
2 / 02	3437	3/5/1997	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes Yes Yes
Temporarily Out of Use		15 / No	8,000	None	Double-Walled	B ● E F ● H I J K L		

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of HAMILTON

3 / 03 **3438** 3/5/1997 Diesel Fiberglass Reinforced Plastic Fiberglass Reinforced Plas Pressurized
 Temporarily Out of Use 15 / No 4,000 None Double-Walled

<input type="radio"/> A	<input type="radio"/> B	<input type="radio"/> C	<input checked="" type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L
<input type="radio"/> B	<input checked="" type="radio"/> D	<input type="radio"/> E	<input type="radio"/> F	<input checked="" type="radio"/> G	<input type="radio"/> H	<input type="radio"/> I	<input type="radio"/> J	<input type="radio"/> K	<input type="radio"/> L		

Yes Yes Yes

Owner: West Fork Holdings LLC			Address: Lone Pine Conoco, 504 US Highway 93 S, Hamilton MT 59840-8967		
Sys Fac ID 5613874	FITS SITE 45098	Location Name LONE PINE INC	Location Street Address 504 US HIGHWAY 93 S	Location City HAMILTON, MT 59840	Location Phone (406) 375-0554
Operating Permit Renewal Date: 17-Feb-2013			Last inspected on: 27-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection		Installed Spill/Over/CPMe
							Piping Release Detection		
1 / 01 Currently In Use	3513	7/1/1998 13 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<input type="radio"/> A <input type="radio"/> B <input type="radio"/> C <input checked="" type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	<input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input checked="" type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	Yes Yes Yes
2 / 02 Currently In Use	3514	7/1/1998 13 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<input type="radio"/> A <input type="radio"/> B <input checked="" type="radio"/> C <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	<input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input checked="" type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	Yes Yes Yes
3 / 03 Currently In Use	3515	7/1/1998 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<input type="radio"/> A <input type="radio"/> B <input checked="" type="radio"/> C <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	<input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input checked="" type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of STEVENSVILLE

Owner: Russell A & Gayla M Cleveland			Address: 1407 Wheelbarrow Cr Rd, Stevensville MT 59870		
Sys Fac ID 4100170	FITS SITE 41376	Location Name THREE MILE TRADING CO	Location Street Address 899 THREE MILE CREEK RD	Location City STEVENSVILLE, MT 59870	Location Phone (406) 777-3365
Operating Permit Renewal Date: 09-Feb-2013			Last inspected on: 12-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 05 Currently in Use	2117	3/1/1993 19 / No	Gasoline 2,000	Cathodically Protected Steel None	Galvanized Steel none	Safe Suction	A B C ● E F G H I J K L B D E F G H I J ● L	Yes Yes Yes
2 / 04 Currently in Use	2116	3/1/1993 19 / No	Diesel 5,000	Cathodically Protected Steel None	Galvanized Steel none	Safe Suction	A B C ● E F G H I J K L B D E F G H I J ● L	Yes Yes Yes
4 / 03 Currently in Use	2115	3/1/1993 19 / No	Gasoline 5,000	Cathodically Protected Steel None	Galvanized Steel none	Safe Suction	A B C ● E F G H I J K L B D E F G H I J ● L	Yes Yes Yes

Owner: Rainforth Corp			Address: 2693 Eastside Hwy, Stevensville MT 59870-6954		
Sys Fac ID 4110286	FITS SITE 41507	Location Name CASEYS STORE	Location Street Address 2693 EASTSIDE HWY	Location City STEVENSVILLE, MT 59870	Location Phone (406) 777-9894
Operating Permit Renewal Date: 25-Sep-2014			Last inspected on: 13-Jun-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / S3 Currently In Use	3614	12/1/1998 13 / Yes	Gasoline 6,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F G H I J ● L B ● E F ● H I J K L	Yes Yes Yes
4 / S4 Currently In Use	3615	12/1/1998 13 / Yes	Diesel 3,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F G H I J ● L B ● E F ● H I J K L	Yes Yes Yes
5 / S5 Currently In Use	3809	12/1/1998 13 / Yes	Diesel 3,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F G H I J ● L B ● E F ● H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of STEVENSVILLE

Owner: Cenex Harvest States Missoula			Address: DBA Mountain West Co Op, 4570 N Reserve St, Missoula MT 59808-1411		
Sys Fac ID 4110330	FITS SITE 41510	Location Name MOUNTAIN WEST CO OP STEVENSVILLE	Location Street Address 115 MAIN ST	Location City STEVENSVILLE, MT 59870	Location Phone (406) 777-5441
Operating Permit Renewal Date: 31-Mar-2015			Last inspected on: 03-Jan-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 06 Currently in Use	911	2/14/1978 34 / No	Diesel 15,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
2 / 04 Currently in Use	909	2/14/1978 34 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
3 / 05 Currently in Use	910	2/14/1978 34 / No	Diesel 15,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
4 / 02 Currently in Use	907	2/14/1978 34 / No	Diesel 15,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K ●	Yes Yes Yes
5 / 03 Currently in Use	908	2/14/1978 34 / No	Gasoline 15,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
6 / 01 Currently in Use	906	2/14/1978 34 / No	Gasoline 15,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Flexible Plastic Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes
7 / 07 Currently In Use	912	12/29/1997 14 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L B D E F ● H I J K L	Yes Yes Yes

Owner: Stephen Clevidence			Address: The Works, 324 Main St, Stevensville MT 59870-2530		
Sys Fac ID 4111429	FITS SITE 41537	Location Name THE WORKS SINCLAIR	Location Street Address 324 MAIN ST	Location City STEVENSVILLE, MT 59870	Location Phone
Operating Permit Renewal Date: 17-Dec-2008			Last inspected on: 21-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 05 Temporarily Out of Use	2346	10/28/1990 21 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plas None	U.S. Suction	A B C ● E F G H I J K L ● D E F G H I J K L	Yes Yes Yes
2 / 06 Temporarily Out of Use	2347	10/28/1990 21 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plas None	U.S. Suction	A B C ● E F G H I J K L ● D E F G H I J K L	Yes Yes Yes
3 / 07 Temporarily Out of Use	2348	10/28/1990 21 / No	Gasoline 2,000	STI-P3 None	Fiberglass Reinforced Plas None	U.S. Suction	A B C ● E F G H I J K L ● D ● F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of STEVENSVILLE

Owner: Ralls Inc			Address: 3912 US Highway 93 N, Stevensville MT 59870-6425		
Sys Fac ID 4113686	FITS SITE 41604	Location Name OLES COUNTRY STORE 15	Location Street Address 3912 US HIGHWAY 93 N	Location City STEVENSVILLE, MT 59870	Location Phone (406) 777-1179
Operating Permit Renewal Date: 08-Apr-2014			Last inspected on: 14-Feb-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection		Installed Spill/Over/CPMe
							Piping Release Detection		
1 / 01 Currently in Use	3316	5/1/1996 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C ● E F ● H I J K L B ● E F ● H I J K L	Yes Yes Yes	
2 / 02 Currently in Use	3317	5/17/1996 15 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C ● E F ● H I J K L B ● E F ● H I J K L	Yes Yes Yes	
3 / 03 Currently in Use	3318	5/17/1996 15 / No	Diesel 3,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C ● E F ● H I J K L B ● E F ● H I J K L	Yes Yes Yes	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of SULA

Owner: Thomcorp LLC			Address: Kurt & Deborah Thomas, PO Box 30, Sula MT 59871-0030		
Sys Fac ID 4110411	FITS SITE 41514	Location Name SULA COUNTRY STORE LLC	Location Street Address 7060 US HIGHWAY 93 S	Location City SULA, MT 59871	Location Phone (406) 821-1041
Operating Permit Renewal Date: 29-Oct-2013			Last inspected on: 23-Jun-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / 03 Currently In Use	3485	3/1/1998 14 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
4 / 04 Currently In Use	3486	3/1/1998 14 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
5 / 05 Currently In Use	3487	3/1/1998 14 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: Lost Trail Ski Area Inc			Address: PO Box 311, Conner MT 59827-0311		
Sys Fac ID 4111692	FITS SITE 41547	Location Name LOST TRAIL POWDER MOUNTAIN	Location Street Address 7674 US HIGHWAY 93 S	Location City SULA, MT 59871	Location Phone (406) 821-3508
Operating Permit Renewal Date: 27-May-2012			Last inspected on: 09-Sep-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	2351	1/1/1990 22 / No	Diesel 8,000	STI-P3 None	No Piping None	Gravity Feed	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	2352	10/1/1992 19 / No	Diesel 8,000	Composite (Steel w/ FRP) None	No Piping None	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in RAVALLI County in the City of VICTOR

Owner: GEQ Inc			Address: 2343 Meridian Rd, PO Box 820, Victor MT 59875		
Sys Fac ID 4113288	FITS SITE 41592	Location Name VICTOR EXXON	Location Street Address 2381 US Hwy 93 N PO BOX 820	Location City VICTOR, MT 59875	Location Phone (406) 363-7079
Operating Permit Renewal Date: 05-Oct-2013			Last inspected on: 09-Sep-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Temporarily Out of Use	3174	11/1/1993 18 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
2 / 02 Temporarily Out of Use	3175	11/1/1993 18 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
3 / 03 Temporarily Out of Use	3176	11/1/1993 18 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
4 / 04 Temporarily Out of Use	3177	11/1/1993 18 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Owner: Manhattan Holdings LLC			Address: PO Box 6000, Butte MT 59702-6000		
Sys Fac ID 6015155	FITS SITE 45455	Location Name TOWN PUMP OF WOODSIDE	Location Street Address #6 Woodside Cutoff Rd	Location City VICTOR, MT 59875	Location Phone (406) 497-6700
Operating Permit Renewal Date: 16-Mar-2014			Last inspected on: 18-Nov-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	5241	/ No	Gasoline 15,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Double-Walled	Not Listed	A B C D E F G H I J K L B D E F G H I J K L	No Yes Yes
2 / 02 Currently in Use	5242	/ No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Double-Walled	Not Listed	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
3 / 03 Currently in Use	5243	/ No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Double-Walled	Not Listed	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
4 / 04 Currently in Use	5244	/ No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Double-Walled	Not Listed	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
5 / 05 Currently in Use	5245	/ No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Double-Walled	Not Listed	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed