

## Facility Summary in ROOSEVELT County in the City of BAINVILLE

<b>Owner:</b> Warrens Welcome Stop Inc		<b>Address:</b> US Highway 2, PO Box 32, Bainville MT 59212-0032	
<b>Sys Fac ID</b> 4313761	<b>FITS SITE</b> 42113	<b>Location Name</b> THE WELCOME STOP	<b>Location Street Address</b> US HIGHWAY 2 PO BOX 32
		<b>Location City</b> BAINVILLE, MT 59212	<b>Location Phone</b> (406) 769-2000
<b>Operating Permit Renewal Date:</b> 27-Jul-2013		<b>Last inspected on:</b> 19-Jul-2010	

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / S3 Currently In Use	3387	12/1/1997 14 / Yes	Diesel 10,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L		B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L																					
	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					
4 / S4 Currently In Use	3388	12/1/1997 14 / Yes	Gasoline 10,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="checkbox"/></td><td>L</td></tr> <tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="checkbox"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> </table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L		B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L	Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="checkbox"/>	L																					
	B		D	E	F	<input checked="" type="checkbox"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Facility Summary in ROOSEVELT County in the City of BROCKTON

<b>Owner:</b> Robert Nygard			<b>Address:</b> PO Box 248, Brockton MT 59213-0248		
<b>Sys Fac ID</b> 4302099	<b>FITS SITE</b> 41962	<b>Location Name</b> B & S QUICK STOP	<b>Location Street Address</b> US HIGHWAY 2 & 7TH ST PO BOX 248	<b>Location City</b> BROCKTON, MT 59213	<b>Location Phone</b> (406) 786-3237
<b>Operating Permit Renewal Date:</b> 13-Mar-2015			<b>Last inspected on:</b> 09-Nov-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 06 Currently in Use	1828	6/12/1995 16 / No	Gasoline 7,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
2 / 07 Currently in Use	1829	6/12/1995 16 / No	Gasoline 5,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

<b>Owner:</b> Cenex Harvest States Brockton			<b>Address:</b> PO Box 86, Brockton MT 59213-0086		
<b>Sys Fac ID</b> 4313651	<b>FITS SITE</b> 42112	<b>Location Name</b> CENEX HARVEST STATES BROCKTON ELEVAT	<b>Location Street Address</b> 600 S TRACKS RD	<b>Location City</b> BROCKTON, MT 59213	<b>Location Phone</b> (406) 786-3221
<b>Operating Permit Renewal Date:</b> 17-Feb-2013			<b>Last inspected on:</b> 12-Aug-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	4317	1/1/1983 29 / No	Diesel 20,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	4318	1/1/1983 29 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
3 / 03 Currently in Use	4319	8/1/1999 12 / No	Diesel 20,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
4 / 04 Currently in Use	4320	8/1/1999 12 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Facility Summary in ROOSEVELT County in the City of CULBERTSON

<b>Owner:</b> Oelkers Inc			<b>Address:</b> PO Box 272, Culbertson MT 59218-0272		
<b>Sys Fac ID</b> 4300030	<b>FITS SITE</b> 41929	<b>Location Name</b> OELKERS SERVICE CENTER	<b>Location Street Address</b> 4 E 6TH ST	<b>Location City</b> CULBERTSON, MT 59218	<b>Location Phone</b> (406) 787-5315
<b>Operating Permit Renewal Date:</b> 18-Oct-2014			<b>Last inspected on:</b> 29-Aug-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	1774	1/10/1953 59 / No	Gasoline 3,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Safe Suction	A B C ● E F G H I J K L B D E F G H I ● K L	Yes Yes Yes
2 / 02 Currently in Use	1775	1/10/1953 59 / No	Diesel 3,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Safe Suction	A B C ● E F G H I J K L B D E F G H I ● K L	Yes Yes Yes
3 / 03 Currently in Use	1776	1/10/1953 59 / No	Gasoline 3,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Safe Suction	A B C ● E F G H I J K L B D E F G H I ● K L	Yes Yes Yes
4 / 04 Currently in Use	1777	1/10/1953 59 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Safe Suction	A B C ● E F G H I J K L B D E F G H I ● K L	Yes Yes Yes

<b>Owner:</b> Val Am Stop & Go LLC			<b>Address:</b> PO Box 345, Culbertson MT 59218-0345		
<b>Sys Fac ID</b> 4301991	<b>FITS SITE</b> 41957	<b>Location Name</b> VAL AM STOP N SHOP	<b>Location Street Address</b> 110 W 6TH ST N	<b>Location City</b> CULBERTSON, MT 59218	<b>Location Phone</b> (406) 787-6327
<b>Operating Permit Renewal Date:</b> 11-Feb-2015			<b>Last inspected on:</b> 03-Jan-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
5 / 05 Currently in Use	3517	7/1/1990 21 / No	Gasoline 6,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F ● H I J K L B D E F G H I ● K L	Yes Yes Yes
6 / 06 Currently in Use	3518	7/1/1990 21 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F ● H I J K L B D E F G H I ● K L	Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Facility Summary in ROOSEVELT County in the City of CULBERTSON

<b>Owner:</b> Missouri Breaks Purvis Truck Stop Inc			<b>Address:</b> PO Box 690, Culbertson MT 59218-0690		
<b>Sys Fac ID</b> 4303015	<b>FITS SITE</b> 41979	<b>Location Name</b> MISSOURI BREAKS TRUCK STOP	<b>Location Street Address</b> 515 6TH ST E	<b>Location City</b> CULBERTSON, MT 59218	<b>Location Phone</b> (406) 787-6200
<b>Operating Permit Renewal Date:</b>			<b>Last inspected on:</b> 10-Jun-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Temporarily Out of Use	3732	5/5/1978 33 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Bare Steel None	Safe Suction	A ● C D ● F G H I J K L B D E F G H I ● K L	Yes Yes Yes
2 / 02 Temporarily Out of Use	3733	5/5/1978 33 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Bare Steel None	Safe Suction	A ● C D ● F G H I J K L B D E F G H I ● K L	Yes Yes Yes
3 / 03 Temporarily Out of Use	3734	5/5/1978 33 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Bare Steel None	Safe Suction	A ● C D ● F G H I J K L B D E F G H I ● K L	Yes Yes Yes
4 / 04 Temporarily Out of Use	3735	5/5/1978 33 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Bare Steel None	Safe Suction	A ● C D ● F G H I J K L B D E F G H I ● K L	Yes Yes Yes

<b>Owner:</b> Miller Oil Co Inc Culbertson			<b>Address:</b> PO Box 408, Culbertson MT 59218-0408		
<b>Sys Fac ID</b> 4307758	<b>FITS SITE</b> 42057	<b>Location Name</b> TRIPLE M SINCLAIR	<b>Location Street Address</b> 3RD W & 6TH ST	<b>Location City</b> CULBERTSON, MT 59218	<b>Location Phone</b> (406) 787-6271
<b>Operating Permit Renewal Date:</b> 12-May-2013			<b>Last inspected on:</b> 09-Dec-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently In Use	3635	7/1/1985 26 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	3636	7/1/1985 26 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes
4 / 04 Currently in Use	3637	7/1/1985 26 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B ● E F G H I J K L	Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Facility Summary in ROOSEVELT County in the City of FROID

<b>Owner:</b> Farmers Union Oil Co Froid		<b>Address:</b> PO Box 68, Froid MT 59226-0068			
<b>Sys Fac ID</b> 4304415	<b>FITS SITE</b> 42007	<b>Location Name</b> FARMERS UNION OIL CO FROID	<b>Location Street Address</b> 105 2ND AVE N	<b>Location City</b> FROID, MT 59226	<b>Location Phone</b> (406) 766-2339
<b>Operating Permit Renewal Date:</b> 19-Feb-2013			<b>Last inspected on:</b> 19-Aug-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe
							Piping Release Detection	
6 / 06 Currently in Use	958	10/1/1990 21 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C ● E F G H I J K L B D E F G H I J ● L	Yes Yes Yes
7 / 07 Currently in Use	959	10/1/1990 21 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C ● E F G H I J K L B D E F G H I J ● L	Yes Yes Yes
8 / 08 Currently in Use	960	10/1/1990 21 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C ● E F G H I J K L B D E F G H I J ● L	Yes Yes Yes
9 / 09 Currently in Use	961	10/1/1990 21 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C ● E F G H I J K L B D E F G H I J ● L	Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Facility Summary in ROOSEVELT County in the City of POPLAR

<b>Owner:</b> Butchs Exxon			<b>Address:</b> PO Box 987, Poplar MT 59255-0987		
<b>Sys Fac ID</b> 4301508	<b>FITS SITE</b> 41949	<b>Location Name</b> BUTCHS EXXON SERVICE	<b>Location Street Address</b> 400 F AVE W	<b>Location City</b> POPLAR, MT 59255	<b>Location Phone</b> (406) 768-3651
<b>Operating Permit Renewal Date:</b> 30-Mar-2013			<b>Last inspected on:</b> 26-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / 08 Currently in Use	508	1/1/1991 21 / No	Gasoline 4,000	Cathodically Protected Steel Double-Walled	Bare Steel None	U.S. Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
4 / 09 Currently in Use	509	1/1/1991 21 / No	Gasoline 4,000	Cathodically Protected Steel Double-Walled	Bare Steel None	U.S. Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
10 / 10 Currently in Use	510	1/1/1991 21 / No	Gasoline 4,000	Cathodically Protected Steel Double-Walled	Bare Steel None	U.S. Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

<b>Owner:</b> Tom Atkinson			<b>Address:</b> PO Box 6, Poplar MT 59255-0006		
<b>Sys Fac ID</b> 4302100	<b>FITS SITE</b> 41963	<b>Location Name</b> TJS QUICK STOP	<b>Location Street Address</b> 302 F ST	<b>Location City</b> POPLAR, MT 59255	<b>Location Phone</b> (406) 768-5225
<b>Operating Permit Renewal Date:</b>			<b>Last inspected on:</b> 16-Jun-1999		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / 03 Currently In Use	0	8/1/1996 15 / No	Gasoline 7,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
4 / 04 Currently In Use	0	8/1/1996 15 / No	Gasoline 5,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

<b>Owner:</b> Farmers Union Oil Co Wolf Point			<b>Address:</b> DBA Agland Coop, 60 US Highway 2 E, Wolf Point MT 59201-1942		
<b>Sys Fac ID</b> 4310278	<b>FITS SITE</b> 42088	<b>Location Name</b> FARMERS UNION OIL CO POPLAR	<b>Location Street Address</b> US HIGHWAY 2 E	<b>Location City</b> POPLAR, MT 59255	<b>Location Phone</b> (406) 768-3251
<b>Operating Permit Renewal Date:</b> 03-Mar-2013			<b>Last inspected on:</b> 03-Sep-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
-----------------------------	---------------	----------------------	---------------------	--	-------------------------------------	-------------	--	------------------------------

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

### Facility Summary in ROOSEVELT County in the City of POPLAR

1 / 05	997	6/1/1994	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	17 / No	10,000	None	Double-Walled	B ● E F G H I J K ●					
2 / 06	998	6/1/1994	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	17 / No	10,000	None	Double-Walled	B ● E F G H I J K ●					
3 / 01	993	10/27/1984	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	27 / No	10,000	None	Double-Walled	B ● E F G H I J K ●					
4 / 04	996	6/1/1994	Gasoline	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	17 / No	10,000	None	Double-Walled	B ● E F G H I J K ●					
5 / 02	994	10/27/1984	Diesel	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	27 / No	10,000	None	Double-Walled	B ● E F G H I J K ●					
6 / 03	995	10/27/1984	Gasoline	STI-P3	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use	27 / No	10,000	None	Double-Walled	B ● E F G H I J K ●					

<b>Owner:</b> Fort Peck Assiniboine & Sioux Tribes		<b>Address:</b> PO Box 1027, Poplar MT 59255-1027	
<b>Sys Fac ID</b> 4313620	<b>FITS SITE</b> 42111	<b>Location Name</b> TRIBAL EXPRESS	<b>Location Street Address</b> US HIGHWAY 2 E
<b>Location City</b> POPLAR, MT 59255		<b>Location Phone</b> (406) 768-5450	
<b>Operating Permit Renewal Date:</b> 01-Apr-2002		<b>Last inspected on:</b> 16-Jun-1999	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use		10/1/1992 19 / No	Gasoline 10,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F ● H I J K L B ● E F ● H I J K L	Yes Yes Yes
2 / 02 Currently in Use		10/1/1992 19 / No	Gasoline 6,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F ● H I J K L B ● E F ● H I J K L	Yes Yes Yes
3 / 03 Currently in Use		10/1/1992 19 / No	Gasoline 6,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F ● H I J K L B ● E F ● H I J K L	Yes Yes Yes

**Tank/Piping Release Detection Codes**

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Facility Summary in ROOSEVELT County in the City of WOLF POINT

<b>Owner:</b> City of Wolf Point			<b>Address:</b> 201 4th Ave S, Wolf Point MT 59201-1514		
<b>Sys Fac ID</b> 4300843	<b>FITS SITE</b> 41941	<b>Location Name</b> L M CLAYTON AIRPORT	<b>Location Street Address</b> MT HIGHWAY 13	<b>Location City</b> WOLF POINT, MT 59201	<b>Location Phone</b> (406) 653-2250
<b>Operating Permit Renewal Date:</b> 12-Jul-2013			<b>Last inspected on:</b> 16-Apr-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
5 / 06 Currently in Use	648	11/1/1992 19 / No	Aviation Gas 8,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
6 / 07 Currently in Use	649	11/1/1992 19 / No	Jet Fuel 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

<b>Owner:</b> Farmers Union Oil Co Wolf Point			<b>Address:</b> DBA Agland Coop, 60 US Highway 2 E, Wolf Point MT 59201-1942		
<b>Sys Fac ID</b> 4306866	<b>FITS SITE</b> 42043	<b>Location Name</b> FARMERS UNION OIL CO WESTSIDE STATION	<b>Location Street Address</b> 60 US HIGHWAY 2 E	<b>Location City</b> WOLF POINT, MT 59201	<b>Location Phone</b> (406) 653-1510
<b>Operating Permit Renewal Date:</b> 04-Mar-2013			<b>Last inspected on:</b> 04-Sep-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
7 / 07 Currently in Use	4327	6/1/1994 17 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
8 / 08 Currently in Use	988	6/1/1994 17 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
9 / 09 Currently in Use	4328	6/1/1994 17 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
10 / 10 Currently in Use	990	6/1/1994 17 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
11 / 11 Currently in Use	4329	6/1/1994 17 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
12 / 12 Currently in Use	992	6/1/1994 17 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



### Facility Summary in ROOSEVELT County in the City of WOLF POINT

13 / 13	<b>1003</b>	8/1/1996	Diesel	STI-P3	Flexible Plastic	Pressurized	A B C ● E F G H I J K L			
Currently in Use		15 / No	14,000	None	Double-Walled		● ● E F G H I J K L	Yes	Yes	Yes
14 / 14	<b>1004</b>	8/1/1996	Diesel	STI-P3	Flexible Plastic	Pressurized	A B C ● E F G H I J K L			
Currently in Use		15 / No	10,000	None	Double-Walled		● ● E F G H I J K L	Yes	Yes	Yes
15 / 15	<b>1005</b>	8/1/1996	Diesel	STI-P3	Flexible Plastic	Pressurized	A B C ● E F G H I J K L			
Currently in Use		15 / No	10,000	None	Double-Walled		● ● E F G H I J K L	Yes	Yes	Yes

#### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed