

Facility Summary in SHERIDAN County in the City of DAGMAR

Owner: Prairie States Coop			Address: PO Box 6, Zahl ND 58856-0006		
Sys Fac ID 4600762	FITS SITE 42481	Location Name PRAIRIE STATES COOP TERMINAL	Location Street Address MAIN ST PO BOX 338	Location City DAGMAR, MT 59219	Location Phone (406) 483-5297
Operating Permit Renewal Date: 16-May-2014			Last inspected on: 28-Feb-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe																								
							Piping Release Detection																									
6 / S6 Currently In Use	4500	11/1/2001 10 / Yes	Diesel 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L													Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
7 / S7 Currently In Use	4501	11/1/2001 10 / Yes	Diesel 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L													Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
8 / S8 Currently In Use	4502	11/1/2001 10 / Yes	Gasoline 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L													Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in SHERIDAN County in the City of MEDICINE LAKE

Owner: School Dist 7 Medicine Lake			Address: PO Box 265, Medicine Lake MT 59247-0265		
Sys Fac ID 4601122	FITS SITE 42502	Location Name MEDICINE LAKE SCHOOL DIST 7	Location Street Address 1 YOUNG ST	Location City MEDICINE LAKE, MT 59247	Location Phone (406) 789-2211
Operating Permit Renewal Date: 11-Aug-2014			Last inspected on: 04-Aug-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
2 / S3 Currently In Use	1603	8/1/1991 20 / No	Heating Oil 10,066	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas Double-Walled	Safe Suction	A B C D E F G H I J K L B ● E F ● H I ● K L	Yes Yes Yes

Owner: Lake Pit Stop LLC			Address: PO Box 173, Medicine Lake MT 59247		
Sys Fac ID 4601127	FITS SITE 42503	Location Name LAKE PIT STOP	Location Street Address MT HIGHWAY 16 & MAIN ST	Location City MEDICINE LAKE, MT 59247	Location Phone (406) 963-2286
Operating Permit Renewal Date: 30-Mar-2013			Last inspected on: 04-Feb-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
6 / S6 Currently in Use	2323	10/1/1997 14 / Yes	Gasoline 15,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F G H I J K L B ● D E F ● H I J K L	Yes Yes Yes
7 / S7 Currently in Use	2324	10/1/1997 14 / Yes	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F G H I J K L B ● D E F ● H I J K L	Yes Yes Yes
8 / S8 Currently in Use	2325	10/1/1997 14 / Yes	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F G H I J K L B ● D E F ● H I J K L	Yes Yes Yes
9 / S9 Currently in Use	2326	10/1/1997 14 / Yes	Gasoline 8,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F G H I J K L B ● D E F ● H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Owner: Sheridan Memorial Hospital			Address: 440 W Laurel Ave, Plentywood MT 59254-1596		
Sys Fac ID 4600795	FITS SITE 42484	Location Name SHERIDAN MEMORIAL HOSPITAL	Location Street Address 440 W LAUREL AVE	Location City PLENTYWOOD, MT 59254	Location Phone (406) 765-1420
Operating Permit Renewal Date: 03-Jun-2014			Last inspected on: 28-Dec-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / S3 Currently In Use	1918	10/1/1998 13 / No	Heating Oil 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: Farmers Union Oil Co Plentywood			Address: 301 W 1st Ave, Plentywood MT 59254-1802		
Sys Fac ID 4601524	FITS SITE 42522	Location Name AUTO TECH SERVICES	Location Street Address 327 W 1ST AVE	Location City PLENTYWOOD, MT 59254	Location Phone (406) 765-1180
Operating Permit Renewal Date: 08-Jun-2013			Last inspected on: 09-Dec-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
8 / 08 Currently in Use	1114	12/10/1989 22 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
9 / 09 Currently in Use	1115	12/10/1989 22 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
10 / 10 Currently in Use	1116	12/10/1989 22 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: Krause Gentle Corp			Address: Marc Hyland, 6400 Westown Pkwy, West Des Moines IA 50266-7709		
Sys Fac ID 4605200	FITS SITE 42646	Location Name KUM AND GO STORE 808	Location Street Address 211 W 1ST AVE	Location City PLENTYWOOD, MT 59254	Location Phone (406) 765-2847
Operating Permit Renewal Date: 21-Mar-2015			Last inspected on: 01-Nov-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
3 / 03 Currently in Use	1498	12/1/1982 29 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curre	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

4 / 04	4358	1/1/1988	Gasoline	Asphalt Coated or Bare Steel	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L B ● E F ● H I J K L	Yes	Yes	Yes
Currently in Use		24 / No	12,000	Impressed Current	Double-Walled					
5 / 05	1500	1/1/1988	Gasoline	Asphalt Coated or Bare Steel	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L B ● E F ● H I J K L	Yes	Yes	Yes
Currently in Use		24 / No	12,000	Impressed Current	Double-Walled					

Owner: Sheridan County Sanitarian				Address: 100 W Laurel Ave, Plentywood MT 59254-1647			
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone		
4606278	42671	SHERIDAN COUNTY	100 W LAUREL AVE	PLENTYWOOD, MT 59254	(406) 765-2310		
Operating Permit Renewal Date: 18-Jun-2014				Last inspected on: 05-Jan-2011			

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
2 / S2	1911	9/1/1995	Heating Oil	Polyethylene Tank Jacket	Flexible Plastic	Gravity Feed	A B C D E F ● H I J K L B D E F ● H I J K L	Yes Yes Yes
Currently in Use		16 / No	10,000	Double-Walled	Double-Walled			

Owner: Sheridan County Sanitarian				Address: 100 W Laurel Ave, Plentywood MT 59254-1647			
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone		
4606279	42672	SHERIDAN COUNTY SHOP	MT HIGHWAY 16 E	PLENTYWOOD, MT 59254	(406) 765-1221		
Operating Permit Renewal Date: 19-Feb-2014				Last inspected on: 05-Jan-2011			

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
5 / 05	1912	1/1/1990	Gasoline	Polyethylene Tank Jacket	Fiberglass Reinforced Plas	Safe Suction	A B C D E F ● H I J K L B D E F G H I ● K L	Yes Yes Yes
Currently in Use		22 / No	10,000	Double-Walled	None			
6 / 06	1913	1/1/1990	Diesel	Polyethylene Tank Jacket	Fiberglass Reinforced Plas	Safe Suction	A B C D E F ● H I J K L B D E F G H I ● K L	Yes Yes Yes
Currently in Use		22 / No	10,150	Double-Walled	None			
7 / 07	1914	1/1/1990	Diesel	Polyethylene Tank Jacket	Fiberglass Reinforced Plas	Safe Suction	A B C D E F ● H I J K L B D E F G H I ● K L	Yes Yes Yes
Currently in Use		22 / No	10,150	Double-Walled	None			
8 / 08	1915	1/1/1990	Waste Oil	Polyethylene Tank Jacket	Fiberglass Reinforced Plas	U.S. Suction	A B C D E F ● H I J K L B D E F G H I ● K L	Yes Yes Yes
Currently in Use		22 / No	1,002	Double-Walled	None			

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Owner: Farmers Union Oil Co Plentywood			Address: 301 W 1st Ave, Plentywood MT 59254-1802		
Sys Fac ID 4606801	FITS SITE 42692	Location Name FARMERS UNION OIL CO PLENTYWOOD	Location Street Address 301 W 1ST AVE	Location City PLENTYWOOD, MT 59254	Location Phone (406) 765-1171
Operating Permit Renewal Date: 19-Feb-2013			Last inspected on: 19-Aug-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
8 / 09 Currently in Use	1038	6/1/1996 15 / No	Gasoline 20,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L (B ● E F ● H I J K L)	Yes Yes Yes
9 / 10 Currently in Use	1039	6/1/1996 15 / No	Diesel 20,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L (B ● E F ● H I J K L)	Yes Yes Yes
10 / 11 Currently in Use	1040	6/1/1996 15 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L (B ● E F ● H I J K L)	Yes Yes Yes
11 / 12 Currently in Use	1041	6/1/1996 15 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L (B ● E F ● H I J K L)	Yes Yes Yes
12 / 13 Currently in Use	1042	6/1/1996 15 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L (B ● E F ● H I J K L)	Yes Yes Yes
13 / 14 Currently in Use	1043	6/1/1996 15 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L (B ● E F ● H I J K L)	Yes Yes Yes
14 / 15 Currently in Use	1044	6/1/1996 15 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C ● E F G H I J K L (B ● E F ● H I J K L)	Yes Yes Yes

Owner: Miller Oil Co Inc Culbertson			Address: PO Box 408, Culbertson MT 59218-0408		
Sys Fac ID 4608609	FITS SITE 42785	Location Name MILLER OIL CO INC E RAILROAD AVE	Location Street Address 416 W RAILROAD AVE	Location City PLENTYWOOD, MT 59254	Location Phone (406) 765-2852
Operating Permit Renewal Date: 04-Mar-2013			Last inspected on: 09-Dec-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / S1 Currently in Use	1617	4/8/1967 45 / Yes	Diesel 12,048	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H I J ● L (B ● E F ● H I J K L)	Yes Yes No
2 / S2 Currently in Use	1618	4/7/1961 51 / Yes	Gasoline 5,327	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H I J ● L (B ● E F ● H I J K L)	No No No
3 / S3 Currently in Use	1619	4/8/1967 45 / Yes	Gasoline 14,848	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plas Double-Walled	Pressurized	A B C D E F G H I J ● L (B ● E F ● H I J K L)	Yes Yes No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

4 / S4 1620 4/7/1968 Diesel Asphalt Coated or Bare Steel Fiberglass Reinforced Plas Pressurized
 Currently in Use 44 / Yes 14,773 None Double-Walled

A	B	C	D	E	F	G	H	I	J	K	L
B	●	E	F	●	H	I	J	K	L		

Yes Yes No

Owner: Montana Pioneer Manor Inc			Address: 605 Sheridan St, Plentywood MT 59254-1715		
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone
4610679	42827	MONTANA PIONEER MANOR INC	605 SHERIDAN ST	PLENTYWOOD, MT 59254	
Operating Permit Renewal Date: 04-Jun-2013			Last inspected on: 09-Dec-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / S2 Currently in Use	1673	5/1/1996 15 / No	Heating Oil 10,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: Sheridan County Sanitarian			Address: 100 W Laurel Ave, Plentywood MT 59254-1647		
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone
4612330	42855	SHERWOOD AIRPORT 4612330	100 W LAUREL AVE	PLENTYWOOD, MT 59254	(406) 765-2310
Operating Permit Renewal Date: 10-Mar-2014			Last inspected on: 05-Jan-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	1916	1/1/1989 23 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	1917	1/1/1989 23 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Owner: MNLC Inc Can Am Stores			Address: 203 Raymond Rd, Plentywood MT 59254-1545		
Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone
4612667	42857	MNLC INC CAN AM STORES	203 RAYMOND RD	PLENTYWOOD, MT 59254	
Operating Permit Renewal Date: 13-Nov-2012			Last inspected on: 13-Jul-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	2954	7/1/1991 20 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

2 / 02
Currently in Use

2955 7/1/1991
20 / No

Diesel
10,000

Polyethylene Tank Jacket
Double-Walled

Fiberglass Reinforced Plas
None

Safe Suction

A	B	C	D	E	F	G	H	I	J	K	L
	B		D	E	F	G	H	I	J	K	L

Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in SHERIDAN County in the City of RESERVE

Owner: Jacks Service Reserve			Address: PO Box 165, Reserve MT 59258-0165		
Sys Fac ID 4602103	FITS SITE 42553	Location Name JACKS SERVICE	Location Street Address 101 MAIN ST	Location City RESERVE, MT 59258	Location Phone (406) 286-5465
Operating Permit Renewal Date: 27-Sep-2014			Last inspected on: 06-Jul-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / 03 Currently in Use	4733	5/21/1991 20 / No	Gasoline 2,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	B	D	E	F	G	H	I	J	K	L			Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
B	D	E	F	G	H	I	J	K	L																							
5 / 05 Currently In Use	4213	7/27/2000 11 / No	Diesel 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L	B	D	E	F	G	H	I	J	K	L			Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
B	D	E	F	G	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed