

Facility Summary in TOOLE County in the City of GALATA

Owner: Fraser Oil Inc		Address: PO Box 770, Inverness MT 59530-0770			
Sys Fac ID 5102311	FITS SITE 43580	Location Name FRASER OIL INC GALATA	Location Street Address US HIGHWAY 2 N	Location City GALATA, MT 59444	Location Phone (406) 432-2321
Operating Permit Renewal Date: 17-Mar-2015			Last inspected on: 20-Oct-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																								
3 / 03 Currently in Use	1126	10/1/1992 19 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L		Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L																						
4 / 04 Currently in Use	1127	10/1/1992 19 / No	Diesel 1,000	STI-P3 None	Fiberglass Reinforced Plas None	Safe Suction	<table border="1" style="font-size: small; text-align: center;"> <tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="checkbox"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="checkbox"/></td><td>K</td><td>L</td><td></td></tr> </table>	A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L		Yes Yes Yes
A	B	C	<input checked="" type="checkbox"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="checkbox"/>	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in TOOLE County in the City of SHELBY

Owner: Singh Inc			Address: ATTN Harinder Singh, PO Box 7208, Great Falls MT 59406-7208		
Sys Fac ID 5100104	FITS SITE 43531	Location Name NOON'S 573	Location Street Address 602 W Roosevelt Hwy	Location City SHELBY, MT 59474	Location Phone (406) 452-1041
Operating Permit Renewal Date: 29-Sep-2013			Last inspected on: 14-Sep-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	4382	2/18/1972 40 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C D E F G H <input checked="" type="radio"/> J K L <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L	Yes Yes Yes
2 / 02 Currently in Use	3557	2/18/1972 40 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C D E F G H <input checked="" type="radio"/> J K L <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L	Yes Yes Yes
3 / 03 Currently in Use	4383	2/18/1972 40 / No	Diesel 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel None	Pressurized	A B C D E F G H <input checked="" type="radio"/> J K L <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L	Yes Yes Yes

Owner: Ben Taylor Inc			Address: PO Box 810, Shelby MT 59474-0810		
Sys Fac ID 5106113	FITS SITE 43637	Location Name MAIN STREET EXXON	Location Street Address 101 E MAIN ST	Location City SHELBY, MT 59474	Location Phone (406) 434-5076
Operating Permit Renewal Date: 08-Jan-2015			Last inspected on: 18-Oct-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
6 / 06 Currently in Use	426	8/16/1989 22 / No	Gasoline 8,000	STI-P3 Double-Walled	Fiberglass Reinforced Plas None	Pressurized	A B C D E F <input checked="" type="radio"/> H I J K L B <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes
7 / 07 Currently in Use	427	8/16/1989 22 / No	Gasoline 4,000	STI-P3 Double-Walled	Fiberglass Reinforced Plas None	Pressurized	A B C D E F <input checked="" type="radio"/> H I J K L B <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes
8 / 08 Currently in Use	428	8/16/1989 22 / No	Diesel 4,000	STI-P3 Double-Walled	Fiberglass Reinforced Plas None	Pressurized	A B C D E F <input checked="" type="radio"/> H I J K L B <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes
9 / 09 Currently in Use	429	8/16/1989 22 / No	Diesel 4,000	STI-P3 Double-Walled	Fiberglass Reinforced Plas None	Pressurized	A B C D E F <input checked="" type="radio"/> H I J K L B <input checked="" type="radio"/> E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in TOOLE County in the City of SHELBY

Owner: Greg and Shawn Matteson LLC			Address: 841 Marias Ave, Shelby MT 59474-1517		
Sys Fac ID 5107144	FITS SITE 43650	Location Name BRYANS AUTO REPAIR	Location Street Address 400 MAIN ST	Location City SHELBY, MT 59474	Location Phone (406) 434-2195
Operating Permit Renewal Date: 04-Feb-2009			Last inspected on: 30-Oct-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																																				
1 / 01 Temporarily Out of Use	3940	12/21/1988 23 / No	Gasoline 2,000	STI-P3 None	Galvanized Steel none	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L																									Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	
2 / 02 Temporarily Out of Use	3941	12/30/1986 25 / No	Diesel 2,000	STI-P3 None	Galvanized Steel none	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L																									Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	
3 / 03 Temporarily Out of Use	3942	12/30/1986 25 / No	Gasoline 8,000	STI-P3 None	Galvanized Steel none	Safe Suction	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L																									Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	
5 / 05 Temporarily Out of Use	1489	5/1/1991 20 / No	Waste Oil 500	Fiberglass Reinforced Plastic None	No Piping None	Not Listed	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L																									Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	

Owner: Simons Petroleum Inc			Address: PO Box 644, Shelby MT 59474-0644		
Sys Fac ID 5108629	FITS SITE 43664	Location Name SIMONS PETROLEUM INC 5108629	Location Street Address 530 W ROOSEVELT HWY	Location City SHELBY, MT 59474	Location Phone (406) 434-2461
Operating Permit Renewal Date: 27-Nov-2014			Last inspected on: 13-Jul-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe																																				
7 / 07 Currently In Use	5014	5/27/2005 06 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L																									Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	
8 / 08 Currently In Use	5013	5/27/2005 06 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L																									Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	
9 / 09 Currently In Use	5012	5/27/2005 06 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L																									Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	
10 / 10 Currently In Use	5015	5/27/2005 06 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table border="1" style="font-size: small;"> <tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table>	A	B	C	D	E	F	G	H	I	J	K	L																									Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																																	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in TOOLE County in the City of SHELBY

Owner: Travel Plazas of Montana Inc			Address: PO Box 6000, Butte MT 59702-6000		
Sys Fac ID 5109749	FITS SITE 43681	Location Name TOWN PUMP INC SHELBY	Location Street Address 1350 W Roosevelt Hwy	Location City SHELBY, MT 59474	Location Phone (406) 434-5221
Operating Permit Renewal Date: 01-Apr-2013			Last inspected on: 11-Dec-2009		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe
							Piping Release Detection	
1 / 01 Currently in Use	2657	9/7/1988 23 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	2658	9/7/1988 23 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
3 / 03 Currently in Use	2659	9/7/1988 23 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
4 / 04 Currently in Use	4291	9/7/1988 23 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
5 / 05 Currently in Use	4292	9/7/1988 23 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
6 / 06 Currently in Use	4293	8/1/1992 19 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Safe Suction	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
7 / 07 Currently in Use	2663	8/1/1992 19 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
8 / 08 Currently In Use	4248	7/1/1999 12 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes
9 / 09 Currently In Use	4413	10/1/2001 10 / No	Diesel 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic None	Not Listed	A B C D E F G H I J K L B D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in TOOLE County in the City of SUNBURST

Owner: Ben Taylor Inc			Address: PO Box 810, Shelby MT 59474-0810		
Sys Fac ID 5102025	FITS SITE 43576	Location Name TAYLORS BULK PLANT	Location Street Address 55 RAILROAD AVE	Location City SUNBURST, MT 59482	Location Phone (406) 937-2161
Operating Permit Renewal Date: 22-Jun-2013			Last inspected on: 27-Jan-2010		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Installed Spill/Over/CPMe
							Piping Release Detection	
6 / S6 Currently In Use	4137	8/31/1999 12 / Yes	Gasoline 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L	Yes Yes Yes
7 / S7 Currently In Use	4138	8/31/1999 12 / Yes	Gasoline 20,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L	Yes Yes Yes
8 / S8 Currently In Use	4139	8/31/1999 12 / Yes	Diesel 20,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L	Yes Yes Yes
9 / S9 Currently In Use	4140	8/31/1999 12 / Yes	Diesel 20,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L	Yes Yes Yes
10 / S10 Currently In Use	4161	8/31/1999 12 / Yes	Diesel 1,500	Unknown None	Flexible Plastic Double-Walled	Pressurized	A B C D E F G H I J <input checked="" type="radio"/> L B D E F <input checked="" type="radio"/> H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in TOOLE County in the City of Sweet Grass

Owner: Duty Free America's			Address: Tax Dept, 6100 Hollywood Blvd FL 7, Hollywood FL 33024-7983		
Sys Fac ID 5101377	FITS SITE 43561	Location Name Duty Free America's	Location Street Address 60 3rd Ave	Location City Sweet Grass, MT 59484	Location Phone (406) 335-2802
Operating Permit Renewal Date: 28-Mar-2015			Last inspected on: 09-Nov-2011		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
2 / 03 Currently in Use	871	1/1/1990 22 / No	Gasoline 15,000	Cathodically Protected Steel None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L B ● E F G H I J K ●	Yes Yes Yes
3 / 04 Currently in Use	872	1/1/1990 22 / No	Gasoline 15,000	Cathodically Protected Steel None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L B ● E F G H I J K L	Yes Yes Yes

Owner: Paper Dollar Bar Inc			Address: PO Box 110, Sweet Grass MT 59484-0110		
Sys Fac ID 5112405	FITS SITE 43699	Location Name MARS GAS & GROCERY	Location Street Address 510 2ND ST	Location City SWEET GRASS, MT 59484	Location Phone (406) 424-8006
Operating Permit Renewal Date: 27-Mar-2015			Last inspected on: 26-Mar-2012		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 01 Currently in Use	2718	6/25/1991 20 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes
2 / 02 Currently in Use	2719	6/25/1991 20 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plas None	Pressurized	A B C ● E F G H I J K L ● ● E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed